PUBLIC WORKS DEPARTMENT MARINE CORPS BASE CAMP LEJEUNE, NORTH CAROLINA 28542

43-200:CJP:dh 6 June 1973

MEMORANDUM FOR FILES

Subj: Conference on Feasibility Study for Updating Family Housing

Encl: (1) List of Attendees

- 1. The conference was convened in the Public Works conference room at 1300 on 4 June 1973. The list of attendees appears in enclosure (1).
- Mr. L. F. Butts, who attended vice Mr. Allen Bryant, explained the purpose of the meeting and recapped the instructions given to the A-E by LANTNAVFACENGCOM. He pointed out that this meeting was to discuss the 60% submission by the A-E but that he hoped the 60% report could be used as the basis for review and comments by his office and by the Base. He further stated that this conference should be concerned primarily with whether or not the A-E had understood the scope of his assignment correctly and was making satisfactory progress in the proper direction. It was agreed that, in a study of this type where the A-E was given very broad latitude in his instructions, it would be inappropriate to consider such subjects as the aesthetics of his architectural treatments, specific materials of construction, etc., since these things could be modified at the inception of specific projects. For instance, the current vinylclad siding project would produce a different exterior appearance than proposed in the feasibility study but would be immaterial from a functional standpoint.
- 3. Mr. Wakeham distributed bound copies of his 60% report for ready reference during the conference. He then presented an oral summary of his design philosophy for the study and explained the system he had used in organizing and presenting his material. He also stated that he would rearrange the final report so that all material relating to a given type of quarters would appear in a separate section devoted to that type. Most of his discussion was devoted to the Tarawa Terrace units since these constituted the largest number of quarters in the study and since they posed some of the most difficult problems.
- 4. A number of specific subjects were considered of great enough importance to warrant discussion during the meeting. Some of these are enumerated:
- a. It was pointed out that renovation of the Tarawa Terrace units would cost about \$18 per square foot and that new, more modern quarters,



Turning Count - Toxys

Water the Contract of



A

could probably be built for very little additional money. It was pointed out that the A-E study was not intended to make any such comparison, but that the estimated costs appearing in the study could be used by the Marine Corps in evaluating the relative merits of new construction versus renovation of old. At the request of the conferees, Mr. Wakeham agreed to make a statement of opinion on the subject in his final report.

- b. Objections were voiced to the sizes of the proposed kitchens in all of the plans. It was generally felt that they provided too little space for more than one person to work.
- c. In Tarawa Terrace, the garbage can location is a long way from the street, thus complicating garbage pickup. Also, garbage must be carried from the kitchens through the living rooms to the outdoors.
- d. Only certain types of units in Tarawa Terrace have been treated in the 60% report. It was pointed out that the combinations of units in certain buildings will pose different remodelling problems. Mr. Wakeham stated that his final report would include enough types of units to cover all situations.
- e. There was general feeling that the proposed conversion of the side porch on the 2-story quarters w/o garages to a fourth bedroom would be unacceptable unless a bath could be provided adjacent to it. Even then, it would be undesirable.
- f. It was agreed that this study should include consideration of electrical capacity only from the service drop to, and including, the interior of the house. Overall electrical distribution will warrant consideration in connection with any actual updating of housing, however, since air-conditioning and electric heating are proposed. (This will be true of other utilities as well.)
- g. The inherent fire hazard in the layout of the Tarawa Terrace units was discussed. This has been reduced, at least, by provision of new and larger sliding windows.
- 5. Mr. Butts requested that the Base use the 60% report as a basis for review and that comments be submitted to him, by telephone, by 14 June. The meeting was then adjourned about 1630.

CONWAY J. POWELL

Director, Design Division

Townsy Soull




ATTENDEES AT CONFERENCE ON FEASIBILITY STUDY FOR UPDATING FAMILY HOUSING 4 JUNE 1973

Name

Mr. Lloyd F. BUTTS
Mr. Wm. R. WAKEHAM
Mr. Larry NIXON
Maj. F. H. MOUNT
1stLt. R. D. BOURQUE
Mr. L. DOOLEY
Mrs. Nancy CLAUS
Mr. H. A. PLOWDEN
Capt. R. E. DAGGETT
Mr. C. J. POWELL
Mr. C. W. BARNES

Mr. P. D. BILLS

LANTNAVFACENGCOM (Code 09A21A)
Bartholomew & Wakeham, Architects
Bass, Nixon & Kennedy, Inc.
MCB, Office of AC/S, Facilities
MCB, Quarters and Housing
MCB, Base Maintenance
MCB, Public Works Officer & OICC/ROICC
MCB, Public Works Department
MCB, Public Works Department
MCB, Public Works Department



FEASIBILITY STUDY TO IMPROVE FAMILY HOUSING

MARINE CORPS BASE CAMP LEJEUNE, NORTH CAROLINA



DEPARTMENT OF THE NAVY
ATLANTIC DIVISION
NAVAL FACILITIES ENGINEERING COMMAND
NORFOLK, VIRGINIA

BARTHOLOMEW & WAKEHAM, ARCHITECTS



FE ASIBILITY STUDY
TO IMPROVE FAMILY HOUSING
PARADISE POINT AND TARAWA TERRACE, SECTION I
MARINE CORPS BASE
CAMP LEJEUNE, NORTH CAROLINA

PREPARED BY
BARTHOLOMEW AND WAKEHAM, ARCHITECTS
3700 COMPUTER DRIVE
RALEIGH, NORTH CAROLINA 27609

FEASIBILITY STUDY TO IMPROVE FAMILY HOUSING MARINE COPRS BASE CAMP LEJEUNE, NORTH CAROLINA

PAGE NO.

TABLE OF CONTENTS PART I GENERAL DESIGN CRITERIA A. UNIT IDENTIFICATION C. TABULATION OF EXISTING QUARTERS PART II PARADISE POINT AREA A. **EXISTING CONDITIONS** B. REQUIREMENTS C. DESCRIPTION OF RECOMMENDED IMPROVEMENTS D. DRAWINGS E. COST ESTIMATE PART III TARAWA TERRACE, SECTION I A. **EXISTING CONDITIONS** REQUIREMENTS B. C. DESCRIPTION OF RECOMMENDED IMPROVEMENTS D. DRAWINGS COST ESTIMATE

STATE OF THE STATE

CHARLEST CONTRACT OF THE

Transferred in the following the property of

TAGINET DO ORIGINA A P

CARACTER CARE TELEVISION OF THE SELECTION ASSESSMENT OF THE SELECTION OF T

FEASIBILITY STUDY TO IMPROVE FAMILY HOUSING MARINE CORPS BASE CAMP LEJEUNE, NORTH CAROLINA

PART I - GENERAL

A. DESIGN CRITERIA

This feasibility study has been prepared utilizing applicable portions of the following references:

- 1. NAVFAC Design Manual, DM-35, Family Housing, dated August 1971.
- 2. Department of Defense Construction Manual, DOD 4270.1-M, dated 1 October 1972.

B. UNIT IDENTIFICATION

There are nineteen different family housing unit types, with variations totaling 1138 units, under consideration by this feasibility study. Four types are located in the PARADISE POINT AREA and fifteen in TARAWA TERRACE I. Standard identification symbols as used in DM-35, giving personnel type, bedrooms, and unit plan type (ie; EM-3BR-1) have been assigned to each unit type. Original identification nomenclature is also indicated in the following TABULATION OF EXISTING QUARTERS for ease of cross reference.

Towards clarification of the content of this study, conditions and recommendations of family housing in the PARADISE POINT AREA are considered complete and separate from those of TARAWA TERRACE, SECTION I.

1892

The first of the state of the s

garang dining metanggianggan nganggan diapada paganing dipada dinah ing dilatah menghilipada. Tanggan paganing

the second second second second

o de la composition La composition de la La composition de la

o near mais en prefettiones, seminas anticos en anomes (n. 1622) tradesimente metro en reconsiente de tradición (n. 1777), en anticos para en anticos en anticos (n. 1622), en en anticos (n. 1622), en en a Esta en anticos (n. 1777), en en en en anticos en anticos en anticos (n. 1782), en anticos (n. 1782), en en en

C. TABULATION OF EXISTING QUARTERS TOTAL QUARTERS: 1138 UNITS

1. PARADISE POINT AREA: 207 UNITS TOTAL

No. Units	Original Unit Type	New Identification Symbol
40	Two story W/O Garages (3BR, 2B)	FGO-4BR-1
100	Cracker Boxes (3BR, 1B)	CGO-3BR-1
43	One story Cape Cod; 1AL & 1AR (3BR, 1B; two variations)	CGO-4BR-1
24	Two story Cape Cod; 2AL & 2AR, 2BL & 2BR; (3BR, 2B; four variations	CGO-5BR-1

2. TARAWA TERRACE I: 931 UNITS TOTAL

Staff NCO Quarters: 173 Units

EM Quarters: 758 Units

Staff NCO Quarters; detached; three variations

16	Type O-1 (3BR, 1B)	NCO-3BR-1
19	Type O-3 (3BR, 1B)	NCO-3BR-2
50	Type O-4 (2BR, 1B)	NCO-2BR-1

Staff NCO Quarters; semi-detached; four variations

13	Type OD-1A (2BR, 1B)	NCO-5 BR - 1
13	Type OD-1B (1BR, 1B)	NCO-5BR-1
22	Type OD-2 (1BR, 1B)	NCO-4BR-1
40	Type OD-3 (2BR, 1B)	NCO-2BR-2

PROBLEM OF THE THE SET OF THE SET

i kanandovi koja je mili alikoka prikanje i kananda krije kanali. Dio modeka i kananda kananda kinanda kananda kananda kananda kananda kananda kananda kananda kananda kananda k

Enlisted Mens Quarters; multi-family; eight variations

	420	Basic 2BR (2BR, 1B)	EM-2BR-1
	180	Basic 3BR (3BR, 1B)	EM-3BR-1
	19	Type A (3BR, 2B)	EM-3BR-2
	46	Type B (3BR, 2B)	EM-3BR-3
	29	Type C-1 (3BR, 2B)	EM-3BR-4
	29	Type C-2 (3Br, 1B)	EM-3BR-5
	6	Type X-1 (3BR, 2B)	EM-3BR-6
	6	Type X-2 (3BR, 1B)	EM-4BR-2
	23	Type A (3BR, 2B)	EM-4BR-1
Trm	og A th	VII V 2 ama commented units	

PART II - PARADISE POINT AREA

A. EXISTING CONDITIONS

- 1. The four types of FGO and CGO family housing units, with variations, considered in this section of this study are located in the PARADISE POINT AREA on the base at Camp Lejeune, North Carolina. These housing units do not meet current minimum adequacy standards for military housing. The deficiencies are in bedroom count; kitchen, bath and storage facilities; other amenities such as covered off street parking, patios and air conditioning.
- 2. The Area Comparison Table included in Requirements for each housing type indicates the existing deficient areas. (Part II, B of this study)
- 3. Latest Family Housing Surveys indicate a deficit of 4BR or more units in the FGO and CGO categories. Refer to Recommended Improvements, Part II, C of this study for methods to increase bedroom count.
- 4. The following Field Survey Results for each housing type indicate typical existing conditions.

The state of the s

FIELD SURVEY OF EXISTING HOUSING CONDITIONS MARKE CORPS BASE, CAMP LEJEUNE, NORTH CAROLINA

PARADISE POINT AREA

UNIT TYPE TWO STORY W/O GARAGE; FGO-4BR-1

COMPLETED December 1947
PORCHES ADDED: 1965

EXTERIOR CONDITIONS

S	ITE	REMARKS
1.	Landscaping	Mature; generally well maintained.
2.	Parking	Some deterioration of off-street concrete wheel strips. No covered parking.
3.	Pedestrian Circulation	Additional walks needed on site. None at street.
4.	Playground & Game Facilities	Community center with good summer activity program.
5.	Other	
SI	TE UTILITÆS	
6.	Sanitary Sewer	Adequate
7.	Storm Drain age	Some evidence of standing water in rear yards.
8.	Water Supply	Adequate
9.	Electrical Distribution	CP&L (Public utility company)

C. BUU DING	REMARKS
11. Recting	Composition shingles, replaced 1961. No current leaks. Max. remaining life 3-4 years.
• 12. Silling	Vert. wood (lower level); horiz. shiplap (upper level; fair condition; some rot.
13. Windows	Wood double hung and metal casements; drafty. fair condition; some rot.
14. Doors	No weatherstripping; screens in fair condition.
15. Storage	No exterior storage.
16. Trash Removal	Loose garbage cans in rear yard 75-80 ft. from house.
17. Fire Separation	Adequate
18. Other	No railing at steps (front & rear); tenant erected plywood porch enclosure at half these houses.
	INTERIOR CONDITIONS
D. STRUCTURAL	
19. Floor Joists	Some sagging at upper floor joists.
20. Wall Studs	Adequate
21. Ceiling/Roof Trusses	Adequate
22. Other	
E. KITCHEN (Inefficient arran	nge me nt)
23. Sink	Adequate size; excellent condition.

- 1			TA	1)	1.0
	1	4 1	4 0	10	KS


24. Carbage Disposer	Recent installation; adequate.
25. Countertop	Inadequate size; good condition, poor arrangement.
26. Cabinets	Inadequate size; fair condition; poor arrangement.
27. Refrigerator	Adequate size; good condition.
28. Range	36" electric; good condition
29. Exhaust	Fan thru wall; adequate
30. Washer/Dryer	Connections in utility room; poor arrangement.
31. Other (Flooring)	Fair condition (sheet vinyl) remaining life-2 years.
BATHROOMS 32. Toilet	No bath facilities on first floor Adequate
33. Tub & Shower	Adequate except wainscot.
34. Lavatory	Very small
35. Accessories	Surface mtd.
36. Wainscot	Cer. tile 4'-0 high (walls & tub); 6'-0 at shower.
37. Other (Flooring)	Cer. tile; good condition.

recognists of the first of the control of the contr

G. FINISHES	REMARKS
38. Floors	Hardwood floor; well maintained; repeated sanding has left very little wood.
39. Walls	Painted adequate
40. Ceilings	Painted
41. Other (Enclosed porch)	Tenant enclosed and panelled screen porch.
H. MECHANICAL EQUIPMENT 42. Heating Unit	Oil fired boiler in pit under stair. Some deterioration will need replacement 4-5 years.
43. Water Heater	50 gal. electric; fair condition.
44. Piping	Some deterioration
45. Other	Some wear on convectors; tenant furnished window air conditioners. Attic exhaust fan w/motorized louvers.
I. ELECTRICAL	
46. Service	2-100 amp panels.
47. Outlets	Adequate
48. Light Fixtures	Old but adequate
49. Wiring	Some exposed raceway for tenants air conditioning.
50. Other	

The planter, Left Halles Viscous parties and the property of t

. MISCELLANEOUS	REMARKS
51. Insulation (Thornal & Sound)	Adequate
52. Other	



FIELD SURVEY OF EXISTING HOUSING CONDITIONS MARINE CORPS BASE, CAMP LEJEUNE, NORTH CAROLINA

PARADISE POINT AREA

UNIT TYPE CRACKER BOX; TYPE CGO-3BR-1

COMPLETED February 1950

EXTERIOR CONDITIONS

	TE	REMARKS
1.	Landscaping	Mature; generally well maintained. Yards in poor condition.
2.	Parking	Some deterioration of off-street concrete wheel strips. No covered parking.
3.	Fedestrian Circulation	Additional walks needed on site. None at street. Existing walks too narrow
4.	Playground & Game Facilities	Community center with good summer activity program.
5.	Other	Tenant furnished yard fence, porch modifications and/or storage sheds exist in approx. 50% of cases.
SIT	TE UTILITIES	
	Sanitary Sewer	Adequate
6.		Adequate Some evidence of standing water in rear yards.
7.	Sanitary Sewer	
6. 7. 8.	Sanitary Sewer Storm Drainage	Some evidence of standing water in rear yards.

BUIL DING	REMARKS
He-Soring	Composition shingles, replaced 1961. No current leaks. Max. remaining life 3-4 years. Copper gutters & generally good condition, some deterioration, 3-5 yr. life
P. Siding	Horiz. wd. shiplap; fair condition
13. Windows	Wd. dbl. hung. screens in poor condition
14. Doors	Wd. panel. Fair condition
15. Storage	No exterior storage
16. Trash Removal	Loose garbage cans in rear yard 75-80 ft. from house.
17. Five Separation	Adequate
18. Other	No railing at rear stoop. No exterior patio. Screen porch damage; some wood rot.
	INTERIOR CONDITIONS
STRUCTURAL	
19. Floor Joists	Adequate
20. Wall Studs	Adequate
21. Ceiling/Roof Trusses	Sagging ceiling joists.
22. Other	
KITCHEN	Inefficient arrangement
23. Sink	Large single bowl stainless steel; good condition.

and the second of the

the season of the

portalistica de la secono de la estaca de la partirio de la constanta de la co

-Correct a remain or his


ser up to

-046999


postelido ligos si una appiniste tivos efficienta.

	REMARKS
24. Garbage Disposer	Recent installation; adequate
25. Countertop	Good condition; inadequate area
26. Cabinets	Good condition; inadequate area
27. Refrigerator	15/16 CF double door; excellent condition
28. Range	36" elec.; fair condition
29. Exhaust	Thru wall fan w/switch; poor location
30. Washer/Dryer	Connections in utility room, dryer outlet inoperative.
31. Other	
BATHROOMS	One bathroom only
32. Toilet	Adequate
33. Tub	Adequate
34. Lavatory	Small but good condition
35. Accessories	Adequate
36. Wainscot	Ceramic tile
37. Other	

FINISHES	REMARKS
38. Flors	Hardwood floors in fair condition. Sheet vinyl kitchen floor in poor condition.
39. Walls	Adequate
40. Ceilings	Adequate
41. Other	Ceramic tile bath wainscot in good condition.
MECHANICAL EQUIPMENT	
42. Heating Unit	Oil fired boiler.
43. Water Heater	50 gal. electric; poor condition
44. Piping	Same
45. Other	
• ELECTRICAL	
46. Service	100-A fuse panel with sep. disconnect for added capacity.
47. Outlets	Adequate
48. Light Fixtures	Old but adequate
19. Wiring	Appears adequate
50. Other	



JS	1	RI	EMARKS		
Sound)	Adequate				
		Adequate	Adequate	Adequate	Adequate



FIELD SURVEY OF EXISTING HOUSING CONDITIONS MARINE CORPS BASE, CAMP LEJEUNE, NORTH CAROLINA

PARADISE POINT AREA

UNIT TYPE ONE STORY CAPE COD; TYPE CGO-4BR-1 COMPLETED December 1948

EXTERIOR CONDITIONS

. SITE	REMARKS
1. Landscaping	Mature; generally well maintained
2. Parking	Some deterioration of off-street concrete wheel strips. No covered parking.
3. Pedestrian Circulation	Additional walks needed on site. None at street.
4. Playground & Game Facilities	Community center with good summer activity program.
5. Other	Some tenant fencing
SITE UTILITIES	
6. Sanitary Sewer	Adequate
7. Storm Drainage	Some evidence of standing water in rear yards.
8. Water Supply	Adequate
9. Electrical Distribution	CP&L (Public utility company)
10. Other	Slow fuel oil delivery

Toggrego is angel logik na hohem simble didina. Basenga sagar sagar sagar na mangan sa ang sagar sagar sagar sa	
Community of the wife for sommer activity or paying the	
and the state of the second of	

C. BUI DING	REMARKS
11. Sooning	Composition shingles, replaced 1961, No current leaks, Max. remaining life 3-4 yrs. Some shingles torn loose.
12. Siding	Asbestos shingles; some broken
13. Windows	Met. casements in wd. trim
14. Doors	No weatherstripping; screens in fair condition. Plywd. over rear door w/tenant air conditioner
15. Storage	No exterior storage
16. Trash Removal	Loose garbage cans in rear yard 75-80 ft. from house.
17. Fire Separation	Adequate
18. Other	Metal chimneys badly stained
	INTERIOR CONDITIONS
D. STRUCTURAL	
19. Floor Joists	Slab on grade
20. Wall Studs	Adequate
21. Ceiling/Roof Trusses	Adequate
22. Other	
E. KITCHEN	Poor arrangement
23. Sink	Small single bowl porcelin enamel; fair condition

	REMARKS
24. Carbage Disposer	Recent installation; adequate
25. Countertop	Inadequate size; good condition, poor arrangement
26. Cabinets	Inadequate size; fair condition; poor arrangement
27. Refrigerator	14 CF; poor condition
28. Range	36" elec., poor condition
29. Exhaust	None .
30. Washer/Dryer	in utility room, dryer connection inadequate; vent thru window
31. Other	
BATHROOMS	No half bath
32. Toilet	Adequate
33. Tub	Adequate
34. Lavatory	Small; good condition
35. Accessories	Surface mtd.
36. Wainscot	Cer. tile 4'-0 high(walls & tub); 6'-0 at shower
37. Other	Cer. tile; good condition

and the size of the

Commence of Bern States of States and States

ringform Librario University

. FINISHES	REMARKS
38. From	Wd. parquet; fair condition, sht. vinyl in kitchen peeling up.
39. Wills	Painted wallboard; adequate
40. Ceilings	Painted gypsum wallboard
41. Other (Enclosed Porch)	Tenant enclosed and panelled screen porch.
MECHANICAL EQUIPMENT	
42. Heating Unit	Oil fired boiler in pit under stair. Some deterioration-will need replacement 4-5 years.
43. Water Heater	50 gal. electric; fair condition
14. Piping	Some deterioration
45. Other	Some wear on convectors; tenant furnished window air conditioners. Attic exhaust fan w/motorized louvers.
ELECTRICAL	
46. Service	100A fuse panel
47. Outlets	Adequate
48. Light Fixtures	Pull chain in bath
49. Wiring	Some exposed raceway for tenants air conditioning.
50. Other	

51. Insulation (Thormal & Sound) Adequate 52. Other	
52. Other	

FIELD SURVEY OF EXISTING HOUSING CONDITIONS MARINE CORPS BASE, CAMP LEJEUNE, NORTH CAROLINA

PARADISE POINT AREA

UNIT TYPE TWO STORY CAPE COD; TYPE CGO-5BR-1 COMPLETED December 1948

EXTERIOR CONDITIONS

. SITE	REMARKS
1. Landscaping	Mature; generally well maintained.
2. Parking	Some deterioration of off-street concrete wheel strips. No covered parking.
3. Pedestrian Circulation	Additional walks needed on site. None at street.
4. Playground & Game Facilities	Community center with good summer activity program.
5. Other	Tenant fencing and clotheslines. Inadequate exterior lightin lighting.
SITE UTILITIES	
6. Sanitary Sewer	Water backup, slow drainage of plumbing fixtures
7. Storm Drainage	Some evidence of standing water in rear yards.
8. Water Supply	Adequate
9. Electrical Distribution	CP&L (Public utility company)
10. Other	

19.5 /g(n)

, y , ph. 我感染 And in the property of the control of the property of the prope

advancio principi de come nel come de cada per antigo de come.

destructions and the control of the

BOU.DING	REMARKS
11 Karag	Composition shingles, replaced 1961. No current leaks Max. remaining life 3-4 years.
12. Siding	Wood horiz. lap siding, some rot in wood trim
13. Windows	Metal casements in wood trim
14. Doors	No protection over front door
15. Storage	No exterior storage
16. Trash Removal	Loose garbage cans in rear yard 75-80 feet from house.
17. Fire Separation	Adequate
18. Other	Badly rusted metal louvers @ attic. Gutters & ds. have 3-5 yr. life remaining.
	INTERIOR CONDITIONS
STRUCTURAL	INTERIOR CONDITIONS
STRUCTURAL 19. Fleor Joists	Slab on grade
19. Fleor Joists	Slab on grade
19. Fleor Joists 20. Wall Studs	Slab on grade Adequate
19. Floor Joists 20. Wall Studs 21. Ceiling/Roof Trusses	Slab on grade Adequate Adequate

and the control of the state of

1 m 4 1 1 m

A STATE OF THE STATE OF

at a recommendation of the formal interest programmes and

and the second second second second

14 Cashara Dimensi	REMARKS
24. Garbage Disposar	Recent installation; adequate
25. Countertop	Inadequate size; good condition, poor arrangement.
26. Cabinets	Poor arrangement, adequate wall cabinet, inadequate base cabinet.
27. Refrigerator	New 15 CF frost free
28. Range	40" electric, good condition
29. Exhaust	None
30. Washer/Dryer	Connections in kitchen
31. Other	
BATHROOMS	One full bath each floor
32. Toilet	Adequate
33. Tub & Shower	Adequate except wainscot
4. Lavatory	Very small
35. Accessories	Surface mtd.
36. Wainscot	Cer. tile 4'-0 high (wall & tub); 6'0 at shower
7. Other (Flooring)	Cer. tile; good condition

The second second second

A transfer of the state of the state of

semination toda, a filtras filtras filtras profits

estections Plantas day or combined to the

and the second

Markey have to be the

and the first of

and a personnelled

and the second second second


Track.

1-2-1


sough is Cd Cost Bash duled TA 10

a boundary body body. Type

G. FINISHES	REMARKS
38. F wrs	Hardwood floor; well maintained; repeated sanding has left very little wood.
39. Walls	Painted wallboard; adequate
40. Ceilings	Painted gypsum wallboard
41. Other (Enclosed porch)	Tenant enclosed and panelled screen porch.
. MECHANICAL EQUIPMENT 42. Heating Unit	Oil fired boiler in pit under stair. Some deterioration-will need replacement 4-5 years.
43. Water Heater	50 gal. elec.; fair condition; slow recovery; located in attic.
44. Piping	Some deterioration
45. Other	No utility room
. ELECTRICAL	
46. Service	100A
47. Outlets	No outlet in first floor hall. Several outlets inoperative
48. Light Fixtures	Old but adequate
49. Wiring	Some exposed raceway for tenants air conditioning.
50. Other	



MI	SCELLANEOUS	. 1	REMARKS
51.	troulation (Thermal & Sound)	Adequate	
52.	Other		
02,	other.		



B. REQUIREMENTS

1. Two Story W/O Garage; Type FGO-4BR-1

a. Exterior

- Provide covered off-street parking at end of existing driveway incorporating exterior bulk storage and screened garbage can area. Connect carport to rear utility room entrance.
- 2. Provide patio and walks
- 3. Contemporize exterior

b. Interior-First Floor

- Renovate kitchen/utility room area to provide new efficient U-shaped kitchen arrangement, washer/dryer area and separate furnace/ water heater room and relocate larger coat closet.
- 2. Add half bath
- 3. Enclose existing screened porch to provide 4th. bedroom and closet.

c. Interior-Second Floor

1. Enlarge bedroom closets (compatible with First Floor entrance modifications).

d. Mechanical

 Install new electric-fired forced air heating/ air conditioning system.

e. Electrical

Increase capacity to accommodate rehabilitation.

2. Cracker Boxes; Type CGO-3BR-1

a. Exterior

- Provide covered off-street parking at end of existing driveway incorporating exterior bulk storage and screened garbage can area. Connect carport to rear utility room entrance.
- 2. Provide patio and walks
- 3. Contemporize exterior

Provide surface of the provide surface of the surfa

The reflect both Butter to a structure of the structure o

Light of the second of the sec

A BOURS OF THE RESERVE OF THE PROPERTY OF T

and the second section of the second section of the

b. Interior

- Renovate kitchen/utility room area to provide new efficient U-shaped kitchen arrangement, washer/dryer area and separate furnace/water heater room and relocated larger coat closet.
- 2. Add half bath between bedrooms 1 and 2. Rearrange and enlarge bedroom closets.
- 3. Provide alternate for glazing existing screened porch to provide increased habitable living area and eliminate high maintenance problem.

c. Mechanical

 Install new electric-fired forced air furnace.
 Modify existing ductwork to accommodate other recommended improvements contained herein.

d. Electrical

1. Increase capacity to accomodate rehabilitation.

3. One Story Cape Cod; Type CGO-4BR-1

a. Exterior

- Provide covered off-street parking at end of existing driveway incorporating exterior bulk storage and screened garbage can area. Connect carport to rear utility room entrance.
- 2. Provide patio and walks
- 3. Contemporize exterior

b. Interior

- Renovate kitchen/utility room area to provide new efficient U-shaped kitchen arrangement, washer/dryer area and separate furnace/ water heater room and relocate larger coat closet.
- 2. Provide new full bathroom
- Rearrange and enlarge bedroom closets and linen closet.
- 4. Enclose existing screen porch to provide 4th. bedroom and closet.

c. Mechanical

 Install new electric-fired forced air heating/ air conditioning system.

d. Electrical

1. Increase capacity to accomodate rehabilitation.

4. Two Story Cape Cod; Type CGO-5BR-1

a. Exterior

- Provide covered off-street parking at end of existing driveway incorporating exterior bulk storage and screened garbage can area. Connect carport to rear utility room entrance.
- 2. Provide patio and walks
- 3. Contemporize exterior

b. Interior-First Floor

- Renovate kitchen to provide new efficient Ushaped arrangement. Provide washer/dryer space in kitchen.
- Rearrange and modernize bath. Provide additional linen storage and separate furnace/water heater room.
- 3. Rearrange and enlarge bedroom closet
- 4. Construct addition to house 4th. bedroom and closet.
- 5. Provide alternate for glazing existing screened porch to provide increased habitable living area and eliminate high maintenance problem.

c. Interior-Second Floor

 Construct new dormer connecting existing dormers to provide 5th. bedroom and closet.

d. Mechanical

Install new electric-fired forced air furnace.
 Modify existing ductwork to accommodate other recommended improvements contained herein.

e. Electrical

1. Increase capacity to accomodate rehabilitation.

The state of the s

The first of the control of the cont

C. DESCRIPTION OF RECOMMENDED IMPROVEMENTS

1. General

There being a deficit of 4BR or more units in the FGO and CGO categories, it is recommended that the present 3BR Two Story W/O Garage houses be improved to include a 4th. bedroom, thereby providing 40 additional 4BR quarters in the FGO category.

It is further recommended that the One Story Cape Cod houses be improved to include a 4th bedroom and the Two Story Cape Cod houses to include a 4th. and 5th. bedroom, thereby providing 43 additional 4BR quarters and 24 additional 5BR quarters in the CGO category.

2. Two Story W/O Garage; Type FGO-4BR-1

a. Exterior

- 1. Off-Street Parking: Construct attached wood frame carport, 11 X 20 feet in size near end of existing driveway in side yard of units. Provide concrete floor slab, pitched for proper drainage, and concrete apron connecting new carport floor to existing concrete driveway strips. Construction of carport and attachment (covered walk) shall be wood frame with composition shingle roof to match house and one of several siding types compatible with contemporized house exterior. Provide alternate for new 10 foot concrete driveway.
- 2. Exterior bulk storage and garbage can enclosure: Construct enclosed covered storage area, 4 X 6 feet, with door and adjacent covered garbage can enclosure, 3 X 5 feet, as an extension to rear of new carport. Construction to match carport. Provide galvanized steel pipe can holder for two cans.
- Patio and walks: Construct new concrete patio,
 12 X 12 feet, provide new concrete walks, 3
 feet wide, between carport and patio and between driveway and front entrance.
- 4. Contemporize exterior: Remove existing wood or asbestos shingle siding. Replace with new stucco or combinations of stucco and brick veneer; stucco and cedar shingles or stucco and wood siding. In some cases the existing siding may remain, where

The state of propose were a resident. The state of the st

and the comprehensive promotion of the contraction of the contraction

in good condition. It is recommended that the exterior designs vary from house to house and yet maintain a unified neighborhood appearance through the repetitive use of one material; in this case, stucco. All recommended exterior materials have long life, low maintenance qualities.

Contemporize front entrance and cover by installing new 3 X 7 foot solid core flush wood door and glass sidelight. Install new aluminum and glass/screen doors at both exterior doors.

Replace existing wood double hung windows with new fixed and operable wood units compatible with exterior design. Repaint existing wood trim.

 Roof replacement: Provide alternate to replace existing roof with new composition shingles to match new carport and other additions. Reflash on an "as needed" basis.

b. Interior-First Floor

- 1. Kitchen: Remove existing cabinets and counters. Close existing side window. Install new window facing rear yard. Install new sheet vinyl floor. Install new plastic laminate covered work counter, wood base and wall cabinets in U-shape arrangement, 10.5 X 8.5 feet. Appliances: Provide new double bowl stainless steel sink and trim; garbage disposal; refrigerator and electric range. (NOTE) In approximately 50% of these houses, existing appliances are in excellent condition and warrant reuse within the new kitchen plan.
- 2. Utility Room: Provide new washer/dryer connections and vent in utility room off kitchen. Provide 5 X 1.5 foot storage shelf above washer/dryer. Provide new sheet vinyl floor. Relocate furnace and water heater to separate closet off utility room. Install 5/8 in. UL rated gypsum wallboard on walls, ceiling and inside face of wood door to closet. Provide new 2'-6 X 6'-8 wood door.
- 3. New bath: Construct new half bath, 3.5 X 8 feet, off utility room. Provide new water closet.

and the second of the second o

The first state of the second state of the sec

of the party of a country was control to the construction of the second

lavatory and trim; new medicine cabinet and other required accessories; new sheet vinyl finish flooring; new 2'-0 X 6'-8 flush wood door with hardware. Walls shall be vinyl wall covering on gypsum wall-board, floor to ceiling. Provide new ceiling exhaust fan with duct to exterior.

4. New bedroom: Remove screen and enclose existing porch to provide a 4th bedroom, 10 X 9.83 feet with a 2 X 9.83 foot closet. Build up new floor to level of existing concrete slab. Install ½ in. ply-wood subfloor and hardwood strip finish flooring to match existing. Provide 2 new windows compatible with other new windows. Provide new 2'-6 X 6'-8 flush wood door in existing opening between living room and new bedroom. Provide new pair 2'-6 X 6'-8 hinged closet doors. Provide new painted gypsum wallboard on walls and ceiling.

c. Interior-Second Floor

 Closet: Enlarge bedroom closet to 2 X 9.67 feet compatible with entrance modifications on First Floor.

d. Mechanical

- Heating Unit: Remove existing oil fired boiler, controls and convectors. Install new forced air heating and air conditioning system incorporating an electric furnace, condenser and sheet metal ductwork. Ductwork to be installed in crawl space for first floor and in attic for second floor. Provide controls and supply grilles.
- 2. Water Heater: Install new 50 gallon capacity electric water heaters on an "as needed" basis.

e. Electrical

1. Service: Some revisions to local low voltage (2400A) distribution system is required.

Increase capacity of existing service to 200A. Install new breaker type panel.

- a. Add 3 outlets and 1 ceiling fixture in 4th bedroom.
- b. Add fixture/outlet to new bathroom
- c. Add/relocate 8 outlets and add 2 ceiling light fixtures to rehabilitated kitchen/ utility area.
- d. Add new front entrance fixture.

and a standar light of Liber 20 ft on the 20 ft of the standard

The state of the s

PARADISE POINT AREA

Carl org			Design Criteria	Existing Area	Fronos . Aren
Net Area			1400 SF (Max.)	1317 SF	
Living Room			12 ft. min. dim.	13'-2 min. dim. (280 SF)	Same
Dining Room			10 ft. min. dim.	12'-6 min. dim. separate room (181 SF)	Same
Kitchen	n.		U-shape or L-shape	Straight counter (123 SF)	U-shape (91 SF)
11	Vall C a	ab.	24 SF	24 SF	30 SF
3.	Base Ca	ab.	32 SF	42 SF	45 SF
C	Counter		12 SF	24 SF	26 SF
D	Drawers		14 SF	16 SF	16 SF
: Utility	Room			57 SF	
Bedroo.	9	1	155 SF area 8 LF closet	181 SF area 5 LF closet	181 SF area 8 LF closet
		2	130 SF area 6 LF closet	127 SF area 4.67 LF closet	Same
		3	105 SF area 4 LF closet	98 SF area 3 LF closet	Same
,,		4	90 SF area 3 LF closet	None	108 SF area 9.83 LF closet
Bath			$2\frac{1}{2}$ total $\frac{1}{2}$ @ first floor	2 baths up (none @ first floor)	$2\frac{1}{2}$ total $\frac{1}{2}$ @ first floor
Linen			3LF	4-5 LF	Same
Bulk Storage			Comb. int. & ext. 60 SF min. 120 SF max.	Interior: attic Exterior: -0-	Interior: attic Exterior: 24 SF

	TENDER OF OVER YOUR	
the state of the s		

3. Cracker Boxes; Type CGO-3BR-1

a. Exterior

- 1. Off-Street Parking: Construct attached wood frame carport, 11 x 20 feet in size near end of existing driveway inside yard of units. Provide concrete floor slab, pitched for proper drainage, and concrete apron connecting new carport floor to existing concrete driveway strips. Construction of carport and attachment (covered walk) shall be wood frame with composition shingle roof to match house and one of several siding types compatible with contemporized house exterior. Provide alternate for new 10 foot concrete driveway.
- 2. Exterior bulk storage and garbage can enclosure: Construct enclosed covered storage area, 4 x 6 feet, with door and adjacent covered garbage can enclosure, 3 x 5 feet, as an extension to rear of new carport. Construction to match carport. Provide galvanized steel pipe can holder for two cans.
- Patio and walks: Construct new concrete patio, 12 x 12 feet, provide new concrete walks, 3 feet wide, between carport and patio and between driveway and front entrance.
- 4. Contemporize exterior: Remove existing wood siding. Replace with new cedar shingles, brick veneer or stucco. Contemporize front entrance and cover by constructing wing walls, extending existing roof and installing new 3 x 7 foot solid core flush wood door with fixed glass sidelight. Install new aluminum/glass/screen doors at front and rear entrances.

Replace existing windows with new aluminum sliding windows at bedrooms, bath, and kitchen; new fixed and operable wood sash at living room/dining room.

5. Roof replacement: Replace existing roof with new composition shingles to match new carport. Replace existing gutters and downspouts with new copper materials. Reflash on an "as needed" basis.

Partie view william constitute on constitution of the constitution

the same was a large whose home and a second second with a second second

b. Interior

- 1. Kitchen: Remove existing cabinets and counters. Install new sheet vinyl floor. Install new plastic laminate covered work counter and wood cabinets in U-shape arrangement, 9 x 11.5 feet. Provide new double bowl stainless steel sink; garbage disposer; refrigerator and electric range.
- 2. Utility Room: Renovate to include separate furnace/water heater area off utility room. Install 5/8 inch VL rated gypsum wallboard on walls and ceiling of utility room. Install new sheet vinyl flooring. Install new 5'-0 x 6'-8 metal sliding door. Relocate coat closet and provide new 2'-6 x 6'-8 wood door; wood shelf and metal hanging rod.
- 3. New bath: Construct new half bath, 3.5 x 6.5 feet, between bedrooms 1 and 3. Provide new water closet, lavatory and trim; new accessories; new sheet vinyl floor and 2'-6 x 6'-8 wood door. Provide vinyl wall covering floor to ceiling on all walls and new ceiling exhaust fan with duct to exterior.
- 4. Closets: Rearrange BR-2 closets to provide more space. Provide new 2'-6 x 6'-8 wood door, shelf and metal rod.
- 5. Enclosed porch alternate: Remove existing screen and enclose porch with new fixed and operable glass sash. Provide new 3'-0 x 7'-0 solid core flush wood door to exterior.

Build up new wood floor with sleepers of existing living room and install $\frac{1}{2}$ inch plywood subfloor and hardwood finish floor to match existing. Provide new painted typsum wallboard on one wall and ceiling.


6. Install vinyl wall covering on existing bathroom walls.

c. Mechanical

- 1. Install new electric fired forced warm air heating/ air conditioning system with ducts in crawl space.
- 2. Water heater: Install new 50 gallon capacity electric water heaters on an "as needed" basis.


d. Electrical

 Service: Some revisions to local low voltage (2400A) distribution system is required. Increase capacity of existing service to 200A.




2. Fixtures and outlets:

- a. Add 1 outlet to dining area.
- b. Add 4 outlets to renovated kitchen/utility area.
- c. Add 1 outlet/fixture to new bath.
- d. Add 2 outlets to BR-2 and 1 to BR-3.
- e. Add new exterior fixture at entrance.
- f. Add new ceiling fixture and outlet to enclosed porch.
- g. Add 2 fixtures to new carport/storage area.



AREA COMPARISON TABLE

		PARADIS	E POINT AREA	
UNIT TIFE	CK	CREK BOXES; T	YPE CGO-3BR-1	
CALLORY		Design Criteria	Existing Area	Froposed Area
Not Area				
ditte_Rome			294 SF	194 SF
Dining Room			1245	112 SF
Kitchen			925F	105 SF
Wall (Cab.	24 SF		3/SF
Base (Cab.	32 SF		42 SF
Count	er	125F		365F
Drawe	ers	14 SF		275F
Utility Room			30 SF	45 SF
Bedrooms	1	170 SF 64F CLO	161 SF 64F CLO	161 SF 6LFCLO
	2	140 SF 4LF CLO	122 SF 6.5 LF CLO.	122 SF 5LF CLO
	3	110 5F 3LFCLO	107 SF 6.5 LF CLO	1075F 5 LFCLO
Bath		1.5	no half bath	1.5
Linen		3LF	ALF	4LF
Bulk Storage		50-855F comb interior & exterior		20 SF EXTERIOR



4. One Story Cape Cod; Type CGO-4BR-1

a. Exterior

- 1. Off-street parking: Construct attached wood frame carport, 11 x 20 feet in size near end of existing driveway inside yard of units. Provide concrete floor slab, pitched for proper drainage, and concrete apron connecting new carport floor to existing concrete driveway strips. Construction of carport and attachment (covered walk) shall be wood frame with composition shingle roof to match house and one of several siding types compatible with contemporized house exterior. Provide alternate for new 10 foot concrete driveway.
- 2. Exterior bulk storage and garbage can enclosure: Construct enclosed covered storage area, 4 x 6 feet, with door and adjacent covered garbage can enclosure, 3 x 5 feet, as an extension to rear of new carport. Construction to match carport. Provide galvanized steel pipe can holder for two cans.
- 3 3. Patio and walks: Construct new concrete patio, 12 x 12 feet, provide new concrete walks, 3 feet wide, between carport and patio and between driveway and front entrance.
 - 4. Contemporize exterior: Remove existing wood siding. Replace with new cedar shingles, brick veneer or stucco. Contemporize front entrance and cover by constructing wing walls, extending existing roof and installing new 3 x 7 foot solid core flush wood door with fixed glass sidelight. Install new aluminum/glass/screen doors at front and rear entrances.

Replace existing windows with new aluminum sliding windows at bedrooms, bath, and kitchen; new fixed and operable wood sash at living room/dining room.

Replace existing bay window at BR-1 with new bay window of contemporary design.

 Roof replacement: Provide alternate to replace existing roof with new composition shingles to match new carport and other additions. Reflash on an "as needed" basis.

The state of the property of the state of th

n de la marti, sous en promis a que en come fratto en Sensitat el passique en est transporter el significa de la come de

b. Interior

- Kitchen/Utility/Room: Remove existing cabinets and counters. Enlarge area to provide separate utility room off kitchen. Install new sheet vinyl floor. Install new work counter, cabinets and appliances in a modified U-shape arrangement, 9.5 x 13.5 feet. Provide new washer/dryer connections and dryer vent in utility room, 5 x 5 feet.
- 2. Furnace/Water Heater Closet: Provide separate closet, 2 x 6 feet, for furnace/water heater. Provide 5/8 inch VL rated gypsum wallboard and new 2'-6 x 6'-8 metal door.
- 3. New bath: Construct new full bath adjacent to existing bath, 5 x 8 feet. Provide new water closet, tub lavatory and trim; new accessories, sheet vinyl floor and 2'-6 x 6'-8 wood door. Provide ceramic tile wainscot, 6'-6 high at tub; other walls shall have vinyl wall covering, floor to ceiling. Install new exhaust fan with duct to exterior.
- 4. New bedroom: Remove screen and enclose porch to provide a 4th bedroom, 12 x 9.83 feet, with a 2 x 9.83 foot closet. Provide new 2'-6 x 6'-8 wood closet door and new 2'-6 x 6'-8 flush wood door between living room and new bedroom. Wall construction shall be of wood studs, insulation and ½ inch gypsum wallboard interior; exterior siding shall be compatible with main house. Build up new wood floor with sleepers to level of existing living room. Install new subfloor and finish wood floor to match existing. Install vinyl wall covering on existing bathroom walls.
- 5. Closets: Rearrange BR-1 closets to provide more space. Provide new pair 2'-6 x 6'-8 wood doors, shelf and metal rod.

c. Mechanical:

- Install new electric-fired forced warm air heating/ air conditioning system with ducts in attic space.
- 2. Water heater: Install new 50 gallon capacity electric water heaters on an "as needed" basis.

d. Electrical

 Service: Some revisions to local low voltage (2400A) distribution system is required. Increase capacity of existing service to 200A. The second of th

and the first of the following the second response to the second second


and the community of the state of a community of

L.) The Co. Common point is an experience of the Co. Co.

e automorphism


2. Outlets and Fixtures:

- a. Add 3 outlets and 1 ceiling fixture in 4th bedroom.
- b. Add fixture/outlet to new bathroom.
- c. Add/relocate 8 outlets and add 2 ceiling light fixtures to rehabilitated kitchen/utility area.
- d. Add new front entrance fixture.



AREA COMPARISON TAKEA

UNIT TYPE	ONE	E STORY GAPE COL	POINT AREA D; TYPE CGO-4	18R-1
Carreor		Dusign Criteria	Existing Area	- Fropos - L Area
Not Area		1400 SF (Max)	10195F	1172 SF
Livir, Roo	m		Living Dining	
Dining Room			(333 SF)	
Kitchen				
Wall	Cab.			
Base	Cab.			
Count	er			
Drawe	ers			
Utility Room	n			
Bedrooms	1	155 SF BLF CLO	1635F 5 LF CLO	166 SF 11 LF CLO
	2	130 SF 6LF CLO	143 SF 4.5 LF CLO	143 SF 45 LF CLO
	3	105 SF 4 LF CLO	1075F 454FCLO	107 SF 45 LF CLO
	4	90 SF 3 LF CLO	-0-	105 SF 10 4F CLO
Bath		2.0	No half bath	2.0
Linen		34F		
Bulk Storage		GO-LOOSTCOMB. INTERIOR SEXTERIOR	noneexterior	20 SF EXTERIOR



5. Two Story Cape Cod; Type CGO-5BR-1

a. Exterior

- 1. Same as Two Story W/O Garages
- 2. Same as Two Story W/O Garages
- 3. Same as Two Story W/O Garages
- 4. Contemporize exterior: Remove existing siding.
 Replace with new cedar shingles, brick veneer or
 stucco. Install new 3 x 7 foot solid core flush wood
 entrance door and new alum/glas/screen doors at front
 and rear entrance.

Replace existing windows with new aluminum sliding windows at bedrooms, bath, and kitchen; new fixed and operable wood sash at living room/dining room.

b. Interior - First Floor

- 1. Kitchen: Renovate existing kitchen by removing existing counters, cabinets and appliances; install new sheet vinyl floor and new counter, cabinets and appliances in U-shape arrangement, 9 x 9.5 feet.

 Provide washer/dryer area in kitchen, with connections and vent, enclosed with pair 2'-6 x 6'-8 louvered wood doors.
- 2. Same as One Story Cape Cod.
- 3. New bedroom: Construct addition to provide 4th bedroom, 9.83 x 9.33 feet, with a closet, 2x 6 feet. Provide new 2'-6 x 6'-8 bedroom door and pair 2'-6 x 6'-8 wood closet doors.

Construction of walls and roof shall be of wood frame with exterior and interior finishes to match existing. Provide new slab on grade and wood parquet finish floor.

- 4. Existing bath: Renovate existing bathroom to provide new tub, water closet, lavatory and trim; new accessories; new ceramic tile, wainscot 6'-6 high at tub Other walls to have vinyl wall covering floor to ceiling. Install new sheet vinyl floor. Construct new linen closet off bath with painted wood shelves and new 2'-0 x 6'-8 wood door.
- 5. Closets: Construct new coat closet at entry with 2'-0 x 6'-8 wood door, shelf and metal rod. Rearrange closets at BR-1 and 2 to provide more space. Install new pair 2'-6 x 6'-8 wood doors, shelf and metal rod for each new closet.

and the state of t

c. Interior - Second Floor


- New bedroom: Construct new dormer between existing dormers to convert existing attic storage space into 5th bedroom, 11 x 8.5 feet and new closet, 2 x 4 feet, with 2'-6 x 6'-8 wood door. Interior wall and floor finishes to match existing.
- 2. Install new vinyl wall covering on existing bathroom walls.

d. Mechanical

- 1. Same as One Story Cape Cod.
- 2. Same as One Story Cape Cod.


e. Electrical


- 1. Same as One Story
- 2. Outlets and fixtures:
 - a. Add 3 outlets to BR-3
 - b. Add 4 outlets to renovated kitchen/utility area.
 - c. Add 1 new entrance fixture
 - d. Add 2 new fixtures to carport/storage area.
 - e. Add 1 new fixture/outlet to renovated bath.
 - f. Add 3 new outlets to 5th bedroom.





AREA COMPARISON TABLE


		PARADISE	POINT AREA	
UNIT TYPE	: TWC	STORY CAPE CO.	D; TYPE CGO-5	BR-1
Cu., er,		Design Criteria	Existing Area	-Froposoxi Area
No. 10. 10. 10.		1400 SF (MAX)	1133 SF	1347 SF
nivia; Room			215 SF	215 SF
Dining Room			76SF	76SF
Kitchen			133 SF	108 SF
Wall	Cab.	24 5		315F
Dase		32 SF		36 SF
Count		12 SF		18 SF
Drawe		14 SF		18 SF
Utility Room				40 SF
Bedrooms	1	155 SF BLF CLO.	150 SF 4.5 LF CLO	150 SF 55 LF GLO.
	2	130 SF 6 LF OLO.	150 SF 4.5 LF CLO	150 SF 5.5 LF CLO
	3	105 SF 4 LF CLO.	140 SF 4LF CLO	1465F 4LF CLO
4.740 L_	4	905F+34FCLO.	-0-	925F+6LFCLO
	5	90 SF+3LFCLO	-0-	955F+4LF CLO.
Bath		2	2	2
Linen		3 LF	2LF	
Bulk Storage		60-100 SF comb. INTERIOR SEXTERIOR		20SF EXTERIOR













FIRST FLOOR PLAN





-12"x12" RETURN -DOWN TOXIZ SUPPLY RISER -


SECOND FLOOR PLAN














CGO-3BR-1








FRONT ELEVATION


CGO·3BR·1
























FLOOR PLAN




CGO·4BR·1











CGO·5BR·1




FIRST FLOOR PLAN


BLA DILITERAL IN LEAVE SPECE




CGO·5BR·1




CGO·5BR·1




FIRST FLOOR PLAN



CGO-5BR-1



CGO · 5BR · 1



COST ESTIMATING FORM MAYDECKS 2417 (REV. 5-63)

0105 01 3800

CATEGORY CODE NUMBER

FAMILY HOUSING CAMP LEJEUNE, NO PARADISE POINT AREA
TWO STORY WIO GARAGE; TYPE PGO-4BR-1

TITHAUP	IES	MATER	RIAL COSTS	LABO	R COSTS	ENGINEER	ING ESTIMATE
NO. OF UNITS	UNIT	UNIT	COST	UNIT	COST	UNIT	cost
2	3	4	5	6	7	3	9
A	TER	IOR I	MPROVE	MEM	6		
25,95	SF SF SF		,			75.00.5	206. 990. 550. 400.
EMA			The state of				1746.
600	5=					.75	450.
MB.							450.
215. EM C	SF					1	275. 275.
1819	SF ea.					1.20	2172.
	275 295 EM A 600 M B.	275 SF 275 SF 27	NO. OF UNIT COST 2 3 4 ENTERIOR 275 SF 275 SF 275 SF 275 SF M B.	NO. OF UNIT COST COST 2 3 4 5 ENTERIOR IMPROVE 275 SF 275 SF 275 SF 275 SF M B. 275 SF	NO. OF UNIT COST COST 2 3 4 5 6 ENTERIOR IMPROVEMENT 275 SF 495 SF 275 SF W B. 275 SF	NO. OF UNIT COST COST COST COST 2 3 4 5 6 7 ENTERIOR IMPROVEMENTS 275 SF 275 SF 275 SF 275 SF M B. 275 SF	NO. OF UNIT COST COST COST COST COST COST COST COS

COST ESTIMATING FORM NAVDOCKS 2417 (REV. 5-63)

0105 013 3800

AREA OR NO

ACTIVITY LOCATION

SHEET 2 OF 4


IDENTIFICATION NUMBER

CATEGORY CODE NUMBER

PROJECT (Or line item) TITLE

FGO-48R-1

QUANTIT	QUANTITIES		MATERIAL COSTS		LABOR COSTS		ENGINEERING ESTIMAT	
NO. OF UNITS	UNIT	COST	COST	UNIT	COST	UNIT	COST	
	3	4	5	6	7	8	•	
1 1	90.					50-	700.	
							3242.	
FOR 306	4555600	t BE	ORM.			250 655 50:- 90:-	767.70.	
ME							2102	
1008	5*					/,-	1008.	
MF							1008.	
INTE	R10	RIN	PROVE	MEM	5			
45						200.	200	
֡֡֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜	MO. OF UNITS	NO. OF UNITS INTERIO	NO. OF UNIT COST INTERIOR IN	NO. OF UNIT COST COST 2 3 4 5 14 90. M D FOR ATH BEDRM. 3006 SF 480 SF 1408 SF 1008 SF INTERIOR IMPROVE	NO. OF UNIT COST COST COST 2 3 4 5 6 /4 90. M D H FOR ATTH BEDRM. 306 SF 684 SF 684 SF 685 SF	MO. OF UNIT COST COST COST COST 2 3 4 5 6 7 AND D FOR ATTH BEDRM. 306 SF 308 SF ME INTERIOR IMPROVEMENTS	NO. OF UNIT COST COST COST COST COST COST COST COS	



COST ESTIMATING FORM MAYDOCKS 2417 (REV. 5-63)

0105 01: 3900

ACTIVITY

SHEET 3 OF 4


IDENTIFICATION NUMBER

CATEGORY CODE NUMBER

PRILEST TO- line item) TITLE

FGO-4BR-1

ITEM (CA FEATURE) DESCRIPTION	QUANTI	TIES	MATERIAL COSTS		LABOR COSTS		ENGINEERING ESTIMAT	
(Abbreviate if necessary)	NO. OF UNITS	UNIT	UNIT	COST	UNIT	cost	UNIT COST -	COST
1	1	3	4	5	6	7	8	9
2. Partitions	24	4					10.	240.
3+100KIN9	168	SF			148.4		1.	168.
4. Kitcheh cabnts.					10000		950.	950.
B /WINDE	15						1	100
5. DOORS & how.	2	ea					90.	180.
CIP TOTAL ITT	110						-	1000
SUB-TOTAL ITE	VI 6							1738.
CLOSET EXPANSION	N							
CLOSET EXPANSION 1. finished area	20	SF					655	210.
		7					المربي	210
SUB-TOTAL ITE	NH							210.
								0
MECHANICAL	¥							
1 Payan aution								
1. Remove existing	15						1	can
boiler & convectors 2. New furnace,	20						500	500.
ducts & controls	15						ben	2500.
auco y control	~~				No.		fu.	2000.
SUB-TOTAL H	EM 7							3000.
PLUMBING								
1 Ratha (ituan)	_	20					100	110
1. Bath(2 fixtures) 2. Water heater	2	eu					350	100.
2. Water neater	1	cu.					250	250.



COST ESTIMATING FORM NAVDOCKS 2417 (REV. 5-63)

0105 01 3800


IDENTIFICATION NUMBER

AREA OR NO LACTIVITY			
AREA OR NE	ACTIVITY	LOCATION	CATEGORY CODE NUMBER

PROJECT (Or line item) TITLE

FGO-4BR-1

ITEM (OR FEATURE) DESCRIPTION	QUANTITIES		MATERIAL COSTS		LABOR COSTS		ENGINEERING ESTIMAT	
(Abbreviate if necessary)	NO. OF UNITS	UNIT	UNIT	COST	UNIT	COST	UNIT	COST
0.11 10	2	3	4.	5	6	7	8	•
3. Hookup	15						150.	150.
SUB-TOTAL ITE	MJ						-	1100
						da 17		1100.
ELECTRICAL,								
1.200 A panel	2	ea.					300.	300
2. fixture allowand 3. add relocate	6 15						200.	200.
3. add/ Actocale	1/2	90.						400
outers	10	au.					25.	400.
SUB-TOTAL ITE	=114							0.00
								900.
SUB-TOTAL A	602	188	-/					1577
	METERS CONTROL TO A CONTROL OF THE PERSON OF		4 6					9,111
10% CONTING	SNCY							1577.
		-					-	
TOTAL PER H	SUSE							17,342
V 10 Mar			CIA	11121	2)			200
x 40 HOU			(40)	×17,34	5)		69	3,929
Tang at any or any								
								Transfer and
REPARED BY (None)	APPROVED BY		applications who	TITLE	OR ORGANIZAT	ON	DATE	




COST	E	ST	IM	A	T	1	N	G	F	ORM	
NAVDOCK	S	24	7	(8	E	۲		5-	63)	

AREA DA NO	ACTIVITY	
	1-141/2/110/15/11/	
	FAMILY HOUSING	5 5 5 13
	IF AIVIII & FILL I VIVE	5.00

CAMP LEJEUNE NC

PARADISE POINT AREA CRACKER BOX; TYPE CGO-3BR-1

	QUANTIT			AL COSTS		R COSTS	ENGINEER	ING ESTIMAT
(Abbreviate if necessary)	NO. OF UNITS	UNIT	UNIT	COST	UNIT	COST	UNIT	- COST
1	2	3	4	5	COST 6	7	COST -	9
CARPORT, STORAGE 4. & COVERED WALK	E	XTE	RIOR	MPRO	DVEME	ENTS		1746.
DRIVEWAY PATIOS & WALKS								450 275
O.NEW EXTERIOR 1. Replace siding 2. FRONT entrance 3. Storm doors 4. Windows	1287	जिस्स्य स्टिस्टर स्टिस्टर्स			18 (%). 10 (%)		120 230:50.	230 140 550.
SUB-TOTAL ITE	MD)						920
ROOFING I. Main building Remove & Replace SUB-TOTAL ITE!		SF					/	1805
GLAZE PORCH								1000
1. Remove screen 2. Glazing 3. OOOR		SF					100. 3.50 90-	100.
SUB-TOTAL ITE	M F	1			LE OR ORGANIZAT		DATE	946



COST ESTIMATING FORM MAYDOCKS 2417 (REV. 5-63)

0105 01 1 3800

SA NO A IPA

TY LOCATION

SHEET 2 OF 3


DENTIFICATION NUMBER

CATEGORY CODE NUMBER

PPOLEST (Or line stem) TITLE

CGO-3BR-1

TEM (OR FEATURE) DESCRIPTION	QUANTI	TIES	MATER	RIAL COSTS	LABO	R COSTS	ENGINEER	NG ESTIMA
(Abbreviate if necessary)	NO. OF UNITS	UNIT	UNIT	COST	UNIT	COST	UNIT	COST
	2	3	4	5	6	7	8	9
1 10000 100 100 100 100 100	INT	ERI	OR	IMPRO	EMA	NTS		
S. KITCHEN UTILITY								
1. Demolition	.15						250,	250
2. Partitions	23	4					10:	230
3. Flooring	35	P					lim	IIM
4 Cab & odonter		1					1100	1100
SUB-TOTAL IT	EMO	51						1827
+ NEW BATH	_	10					10	01
1. Partitions	00	4					0:-	80
2 Flooring 3 Door Grardwr	20	m					an-	20
4. Wallcovering	168	SF					30	50
							1.50	30.
SUB-TOTAL IT	EM	41						243
- MILE WHO IN	2					•		
OTHER INTERIO	\							
RENOVATIONS								
1. Partitions	22	CF					10.	220
2 DOOKS & HARDING	9	eg					90	270
3. Painting	15						400	400
2 DOOKS & HARDING 3. Painting SUB-TOTAL IT	TXA	-						
NO TOTAL THE	111	41		and the second				890.
EFARED BY (Name)	APPROVED BY			TITU	E OR ORGANIZAT	ON	DATE	



COST ESTIMATING FORM

IDENTIFICATION NUMBER

OF 3

0105 01 1 3800

AREA OR NO ACTIVITY


LOCATION

CATEGORY CODE NUMBER


PROJECT (Or line stea) TITLE

CGO- 3BR-1

EM (OR FEATURE) DESCRIPTION	QUANTIT	IES	MATERIA	AL COSTS	LABO	R COSTS	ENGINEERI	NG ESTIMATI
(Abbreviate if necessary)	NO. OF UNITS	UNIT	UNIT	COST	UNIT	COST	UNIT COST	COST
	2	3	4	5	6	7	8	•
NECHANICAL 1. ROMONE EXISTING boiler & convectors 2. New fur nace, ducts & controls SUB-TOTAL 17	LS LS	J					350. 1500.	350. 1500. 1850.
PLUMBING 1. Half bath Chix 2. Water healer 3. Hook UP SUB: TOTAL	URES) 2 LS ITEN	ea ca					350. 250. /50.	700. 700. 700. 700. 7100.
ELECTRICAL 1.200 A panel 2 Fixtyres 3. outles SUB TOTAL	15 ITEM	ea ea					300 150 25	300. 150. 175.
SUB-TOTAL 10% CONTIN TOTAL PER X 100 H			060 E	:3BR-1				12,677
X 100 H	WES	(13	945.X	100)			1	394,50



COST ESTIMATING FORM SHEET MAYDOCKS 2417 (REV. 5-63) 0105 0: 3800 CAMPLEJEUNE NO PARADISE POINT AREA ITEM (OR FEATURE) DESCRIPTION ENGINEERING ESTIMATE (Abbreviate if necessary) NO. OF UNIT COST COST COST RIMPROVEN A. CARPORT, STORAGE C.PATIOS & WALKS D.NEW EXTERIOR 1. Replace siding 3. Storm dooks Windows 5. Bay window SUB-TOTAL ITEM D E. ENCLOSE PORCH FOR 4TH F. NEW ROOFING 1. Main building Remove & Replace 1420 SUB-TOTAL ITEM G. KITCHEN WILLTY 1. Demolition PREPARED BY (Name) APPROVED BY TITLE CR ORGANIZATION



COST ESTIMATING FORM

0105 01: 3800

SHEET 2 OF 3


DENTIFICATION NUMBER

AGENCY CODE NUMBER

PROLECT /Or line item) TITLE

CGO-4BR-1

ITEM (OR FEATURE) DESCRIPTION	QUANTIT	IES	MATERI	AL COSTS	LABO	R COSTS	ENGINEER	ING ESTIMAT
(Abbreviate if necessary)	NO. OF UNITS	UNIT	COST	COST	UNIT	COST	UNIT	COST
1	2,	3	4	5	6	7	8	9
2. partiuons	10	4					10.	700.
3. +100RING	155	5					1,-	155.
4 Kitchen cabris								,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
# counter	15						1150.	1150.
5. DOORS & hardwr	3	99					90	270.
O. 500 5 7 / Million 1111							10.	210.
SUB-TOTAL ITE	MG							2435.
300 10170 119	<i>"</i> . •							2700.
NEW BATHROOM								
FINEN MET								
phill our								Yes
1. Partitions	10	15					10.	120.
2. Flooring	20	GE					10.	30.
3. CERAMIC THE	50	3=					2	160
4 rinyl wall cover	IAA	SE					in	10
5 doors & hardwr	14	m					an-	16%
J. Goons Francis		· w					10.	100.
SUB-TOTAL ITE	MH							523.
	• • • • • • • • • • • • • • • • • • • •							020.
. UTILITY ROOM								
I Additional appar	21	SE					18-	618
1. Additional area	30	SF					10.	040.
SUB-TOTAL H	E ME	-						1.10
WO TOTAL TIE	411 7	- 1	A Buck					048,
SUB-TOTAL ITE MECHANICAL I. Remove existing								
1 ROMOR DXISTING								
miler & mountains	15						250	250
REPARED BY (Name)	APPROVED BY				E OR ORGANIZAT		W.	W.



COST ESTIMATING FORM MAYDOCKS 2417 (REV. 5-63)

G105 61 3800 E

SHEET 8 OF 3


IDENTIFICATION NUMBER

CATESORY CODE NUMBER

PROJECT /Or sine stem; TITLE

CGO-48R-1

TEM (CR FEATURE) DESCRIPTION	QUANTIT	IES	MATERI	AL COSTS	LABOR	R COSTS	ENGINEER	ING ESTIMAT
(Abbreviate if necessary)	NO. OF UNITS	UNIT	COST	COST	UNIT	COST	UNIT	COST
1 0,000	1	3	4	•	6	7 2	8	1
2 New furnoce ducts & controls	15						1750	1750
SUB-TOTAL ITEM							1750.	1750
								2100
PLUMBING I New bath (3-fixt.) 2 Water heater 3. Hookup								
I New bath (3-pxt.)	3	ea					350.	1050
2 Nater realer		ea					250.	250
3. HOOKUP	15						150	150
SUB-TOTAL ITE	MK							450
								1100
ELECTRICAL,	,	20					244	200
1. 200 A Panel	20 /4	54.					300.	150
2. FIXTURE allowand 3. add/relocate outlets							150.	150
outlets	//	ca					25.	275.
CUP TOTAL H	-11					•	1 +	
SUB-TOTAL IT		-						725.
SUB-TOTAL T	IPE (29	7.4E	38-1				17372
								1727
10% CONTINE								1731.
TOTAL PER A	MIS	E						1910
	The second second		110				1 +	
X 43 Ha	USES		(43)	(19,10	9)			321.69




COST	E	STIM	ATI	NG	FORM	
MAYDOCK	S	2417	(REV.	5-	63)	

0105 01: 3800

SHEET / OF 3

IDENTIFICATION NUMBER

ANEA OR NE	FAMILY H	OUSING	GAMP	LEJEUN	ENC	CATEGORY	CODE NUMBER	
PNOTICE TOP LINE	itea) TiTLE		DISE P	CAPE C	REA		260 £	BR-1
ITEM (OR FEA	TURE) DESCRIPTION	"QUANTITIE:	S MATER	RIAL COSTS	LABO	R COSTS	ENGINEER	ING ESTIMATE
(Abbrevia:	te if necessary)	NO. OF UNITS	NIT COST	COST	UNIT	cost	UNIT	COST
	1		3 4	5	6	7	8	9
DONE OF NEW 2 NEW 3. ENTR	SEVALKS EXTERIOR VE SIDING Siding	13605	FFAGGA	DR IMF	ROVA	MENT	20,000	1746. 4505. 272. 1900. 140. 272.
NEMOVE SUB	building the replace TOTAL ITE	1320S M E	AREA:	5			/,-	1320. 1320.
-	TIONAL L f floor add the bed ROO		F				18	2880.
JOR 51	HOOR dorn h bedroom 3-TOTAL	545	 				18	972.
PREPARED BY (Name)	1-1110	APPROVED BY		17171	OR ORGANIZAT	TON) DATE	1001



COST ESTIMATING FORM NAVDOCKS 2417 (REV. 5-63)

0105 01 1 3600

SHEET 2 OF 3

IDENTIFICATION NUMBER

AREA CH NO

ACTIVITY


LOCATION

CATEGORY CODE NUMBER

PROJECT for line stea) TITLE

0GO-5BR-1

TEM (OR FEATURE) DESCRIPTION	"QUANTI"	TIES	MATERI	IAL COSTS	LABOR	COSTS	ENGINEER	ING ESTIMAT
(Abbreviate if necessary)	NO. OF UNITS	UNIT	UNIT	COST	UNIT	COST	UNIT COST .	COST
1	1	3	1,00	5	6	7	8	
1 1000015.11.	11	VIE	RIOR	IMPR	DVEME	W/5		
6. KITCHEN JUTILITY 1. Demolition							100	110
1. Demolition	15	1					400.	400.
2. Partitions	10	4					10,-	100.
3, HOOKING top	75	SF					11-	75.
4. COO, & COUTICK	45	an					1000.	1000.
5. doors# hardwr	= M	99					90.	90.
SUB-TOTAL IT	4116	7						7665.
I. RENOVATE								1
EXISTING BATH								108
THE OWNERS								700.
OTHER INTERIO	R							
RENOVATIONS								
1. Anetitions	16	LF					10,-	460.
2 Doors & hardwa	5	an.			1		90-	450
2 DOORS & hardware 3. Painting	15						600.	600.
SUB-TOTAL	MEN	11				•		1510
								510
MECHANICAL							FAA	700
/ KCMOVECXISTING	15						1300.	200,
boiler & convectors	10						200	100
2 New furnace	15						£500.	2500
ducts of controls	TTAN	1						nan
DOUDING!	IAVI	7				Magazinak di S		3000.
PEPARED BY (Name)	APPROVED BY		L	Tri	TLE OP ORGANIZAT	ION	DATE	L



COST ESTIMATING FORM NAVDOCKS 2417 (REV. 5-63)

0105 01: 3800

SHEET

053

IDENTIF: CATION NUMBER

AREA OR NO

ACTIVITY


LOCATIO

CATEGORY CODE NUMBER

PROJECT (Or line item) TITLE

C60-5BR-1

EM (OR FEATURE) DESCRIPTION	QUANTIT	TES	MATERI	AL COSTS	LABO	R COSTS	ENGINEER	ING ESTIMAT
(Abbreviate if necessary)	NO. OF UNITS	UNIT	UNIT	COST	UNIT	cost	UNIT	COST
1	2	3	4	5	6	7 .,	8	,
t. PLUMBING 1.Bath fixtures 2. Nater heater 3. Hookup SUB-TOTAL ITE	3/25 M H	ea.					150. 250 150	450. 250. 150.
ELECTRICAL 1.200 A panel 2. FIXTURES 3 OUT lets 5UB TOTAL	150	ea ea I					300. 150. 25.	300. 150. 250. 700.
SUB-TOTAL			60·	5BR-				18,043
TOTAL PER	HOUS	E				•		19847
× 24 H	NOE	٥		X2	4)			716,328
PARED BY (Name)	APPROVED BY			[7]	TLE OR ORGANIZAT	ION	DATE	



PART III - TARAWA TERRACE I

A. EXISTING CONDITIONS

- 1. The types of NCO and EM family housing units considered in this Section of this study are located in TARAWA TERRACE, SECTION I on the base at Camp Lejeune, North Carolina. These housing units, completed in 1953, do not meet current minimum adequacy standards for military housing. The deficiencies are in net living area; kitchen, bath and storage facilities; fire separation; thermal and sound insulation; other amenities such as patios and air conditioning. The installation of central air conditioning equipment and supply duct work is currently under contract and is not included as part of this study excepting where modifications are required for compatability with recommendations contained herein.
- 2. The Area Comparison Table included with Requirements for each housing type, Part III, B of this study, indicate the areas of deficiency.
- 3. Latest Family Housing Surveys indicate a deficit of 4BR or more units and a large surplus of 3BR units in the NCO and EM categories. Refer to Recommended Improvements, Part III, C of this study for methods to increase bedroom count.
- 4. The following field survey results for each unit type indicate typical existing conditions.

The first of the second of the

FIELD SURVEY OF EXISTING HOUSING CONDITIONS MARINE CORPS BASE, CAMP LEJEUNE, NORTH CAROLINA

TARAWA TERRACE I

,	UNIT	TYPE	BASIC	3BR:	EM-3BR-1

COMPLETED 1953 PORCHES ADDED: 1965

EXTERIOR CONDITIONS

. S	ITE	REMARKS
1.	Landscaping	Adequate
2.	Parking	Off street parking adequate in number (32 cars for 16 units at this location). Some paving and curb deterioration.
3.	Pedestrian Circulation	Poor; additional walks needed. Some deterioration of existing walks.
4.	Playground & Game Facilities (Community Center)	Scattered and deteriorated playground equipment in yards.
5.	Other	Some tenant owned equipment, fencing and alterations exist. Unsightly clotheslines on street side.
	TE UTILITIES Sanitary Sewer	Line size minimun; slow drainage; evidence of roots or other obstruction in lines.
7.	Storm Drainage	Swales in yards; some evidence of standing water.
8.	Water Supply	Could not find outside cutoff for each unit; multiple units on 1 valve.
9.	Electrical Distribution	CP&L (public utility company)
10.	Other	

TO HAVE BEING THE STREET THE

and the second


BUILDING	REMARKS
11. Reofing	Composition shingles new in 1960-61; no evidence of leaks; 3-5 year life remaining.
12. Siding	Asbestor shingles-poor condition; wood siding-some evidence of rot; cedar shingles-good condition.
13. Windows	Metal casements in wood frame; poor operation; screens in poor condition.
14. Doors	Poor condition; screens badly damaged.
15. Storage	Bulk storage on porch. Poor condition.
16. Trash Removal	By means of 6&8 CY dumpsters (2 per 12-20 units avg.); dumpsters in yards with no pad under; in some cases dumpsters are in street circulation pattern.
17. Fire Separation	Masonry firewall between each 3 units; no rated separation between units.
18. Other	No gutters or downspouts

D.	CT	'D	חוו	וחד	ID	AY
D.	01	L	UU	1 (117	AL

19. Floor Joists	Slab on grade
20. Wall Studs	Some random evidence of termite damage.
21. Ceiling/Roof Trusses	Some sagging at opening between living room and kitchen.
22. Other	There are 92 units on crawl space. Some random evidence of rot and termite damage.
E. KITCHEN	Inefficient arrangement
23. Sink	Double bowl porcelin enamel; some chipping; generally fair condition.

Pour les verdennes monteners supplieurs penul de

	REMARKS
24. Carbage Disposer	None
25. Countertop	Good condition; inadequate size and poor arrangement.
26. Cabinets	Fair condition; inadequate size and poor arrangement.
27. Refrigerator	14 CF; good condition
28. Range	20" gas; good condition
29. Exhaust	Fan in clg. above range w/pull chain; fair condition.
30. Washer/Dryer	Connection in kitchen; poor location and inefficient arrangement.
31. Other	
BATHROOMS	No half bath
32. Toilet	Poor condition (broken seat, come chipping)
33. Tub (steel)	Some evidence of rust
34. Lavatory	Some chipping of finish
35. Accessories	Adequate
36. Wainscot	Plastic laminate nailed to wall at tub; poor condition.
37. Other	



F.	. FINISHES	REMARKS
	38. Floors	Asphalt tile floor throughout; poor condition
	39. Walls	Painted gypsum wallboard; fair condition.
	40. Ceilings	Painted GWB; fair condition.
	41. Other	5/8" plywood sliding closet doors; poor condition; some damage.
G.	. MECHANICAL EQUIPMENT 42. Heating Unit	Gas-fired space heater exposed to view in living room.
	43. Water Heater	Gas-fired, vented thru roof; exposed in kitchen (30 gal.
в т	44. Piping	Uninsulated in attic; previous problems of freezing. Ap adequate however recent rehab, of off-base units nearb resulted in a finding of complete deterioration of water
	45. Other	supply piping.
н.	. ELECTRICAL	
	46. Service	100 A fused panel is inadequate for rehabilitation.
	47. Outlets	Deficit of 4 in bedrooms
	48. Light Fixtures	None in living room
	49. Wiring	Appears adequate
	50. Other	Master TV antenna hook-up; no doorbell


and in the second of the secon

activity distance of months and also also beauty and

Its rider on the section when These a

PARTY TANKS

I	. MISCELLANEOUS	REMARKS	
	51. Insulation (Thermal & Sound)	Blown in termal insulation @ clg. joists; no sound insulation between units.	
	52. Other (Hardware)	All locksets and knobs rusty and slow operation; some hardware missing.	



FIELD SURVEY OF EXISTING HOUSING CONDITIONS MARINE CORPS BASE, CAMP LEJEUNE, NORTH CAROLINA

TARAWA TERRACE I

UNIT TYPE BASIC 2BR, TYPE EM-2BR-1

COMPLETED 1953

PORCHES ADDED: 1965

EXTERIOR CONDITIONS

SITE	REMARKS
1. Landscaping	Adequate
2. Parking	No off street parking at this location
3. Pedestrian Circulation	Same as basic 3BR
4. Playground & Game Fac	cilities Same as basic 3BR
5. Other	Same as basic 3BR
SITE UTILITIES 6. Sanitary Sewer	Plumbing backup; probably from tree roots in lines.
7. Storm Drainage	Same as basic 3BR
8. Water Supply	Adequate
9. Electrical Distribution	CP&L (public utility company)
O. Other	





FIELD SURVEY OF EXISTING HOUSING CONDITIONS MARINE CORPS BASE, CAMP LEJEUNE, NORTH CAROLINA

TARAWA TERRACE I

UNIT TYPE BASIC 2BR, TYPE EM-2BR-1

COMPLETED 1953

PORCHES ADDED: 1965

EXTERIOR CONDITIONS

SITE	REMARKS
1. Landscaping	Adequate
2. Parking	No off street parking at this location
3. Padestrian Circulation	Same as basic 3BR
4. Playground & Game Facilities	Same as basic 3BR
5. Other	Same as basic 3BR
SITE UTILITIES 6. Sanitary Sewer	Plumbing backup; probably from tree roots in lines.
7. Storm Drainage	Same as basic 3BR
8. Water Supply	Adequate
9. Electrical Distribution	CP&L (public utility company)
O. Other	

TRANSPORT VANA

contact and the tenth and the same of the

The same of the sa

software and the stream and the first time of the second state of

C. BUILDING	REMARKS:
11. Roofing	Same as basic 3BR
12. Siding	Vertical wood and asbestor shingle
13. Windows	Some broken panes; torn screens, metal casements in wood frames.
14. Doors	Screens damaged
15. Storage	Bulk storage on porch; fair condition.
16. Trash Removal	Same as basic 3BR
17. Fire Separation	Same as basic 3BR
18. Other	
. STRUCTURAL	INTERIOR CONDITIONS
19. Floor Joists	Slab on grade
20. Wall Studs	Same as basic 3BR
21. Ceiling/Roof Trusses	Adequate
22. Other	Same as basic 3BR
. KITCHEN	Inefficient arrangement
23. Sink	Small porcelin enamel; badly chipped

HEE CHEEK CHICK OF

		REMARKS
24.	Garbage Disposer	None
25,	Countertop	Inadequate size; fair condition
26.	Cabinets	Inadequate size; poor condition
27.	Refrigerator	9CF size; poor condition
28.	Range	20" Gas, fair condition
29.	Exhaust	Fan in clg. above range with pull chain; fair condition
30.	Washer/Dryer	Washer conn. under sink; dryer next to ref.; poor arrangement.
31.	Other	No dining room; no utility room; poor living room fenestration as window opens to enclosed porch.
• BA	THROOMS	Same as basic 3BR
32.	Toilet	
33.	Tub (steel)	Same as basic 3BR
34.	Lavatory	Small; badly chipped
35.	Accessories	Same as basic 3BR
36.	Wainscot	Same as basic 3BR
	Other	

the manufactor of tolder and arbitraries and discount

35795 2 TOOL 45869 T.

minor is a concine to the second

and the property of the control of the control of the control of

The first

Basic Control of Basica


Silver of building a season of the control of the c

FINIS IES	REMARKS	
38. Facors	Same as basic 3BR	
39. Walls	Same as basic 3BR	
40. Ceilings	Same as basic 3BR	
41. Other	Same as basic 3BR	
MECHANICAL EQUIPMENT		
42. Heating Unit	Same as basic 3BR	
43. Water Heater	Same as basic 3BR	
44. Piping	Same as basic 3BR	
45. Other		
ELECTRICAL		
46. Service	100 A fused panel inadequate for rehabilitation	
47. Outlets	Deficit in bedroom (2 in each)	
48. Light Fixtures	Some outside fixtures inoperable. Ceiling fixture needed in living room.	
49. Wiring	Same as basic 3BR	
50. Other	Same as basic 3BR	

KIND OF A DOMESTIC OF A STORY

MISCELLANEOUS		REMARKS	
51.	Lisulation (Thermal & Sound)	Same as basic 3BR	
52.	Other	Same as basic 3BR	

!



B. REQUIREMENTS

1. General

- a. Convert existing method of garbage collection from dumpsters to individual garbage cans for each unit.
- Remove deteriorated and scattered playground equipment.

2. Basic 3BR (Multi-Family); Type EM-3BR-1

a. Exterior

- 1. Provide patio and pedestrian walks
- 2. Provide garbage can enclosure screen
- 3. Remove existing clothesline poles
- 4. Contemporize building exterior
- 5. Install new roof

b. Interior

- Increase net living area, closet and bulk storage space.
- 2. Add half bath and utility room.
- 3. Renovate existing baths. Provide ceramic tile wainscot and sheet vinyl flooring.
- 4. Renovate kitchen to accomodate efficient new U-shaped counter arrangement.
- Remove existing asphalt tile floor. Replace with new radium treated wood parquet flooring.
- Replace interior doors and hardware.
- 7. Provide 1 hour fire separation between units.

c. Mechanical

 Replace existing gas-fired space heater with new forced air system. Provide furnace/water heater enclosure. Replace water heaters.

d. Electrical

Increase capacity to accommodate rehabilitation.
 Add additional electric outlets compatible with other recommended improvements.

men successive and the second second

The Market Company of the Company of

A service and a service of the property

Hilly states on a state of the interest of the deli-


3. Basic 2BR (Multi-Family); Type EM-2BR-1

a. Exterior

- 1. Same as Basic 3BR
- 2. Same as Basic 3BR
- 3. Same as Basic 3BR
- 4. Same as Basic 3BR
- 5. Same as Basic 3BR

b. Interior


- 1. Same as Basic 3BR
- 2. Add utility room
- 3. Renovate existing bathroom
- 4. Same as Basic 3BR
- 5. Same as Basic 3BR
- 6. Same as Basic 3BR
- 7. Same as Basic 3 BR
- 8. Same as Basic 3BR
- 9. Same as Basic 3BR



- 4. Type A (Multi-family); Type EM-3BR-2
- 5. Type A (Multi-family); Type EM-4BR-1
- 6. Type B (Multi-family); Type EM-3BR-3
- 7. Type C-1 (Multi-family); Type EM-3BR-4
- 8. Type C-2 (Multi-family); Type EM-3BR-5
- 9. Type X-1 (Multi-family); Type EM-3BR-6
- 10. Type X-2 (Multi-family); Type EM-4BR-2

Staff NCO quarters

- 11. Type O-1 (detached); Type NCO-3BR-1
- 12. Type O-3 (detached); Type NCO-3BR-2
- 13. Type O-4 (detached); Type NCO-2BR-1



14. Types OD-1A & OD-1B (Semi-detached); Type NCO-5BR-1

a. Exterior

- 1. Convert 1 screened porch into patio; remove 1 porch; provide pedestrian walks.
- 2. Provide garbage can enclosure screen
- 3. Contemporize building exterior
- 4. Install new roof

b. Interior

- 1. Convert two units into one 5BR, 2 bath unit.
- 2. Relocate one bathroom; renovate one existing bathroom.
- 3. Renovate existing kitchen to accommodate new efficient U-shape arrangement.
- 4. Provide utility room.
- 5. Remove existing asphalt tile floor, install new radium treated wood parquet flooring.
- 6. Replace interior doors and hardware

c. Mechanical

- Install new electric-forced air heating/air conditioning system.
- 2. Replace water heater.

d. Electrical

- Increase service capacity and add/relocate outlets to accommodate improvements.
- 2. Install new light fixtures throughout.

en en galengaffenen inggeren som eller eller och att som eller att som e

15. Type OD-2 (Semi-detached); Type NCO-4BR-1

a. Exterior

- 1. Same as Type OD-1A&1B
- 2. Same as Type OD-1A&1B
- 3. Same as Type OD-1A&1B
- 4. Same as Type OD-1A&1B

b. Interior

- 1. Convert 2 units into one 4BR, 2 bath unit.
- 2. Renovate existing bathrooms
- 3. Renovate existing kitchen
- 4. Provide utility area. (Same as Type OD-1A&1B)
- 5. Same as Type OD-1A&1B
- 6. Same as Type OD-1A&1B


c. Mechanical

- 1. Same as Type OD-1A & 1B
- 2. Same as Type OD-1A & 1B

d. Electrical

- 1. Same as Type OD-1A & 1B
- 2. Same as Type OD-1A & 1B

16. Type OD-3 (Semi-detached); Type NCO-2BR-2



C. DESCRIPTION OF RECOMMENDED IMPROVEMENTS

1. General

There being a deficit of 4BR or more units and a surplus of 3BR units in the NCO and EM categories, it is recommended that the present type OD-1 units (consisting of a duplex containing 1-1BR and 1-2BR unit) be combined to provide 13-5BR quarters and the present type OD-2 units (duplexes containing 2-1BR units) be combined to provide 11-4BR quarters in the NCO category.

It is further recommended that approximately half the present type A units and all type X-2 units be improved to include a 4th bedroom, thereby providing 29-4BR quarters in the EM category.

2. Basic 3BR (Multi-family); Type EM-3BR-1

a. Exterior

- Patio and walks: Remove existing screen porch and flat roof (existing bulk storage room to remain). Remaining concrete porch slab will be a usable open patio. Provide new 3 foot wide concrete walk to garbage can area. Install new 8 x 7 foot sliding glass door to patio.
- 2. Garbage can enclosure: Construct covered garbage can enclosure, 3 x 5 feet, as an extension of existing bulk storage room. Enlarge storage room to 4 x 10 feet to afford patio privacy. New construction shall be of wood frame with composition shingle roof and siding compatible with buildings. Provide galvanized steel can holder for two cans.

The residence of the property of the property

manifer the state of the manifered distribution of parties.

3. Contemporize exterior: Remove existing asbestos shingle, wood and striated plywood siding. Replace with new stucco; or combinations of stucco and cedar shingles; stucco and tedlar coated composition siding or other comparable materials with long life and low maintenance qualities. Existing cedar siding may remain where in good condition. It is recommended that exterior siding materials vary from building to building, (rather than unit to unit as at present) and that a unified neighborhood appearance be accomplished through the repetitive use of one material; in this case, stucco.

Install new side entrance of 3 X 7 foot solid core flush wood door and glass sidelight. Install new aluminum and glass/screen door at entrance.

Replace existing metal casement windows with new aluminum sliding sash compatible with exterior design.

4. Roof: Replace existing roof with new 235# composition shingles. Schedule of roof replacement should be coordinated with building additions phase for proper material match. Reflash on an "as needed" basis.

b. Interior

- 1. Additional living area: Construct new wood frame addition at end of unit, 7 X 24.67 feet, providing 168 SF additional net living area. Construction shall be slab on grade with wood frame walls, wood roof trusses and gypsum wallboard finish walls and ceiling to match existing. Install new wood parquet floor. Relocate wall of BR-3 to increase net area. Remove existing plywood clothes closets and sliding doors. Construct new closets, with stud walls and gypsum wall board finish, to provide additional storage. Install new hinged closet doors throughout.
- 2. New bath and utility room: Install new half bath, 5 X 5 feet, adjacent to existing bath. Provide new water closet; lavatory and trim; medicine cabinet and required accessories; new sheet vinyl floor; new vinyl wall covering, floor to ceiling; new 2'-0 X 6'-8 flush wood door with hardware, at bath. Add utility room, 5 X 5 feet, provide washer/dryer connections; dryer

The remains a second of the se

- vent thru roof; new sheet vinyl floor.
- 3. Existing bath: Remove existing plumbing fixtures; replace with new tub, water closet and lavatory; replace trim. Remove existing plastic laminate wainscot; replace with new ceramic tile; set in cement mortar 6'-6" high at tub. Other walls to have vinyl wall covering floor to ceiling. Install new sheet vinyl floor. Provide new accessories.
- 4. Kitchen: Remove existing cabinets, counter and appliances. Install new wood cabinets and plastic laminate covered work counter in U arrangement. Provide new double bowl stainless steel sink and trim; garbage disposer; refrigerator and electric range. Install new sheet vinyl flooring.
- 5. Floors: Remove existing asphalt tile. Install new radium treated wood parquet flooring in mastic over existing concrete slab.
- 6. Hardware: Replace finish door hardware throughout.
- 7. Fire separation: Add one layer 5/8 in. UL rated gypsum wallboard to each side of partitions between living units to provide 1 hour separation.
- 8. Furnace/water heater enclosure: Construct closet enclosure of wood studs with 5/8 in. gypsum wall-board walls and ceiling. Provide louvered door.

c. Mechanical

- HVAC: Remove existing gas-fired space heater.
 Install new electric furnace connected to concealed sheet metal duct system. Modify existing ducts for compatibility with recommended improvements.
- 2. Water heater: Replace existing gas-fired water heaters with new 50 gal. capacity electric heaters.

d. Electrical

- 1. Service: Increase existing 100A service to 150A capacity. Install new breaker type panel.
- 2. Outlets and fixtures: Replace all existing light fixtures.
 - a. Add 2 outlets to BR-1
 - b. Add 1 outlet each to BR-2&3
 - c. Add 3 outlets to living-dining area
 - d. Add 2 new clg. fixtures to living-dining area

TARAWA TERRACE I

Car		Donies Cuitania		
Category		Design Criteria	Existing Area	Proposed Area
Net	Arc.1080	1080 SF (Max)	868 SF	1007 SF
Living Room		12 Ft. min. dim.	(196 SF)	(246SF)
Dining Room		9'-6 min. dim.	Kitchen/dining combination	Separate area (94 SF)
Kitcher	n	U-shape of L-shape	Inefficient arrangement (151 SF)	U-shape arrangement 72 SF
V	Wall Cab.	24 SF (min.)	19 SF	26 SF
Base Cab.		32 SF (min.)	26 SF	48 SF
C	Counter	12 SF (min.)	10 SF	24 SF
Drawers		14 SF (min.)	11 SF	16 SF
Utility Room			None	30 SF area off kitchen for wash/dry
Bedroo	ms 1	150 SF area 6 LF closet	133 SF area 5 LF closet	142 SF area 6 LF closet
	2	125 SF area 4 LF closet	115 SF area 4.5 LF closet	115 SF area 7 LF closet
	3	100 SF area 3 LF closet	92 SF area 5 LF closet	111 SF area 3.5 LF closet
Bath		1.5 (min)	1.0	1.5
Linen		2 LF	2.5 LF	3 LF
Bulk Storage		50-85 SF total; 24 SF min. exterior	none interior; 24 SF exterior	40 SF (exterior) 16 SF (interior) 56 SF total

	일 이 마시 아이는 얼마는 요리를 하고 하는 사람들은 유가를 가다면 가다면 요하다면 되었다. 이렇게
The state of the s	
The second are specifically	
A Commence of the Commence of	
-585	
The second se	

3. Basic 2BR (Multi-family); Type EM-2BR-1

a. Exterior

- 1. Same as basic 3BR
- 2. Same as basic 3BR
- Contemporize exterior: Remove existing siding. Replace with new stucco, stained vertical wood or tedlar coated composition siding.

Install new 3 x 7 foot solid core flush wood entrance door. Install new aluminum/glass/screen door at front and rear entrances.

Replace existing met. casement windows with aluminum horizontal sliding sash. Provide new fixed and operable wood sash at dining room.


4. Roof: Same as 3BR

b. Interior

- 2. New utility room: Construct new utility room, 7.5 x 6.5 feet, containing washer/dryer connections and furnace/water heater, adjacent to existing bathroom. Install 5/8 in. UL rated gypsum wallboard on walls and ceiling. Install new sheet vinyl floor. Install new 2'-6 x 6'-8 wood door.
- 3. Same as Basic 3BR
- 4. Same as Basic 3BR
- 5. Same as Basic 3BR
- 6. Same as Basic 3BR
- 7. Same as Basic 3BR


c. Mechanical

- HVAC: Remove existing gas-fired space heater. Install new electric-fired forced warm air heating/air conditioning system. Modify existing ductwork to accommodate recommended improvements.
- Water heater: Replace existing gas-fired water heater with new 30 gal. capacity electric heater.




d. Electrical

- 1. Service: Increase existing 100A service to 150A. Install new breaker type panel.
- 2. Fixtures and outlets: Replace existing light fixtures throughout.
 - a. Add 1 outlet to each bedroom
 - b. Add 2 outlets to dining room
 - c. Add 4 outlets and fixture to utility room
 - d. Add 2 outlets to kitchen



TARAWA TERRACE I

UNIT	TYPE: 1	BASIC 2 BR; TYPE EM-2BR-	1	
Category		Design Criteria	Existing Area	I ronose ! Ars:
Net Area		950 SF (max)	726 SF	761 SF
Living Room		12' min. dim.	174 SF	174 SF
Dining	g Room	9'-0 min. dim.	Kitchen/dining combination	Separate area (70 SF)
Kitchen		U-shape or L-shape preferred	(136 SF)	U-shape arrangemen (72 SF)
	Wall Cab.	21 SF (min)	12 SF	26 SF
	Base Cab.	28 SF (min)	12 SF	48 SF
	Counter	10 SF (min)	6 SF	24 SF
	Drawers	12 SF (min)	6 SF	16 SF
Utility	Room	Required	None	45 SF for Wash/Dry and Furn/WH
Bedroo	oms 1	10' min. dim. 150 SF area 6 LF closet	94 SF area 4.5 LF closet	135 SF area 6.5 LF closet
	2	9'2 min. dim. 125 SF area 4 LF closet	94 SF area 3.5 LF closet	113 SF area 6.5 LF closet
2				
Bath		1.0	1.0	1.0
Linen		2LF	2LF	2.5 LF
Bulk Storage		40-70 SF total; 24 SF min. exterior	None interior 24 SF exterior	40 SF exterior 13 SF interior 53 SF total



- 4. Type A (Multi-family); Type EM-3BR-2
- 5. Type A (Multi-family); Type EM-4BR-1
- 6. Type B (Multi-family); Type EM-3BR-3
- 7. Type C-1 (Multi-family); Type EM-3BR-4
- 8. Type C-2 (Multi-family); Type EM-3BR-5
- 9. Type X-1 (Multi-family); Type EM-3BR-6
- 10. Type X-2 (Multi-family); Type EM-4BR-2

Staff NCO quarters

- 11. Type O-1 (detached); Type NCO-3BR-1
- 12. Type O-3 (detached); Type NCO-3BR-2
- 13. Type O-4 (detached); Type NCO-2BR-1

14. Type OD-1A & OD-1B (Semi-detached); Type NCO-5BR-1

a. Exterior

1. Convert existing screen porch to patio: Remove screen and flat roof from existing porch to rear of OD-1A unit; existing bulk storage to remain and be enlarged. Construct 3 foot wide concrete walk from patio to garbage can area. Install new 8 x 7 foot sliding glass door to patio.

Remove existing screen porch from end of OD-1B unit entirely.

- 2. Garbage can enclosure: Same as Basic 3BR
- Contemporize exterior: Remove existing siding.
 Replace with new stucco, stained vertical wood siding or brick veneer.

Install new main entrance of 3 x 7 foot solid core flush wood door and fixed glass sidelight. Provide new alum/glass/screen door.

Replace existing metal casement windows with new aluminum horizontal sliding sash.

4. Roof: Same as Basic 3BR

b. Interior

- 1. Remove existing interior partitions and construct new wood stud/gypsum wallboard partitions as shown on drawings.
- 2. Bathrooms: Remove existing bath at OD-1A unit. Install new full bathroom adjacent to existing; provide new water closet, lavatory and trim; new 36 x 36 in. shower with ceramic tile floor, curb and wainscot, 6'-6 high; new accessories; new sheet vinyl floor and vinyl wall covering on walls.

Renovate existing bathroom: Same as Basic 3BR (para. C, 2, b, 3).


- 3. Kitchen: Remove existing kitchen equipment. Construct new kitchen, 8 x 12 feet; install new counter, cabinets and appliances in U-shape arrangement. Install new sheet vinyl flooring.
- 4. New utility room: Same as Basic 2BR.
- 5. Floors: Same as Basic 3BR.
- Doors and hardware: Replace existing interior doors with new hollow core flush wood hinged doors of appropriate sizes. Install new stainless steel hardware.

c. Mechanical


- 1. HVAC: Same as Basic 3BR
- 2. Water heater: Replace existing gas-fired heater with new 50 gal. capacity electric water heater.

d. Electrical

- 1. Service: Same as Basic 3BR
- 2. Outlets and fixtures: Replace existing light fixtures throughout.
 - a. Add 8 outlets/2 new fixtures to new kitchen/utility room ares.
 - b. Add 1 outlet/fixture to new bathroom.
 - c. Add 2 outlets/2 new fixtures to hall.
 - d. Add 2 outlets to BR-1
 - e. Add 2 outlets to BR-2
 - f. Add 2 outlets to BR-3



UNIT TYPE	00	-IA & IBS TYPE N	TERRACE 1			
Cue, i.e.		Design Criteria	Existing Area	Proposed Area		
Not All a		1250 SF (Max.)	1417 SF	1367 SF		
Living Korea				283 SF		
Dining Room				85SF		
Kitchen				85SF		
Wall (Cab.	24 SF		36 SF		
Base (Cab.	32 SF		36 SF		
Counter		12 SF		30 SF		
Drawers		4 SF		20 SF		
Utility Room			NONE	48 SF		
Bedrooms	1	140 SF 6 LF CLO		173 SF 7.5 LF CLO		
	2	115 SF 4 LFCLO		120 SF 8.5 LF CLO		
	3	100 SF 3LF CLO		120 SF 8.5 LF CLO		
	4	90 SF+ 3LF CLO		115SF + 10 LFCLO		
	5	905Ft SLFCLO		935 +5.5 LF CLO		
Bath		2.0	2.0	2.0		
Linen		2LF		2LF		
Bulk Storage		100-100 SF COMB:				



15. Type OD-2 (Semi-detached); Type NCO-4BR-1

a. Exterior

- 1. Convert existing screen porch to patio. Remove existing screen, flat roof and wooden storage area from rear of units. Remove portion of existing concrete slab, 9.5 x 19.5 feet. Install new 8 x 7 foot sliding glass door to patio. Construct new 3 foot wide walk from patio to garbage can area.
- 2. Garbage can enclosure and exterior bulk storage: Construct new covered storage area, 5 x 6.5 feet, and garbage can screen 5 x 3 feet, at patio. Construction to be of wood frame with exterior siding compatible with building. Provide new 2'-6 x 6'-8 flush wood door and plywood storage shelving. Provide galvanized steel garbage can holder for two cans.
- Contemporize exterior: Remove existing siding.
 Replace with new stucco, stained vertical wood siding or brick veneer.

Install new 3 x 7 foot solid core flush wood entrance door and aluminum/glass/screen door.

Replace existing metal casement windows with new aluminum horizontal sliding sash. Construct new contemporary bay window of wood sash at new dining room.

4. Roof: Same as Basic 3BR

b. Interior


- 1. Same as Type OD-1A & 1B
- Existing bathrooms: Renovate existing bathrooms. (Same as Basic 3BR)
- 3. Existing Kitchen: Remove existing kitchen equipment. Install new work counters, cabinets and appliances in parallel arrangement, 8.67 x 9.5 feet. Install new sheet vinyl flooring.
- 4. New Utility Room: Construct new utility area adjacent to hall to include washer/dryer connections and furnace/water heater. Install 5/8 in. UL rated gypsum wallboard on walls and ceiling. Install metal sliding doors and new sheet vinyl flooring.
- 5. Floors: Same as OD-1A & 1B
- 6. Doors and Hardware: Same as OD-1A & 1B

c. Mechanical

- 1. Same as OD-1A & 1B
- 2. Same as OD-1A & 1B


d. Electrical

- 1. Service: Same as Basic 3BR
- 2. Outlets and fixtures: Replace existing light fixtures throughout.
 - a. Add 2 new outlets in kitchen.
 - b. Add 2 new outlets in dining room.
 - c. Add 3 new outlets in utility room.
 - d. Add 2 new outlets each in BR-3&4.





TANK O MANAGON LAURID

UNIT TOP	OC	1-25 TYPE NOO-4	A TERRACE I			
Consultant Net Asi		Design Criteria 1250 SF (MAX)	Existing Area	Proposed Area 1242 SF		
Living Room				204 SF		
Dining Roo	m			835F		
Kitchen				825F		
Wall	Cab.	24 SF		25 SF		
Base	Cab.	32SF		33 SF		
Count	er	12 SF		225F		
Drawers		14 SF		22 SF		
Utility Room	n		NONE	33 SF		
Bedrooms	1	140 SF GLF GLO		1425F 84FCLO		
	2	115 SF 4 LF CLO		116 SF 8 LF CLO		
	3	100 SF 3LF CLO		105 SF 55 LF CLO		
	4	90 SF 31F CLO		105 SF 5.5 LF CLO		
Bath		2.0	2.0	2.0		
Linen		245	- Indiana is	4.5LF		
Bulk Storage		GO-100 SF COMB. INTERIOR & EXTERIOR	175F EXTERIOR 225F INTERIOR 395F TOTAL	22 Interior 30 exterior		




16. Type OD-3 (Semi-detached); Type NCO-2BR-2







FLOOR PLAN




FRONT ELEVATION


EM·2BR·1







EM·2BR·1






FLOOR PLAN







FLOOR PLAN




FRONT ELEVATION


EM·3BR·1







EM·3BR·1







FLOOR PLAN






NCO · 4BR·1






NCO · 4BR · 1




NCO·5BR·1



COST	E	ST	11.	AT	1	NG	FORM	
MAYCOC	15	24	17	165	١	. 5-	631	

MILY HOUSING DAMPLEJEUNE NC TARAWA TERRACE I

TEM (OR FEATURE) DESCRIPTION	QUANTITI	ES	MATERIA	MATERIAL COSTS		COSTS	ENGINEERING ESTIMAT		
(Abbreviate if necessary)	NO. OF UNITS	UNIT	COST	COST	UNIT	COST	UNIT	cost	
1	,	3		5	6	7	8	•	
A. STORAGE; CAN ENCLOSURE B. NEW EXTERIOR	4	X72	EKIUK	IMPI	KOVEN	NEV T	5	1114.	
1. Remove & Replace Cxisting siding 2. Windows 3. Entrance door 4. Storm door 5. Patio door	304	Fagaga					1.20	35. 200. 120. 250. 250.	
SUB-TOTAL ITEM ROOFING I Kemove & Replace Coxisting unit								1005	
SUB-TOTAL ITE	MC	SF					/,-	1089	
NEW LIVING ARE 1. Demolition 2. Finished area SUB-TOTAL IT	ALS 97	SF					500. 18:	500:	



COST ESTIMATING FORM

0105 01: 3800

APEN OF NO

SHEET 2 OF 3

IDENTIFICATION NUMBER


PODERT 'Or line item) TITLE

LOCATION

CATEGORY CODE NUMBER

EM-28R-1

ITEM (OR FEATURE) DESCRIPTION	QUANTITIES MATERIAL COSTS		IAL COSTS	LABO	COSTS	ENGINEERING ESTIMAT		
(Abbreviate if necessary)	NO. OF UNITS	UNIT	COST	COST	UNIT	COST	UNIT COST -	COST
1	2	3		5	6	7	8	9
KITCHEN	//	VIE	RIOR	MPRO	PVEME	W/S	8	
2. Flooring 3. Counter & cab.	2505	SF					10:-	36 900
SUB-TOTAL ITE	ME						100	961.
EXISTING BATH RENOVATIONS								403
OTHER INTERIOR RENOVATIONS								
1. Partitions 2 DOOKS & hardwr 3. Flooring 4 Painting	50	488					10:-	500 990 300
SUB-TOTAL IT MECHANICAL	EM	0						2480
1. New furnace a duct modification SUB-TOTAL ITE	t s Ls						850	850



COST ESTIMATING FORM

C105 01: 3800

SHEET 3 OF 3

AREA OR NO

ACTIVITY


LOCATION

CATEGORY CODE NUMBER

PROLECT (Or line item) TITLE

EM-28R-1

TEM (OR FEATURE) DESCRIPTION	QUANTI	TIES	MATERIAL COSTS		LABO	OR COSTS	ENGINEERING ESTIMAT		
(Abbreviate if necessary)	NO. OF UNITS	UNIT	COST	COST	UNIT	COST	UNIT	COST	
1	2	3			6	7	8	The second	
I.PLUMBING	417								
1. New bath fixt. 2. Mater neater 3. Hookup	3,	99.					150.	450.	
- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	15						150.	150.	
SUB-TOTAL IT	EM	7						800.	
ELECTRICAL									
1.150 A Panel 2. Fixtures 3. outlets	15	a					250	250	
	9	ca.					25.	225	
SUB-TOTAL IT		5						900.	
SUB-TOTAL T	YPE	4	M-2	BR-1		•		1184	
10% CONTINE		1						1185	
TOTAL PER C	INI		can					13,03	
× 4200			,44	DX			5,	4737	
EPARED BY (Name)	PPROVED BY			TITL	E OR ORGANIZAT	TION	DATE		



COST	E	STI	ATIN	iG	FORM
MAYDOCI	(\$	2417	(REV.	5-	63)


0105 01: 3300

SHEET OF 4

IDENTIFICATION NUMBER

CATEGORY CODE NUMBER

MILY HOUSING CAMPLEJEONE, NO SIC 3BR; TYPE EM-3BR-1 ENGINEERING ESTIMATE LABOR COSTS ITEM (OR FEATURE) DESCRIPTION (Abbreviate if necessary) NO. OF UNIT COST COST COST EXTERIOR IMPROVE A. STORAGE, CAN ENCLOSURE SUBTOTAL ITEM B. NEW EXTERIOR 1. Remove & Repl existing siding 2. Windows 3. Patio door SUB-TOTAL ITEM C. ROOFING 1. Remove & Replay @existing unit SUB-TOTAL ITEM D. NEW LIVING AREA SUB-TOTAL ITE PPEPARED BY (Name) TITLE OR ORGANIZATION



COST ESTIMATING FORM NAVOOCKS 2417 (REV. 5-63)

SHEET 2 OF 4

0:05 01 380	0
-------------	---

REA OF NO ACTIVITY


LOCATION

CATEGORY CODE NUMBER

PROJECT /Or line item) TITLE

EM-38R-1

TEM (CR FEATURE) DESCRIPTION	QUANTIT	IES	MATERI	AL COSTS	LABOR	COSTS	ENGINEER	RING ESTIMAT
(Abbreviate if necessary)	NO. OF UNITS	UNIT	COST	COST	UNIT	COST	UNIT COST .	COST
	2	3	4	5	6	7	8	9
E. KITCHEN/OTILITY	//	ME	RIOR	MPRC	VEME	NTS		
1. Demolition 2. Flooring 3. Counts & counter	158550	SF 3a.					300	300. 33. 900.
5. Partitions SUB-TOTAL ITE	ME	F					70.	420. 1833.
BATH/UTILITY AREA 1. PARTITIONS 2. DOORS & HARdWR 3. Flooring 4. Wall covering	500	上面生产					0.00.30	1080504
SUB-TOTAL ITE EXISTING BATH RENOVATIONS	MF							318.
1. Ceramic tile 2 Flooring 3. Wall covering 4 Doors & harowr SUB-TOTAL ITE	5000 AN	SF ST CO					3 1:- 30 90	150.



COST ESTIMATING FORM HAVDOCKS 2417 (REV. 5-63)

0105 01 3800

SHEET 3 0

IDENTIFICATION NUMBER

LPEA OR NO ACTIVITY


LOCATION

CATEGORY CODE NUMBER

PROJECT (Or line item) TITLE

EM-38R-1

TEM (OR FEATURE) DESCRIPTION OUANTITIES MATERIAL COSTS LABOR COSTS ENGINE NO. OF UNIT COST COST COST COST COST 1 2 3 4 5 6 7 8 H, INTERIOR RENOVATIONS 1 PAINTLY ONS 2 ODORS & HARdWR 6 89 3 Flooring 4 Painting 308-TOTAL ITEM H MATERIAL COSTS LABOR COSTS ENGINE AMERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS ANTERIAL COSTS ANTERIAL COSTS ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS ANTERIAL COSTS ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS LABOR COSTS ENGINE ANTERIAL COSTS A	COST 9
H. INTERIOR RENOVATIONS 1. Partitions 2. DOORS & Hardwr 6. 29 3. Flooring 4. Painting 3. WB-TOTAL ITEM H	
1. Pantitions 2. DOORS & Hardwe 6 89 3. Flooring 864 SF 4. Painting 2.3 3. WB-TOTAL ITEM AT	
·	500. 540. 400.
. MECHANICAL	2304
I New furnace & duct midifications LS 900	900
SUB-TOTAL ITEM I PLUMBING I NEW bath fixt. 2 eg 2 Exist bath 3 eg 150.	900. 100. 450.
3. Water nearer 1 Ga 150 150 150 150	150.



COST ESTIMATING FORM NAVDOCKS 2417 (REV. 5-63)

0105 01 3900

SHEET OF

1911 39 NO

ACTIVITY


LOCATION

CATEGORY CODE NUMBER

FFO.EST for line stem) TITLE

EM-388-1

TEM (OR FEATURE) DESCRIPTION	~QUANTIT	TIES	MATERI	AL COSTS	LABO	R COSTS	ENGINEER	RING ESTIMATE
(Abbreviate if necessary)	NO. OF UNITS	UNIT	COST	COST	UNIT	. cost	UNIT COST -	COST
X. ELECTRICAL	2	3			6	7	8	9
1 150 A panel	45						250.	250
2 Fixture allowant 3. adal, relocate	e 4s						150.	150
authers	13	eq.					25.	325.
CUR TATAL H				,				
SUB-TOTAL ITE								725.
SUB-TOTAL T	IPE	EN	1.38	R-1				14,720
10% CONTING	SENC	V						1473
								11 100
TOTAL PER	UNIT							10,199
× 180	UNITE	1	(18	0x 16	199.)	0	915 90
							1	113,02




COST ESTIMATING FORM OF 3 SHEET MAYDOCAS 2417 (924. 5-63) 0105 01: 3800 CATEGORY CODE NUMBER HOUSING CAMPLEVEUNE NC PROJECT for line item! TITLE TARAWA TERRACE I MATERIAL COSTS LABOR COSTS ENGINEERING ESTIMATE ITEM (OR FEATURE) DESCRIPTION (Abbreviate if necessary) UNIT UNIT COST COST COST B. NEW EXTERIOR SUB-TOTAL ITEM C. ROOFING D. NEW LIVING A 1. finished arec F. NEW, BAT 1. Partitions 2. Ceramic tile

PREPARED BY (Name)

APPROVED BY

TITLE OR ORGANIZATION

STAC



COST ESTIMATING FORM MAYDOCKS 4417 (REV. 5-63)

0105 01 3300

APER DR NO

SHEET 2 OF 3


ACTIVITY LOCATION CAT

PROJECT (Or line item) TITLE

CATEGORY CODE NUMBER

NCO-5BR-1

TEM (OR FEATURE) DESCRIPTION	QUANTI	TIES	MATERI	AL COSTS	LABO	R COSTS	ENGINEER	ING ESTIMAT
(Abbreviate if necessary)	NO. OF UNITS	UNIT	UNIT	COST	UNIT	COST	UNIT COST -	COST
1511 00	2	3	4	5	6	7	8	9
3. Flooring 4. Wall overing 5. DOOR & hardy SVB-TOTAL	25 160 ITEN	Strea F					1	25. 48. 90. 553.
EXIST. BATH RENOVATIONS	1	ea						403
RENOVATIONS 1: DEMOLITIONS 2: PARTITIONS 3. DOORS & MARAIN 4: FLOORING 5: PAINTING SUB-TOTAL	R LS III A 1262 ITEN	#g:st					500.	500 1110 1260 1260 450 4582
MECHANICAL 1. New furnace auct modificant	t was L	\$					1500.	150C
PLUMBING 1. NEW bath fixt. 2. EXIST, bath fixt.	33	09	Pages A				<i>350. 150.</i>	1050 450



COST ESTIMATING FORM NAVDOCKS 2417 (REV. 5-63)

0105 01: 3800

SHEET 3

IDENTIFICATION NUMBER

AREA OR NO

ACTIVITY


LOCATION

CATEGORY CODE NUMBER

PPOJECT (Or line item) TITLE

NCO-5BR-1

TEM (OR FEATURE) DESCRIPTION	QUANTIT	TIES	MATERI	AL COSTS	LABOR	COSTS	ENGINEERI	NG ESTIMATI
(Abbreviate if necessary)	NO. OF UNITS	UNIT	COST	COST	UNIT	COST	UNIT COST -	COST
	2	3	4.50	5	6	7	8	,
F PLUMBING								
3. Water heaten 4. Hookup	1	9					250.	250
	45		_				150	150.
SUB-TOTAL	ITEN	J						1900.
ELECTRICAL							-	
1.200 A Panel 2. Fixtures	15	29					300	300.
3 outlets	17	80					25.	425
SUB TOTAL A	TEM	K					2.	
			100	EDDI				925.
SUB-TOTAL	, ,		w	DDN-1				7,455
10% CONTIN	GEN	CY						1745
TOTAL PER	ONI	T						1920
X 13 0			1		12)			10/1
W 15 01	1113			^	12)		2	49,60
All the state of t			Transfer of the second					
ARED BY (Name)	APPROVED BY			TITL	E OR ORGANIZATI	ON	DATE	



COST	E	ST	11.	A	T	1	N	G	F	DRM	
MYADOCK											

SHEET

OF 3


=		=	-	_	-	_	•		_	_	_
	-	-			-	-	-	_	_	_	_

CATEGORY CODE NUMBER

PROJECT (Or line : tem) TITLE

FAMILY HOUSING CAMPLEJEUNE NC TARAWA TERRACE I

TEM (OR FEATURE) DESCRIPTION	QUANTIT	IES	MATERI	AL COSTS	LABOR	COSTS	ENGINEER	ING ESTIMAT
(Abbreviate if necessary)	NO. OF UNITS	UNIT	UNIT	COST	UNIT	cost	UNIT COST -	COST
1		3	1	5	6	7	8	9
PATIO, WALKS STORAGE, CAN ENCLOSURE	EXT	EX	PIOR	IMPR	DVEM	ENTS	5	
1. DEMOTITION 2. Walls 3. DOOK & hardWR 4. Walk	275	SF SF SF					400.	400. 550. 23.
SUB-TOTAL IT	EM A	f						1063.
3. NEW EXTERIOR 1. Siding 2. Entrance dr. 3. Stormdoor	1550	SF					1.20	1860
4. Patio door 5. Windows 6. Bay window	19/	2000					250 50 550	250. 450. 550.
SUB-TOTAL I		3						3300.
C. ROOFING I. New Roof SUB-TOTAL A	2038 TEM	SF					1	2038 .
O. NEW LIVING AR I finished area	EA19	SE					18	342.



COST ESTIMATING FORM NAVPOCKS 2417 (REV. 5-63)

0105 013 3800

SHEET 2 OF 3

APER OF NE ACTIVITY


LOCATION

CATEGORY CODE NUMBER

PEDLECT (Or time ttem) TITLE

NCO-4BR-1

TEM (OR FEATURE) DESCRIPTION	QUANTIT	IES	MATERI	AL COSTS	LABOR	COSTS	ENGINEER	ING ESTIMAT
(Abbreviate if necessary)	NO. OF UNITS	UNIT	UNIT	COST	UNIT	cost	UNIT COST -	COST
1	2	3	4	5	6	7	8	9
E. KITCHEN	IN	EX	RIOR	IMPR	OVEN	ENT		
1. Partillons 2. Plooring 3. Cab & Counter	46	5					10 em	200.
SUB-TOTAL 1	TEM I						800,	1046.
RENOVATIONS	2	39					403.	806
OTHER INTERIOR RENOVATIONS	?							-10
1. DEMOLITION 2 Partitions 3 DOORS & hardy	25	45					500.	500. 1260
4 Flooring 5. Painting	1085	SF					400.	1085.
MECHANICAL	ITEN	1 6						4115.
I New furnace aduct modifica SUB TOTAL	tions						1500.	1500
PLUMBING	ITEN	1 /						1500.
PLUMBING 1.Bath fixtures	6	90					150.	900.



COST ESTIMATING FORM MAYDOCKS 2417 (REV. 5-63)

0105 01: 3800

SHEET 3 OF 3

IDENTIFICATION NUMBER

ACTIVITY

CATEGORY CODE NUMBER

PROJECT (Or line item) TITLE

NCO-4BR-1

QUANTIT	IES	MATER	IAL COSTS	LABO	R COSTS	ENGINEER	ING ESTIMAT
NO. OF UNITS	UNIT	UNIT	COST	UNIT	COST	UNIT	COST
2	3	4	5	6	7 .	8	9
15	ca I					250.	250. 150. 1300
TYPE 16EN	EA	-	-48R-1			250.	250 150 275. 675. 16279 1628
		(17	,907. x	11)			17,90
	AND CONTRACTOR CONTRAC						
	IND. OF UNITS 2 LS TEM TEM TYPE 16EN	LATEM I LEM I LEM J TEM J TYPE N 16ENCY R UNIT	NO. OF UNIT UNIT COST 2 3 4 I CA LS TEM I I CA LS TEM I ITEM J TYPE NCO IGENCY R ONIT	NO. OF UNIT UNIT COST 2 3 4 5 I CA LS TEM I LS TEM J TYPE NOO-48R-1 16ENCY R UNIT	NO. OF UNIT COST COST 2 3 4 5 6 LS CA LS	NO. OF UNIT COST COST COST 2 3 4 5 6 7 LS CA LS	NO. OF UNIT COST COST COST COST COST COST COST COS

