BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
M-518	18,000 sf	1300 sf 41 windows			MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
CONTRACT	C 9/25/63 signed		Waterproofed
AB9-23-31848	7/27/70	1880	Paint int
3249	10-27-72	941	Repair + paint int
3193	10-13-72	3085	Repair + paint ext
4795	8-26-75	9/E	Replace fire Hydrant near M-518
4994	4-2-76	9/E	Repair water line under Bldg M-518
4454	1-10-75	517	Replace + paint stud masonite
3391	8-21-75	1185	Self-help, tile decks
4795	8-16-77	—	Replace fire hydrant
3405	12-18-81	7874	Int spkr paint ext complete 2 coats
5182	4-30-82	5727	Rpl. steam coils in A/H units
3371	1-7-83	1246	Repair interior + exterior and Premie new wood
1512	10-8-83	1512	Install Window Shades in M-518
1050	11-8-83	2053	Install "V" Blinds
3342	3-1-83	624	Replace light fixtures
3164	10-31-83	3395	Remove floor & Condensate
4432	Compl	941	R/L Thermometer + Thermo sockets 7-26-84

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION