BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
BB-71					MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
Contract	6/13/66		Install Ventilating System
345	1-25-74	1089	Repair to Butler Bldg ext
3158	2-1-74	1984	Repair & paint int
4307	3-2-73	319	Replace air compressor
1071	2-12-71	3331	Install (3) oil fired furnaces
3609	4-28-78	2077	Hook up (2) Dsl generator alter
3609	4-28-78	2071	Repair to motor exhaust system
Contract 79-76320	1979	1222	Ext paint
3220	12-7-79	488	Replc 3 roof jacks
4202	9-9-80	196	Rprs. to bldg
3464	6-27-80	476	Rpr (4) roof jacks
2125	7-11-80	1047	Treat bldg for termites
2192	9-16-83	836	Clean up oil spill
0142	4-14-91	1845	MODIFY VEH EXHAUST SYSTEM

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION