BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
SA-29					

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
72-4427	4-4-72	624	Repair water lines & Replace float switch to wash rack
3229	8-15-69	600	Repair 2" water main serving wash rack
3423	8-16-74	128	Repair & paint ext
4155	10-31-79	3327	Repl existing circulating pump & piping
4210	6-27-80	272	Est & prs before contract painting
4155	4 Apr 80	95	Repl existing circulating pump & piping on L.U.T. wash rack

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION

BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
S-551					

JOB ORDER NO	DATE ~~COMPLETED~~ signed	COST	DESCRIPTION
4000	9-18-81	841	Install ~~add parts~~ add. parts to A/C system
4560	9-2-83	2632	Rpl A/C
3575	12-5-84	2566	Repl Existing water line
3005	Comp	~~Comp~~ 385	Install retainer wall 6" high 15' long.

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION