BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
AS 2003					

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
5638	8/2/76	/	Make necessary repairs & test electric motor
5465	6/25/76	263	Remove / Rpl elect starter
4867	2/9/76	4009	Rpl fire pump controller
4605	8-5-77	274	Repairs for operation of fire pumps
3148	8-21-81	741	Rpr water leak under floor
7459	Comp	189	Lime & fertilize around qtrs
2163	9-19-80	236	Rpl contaminated soil with fresh dirt
6629	Comp	96	Amend. to Jon 6629
5147	2-10-84	490	Replace 3 Bioze hose thread
3104	9 JUN 90	9086	Rem/Repl 50 H.P Fire Pump Controller

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION