to: Ken Jolly 6 April 84

VIA: Director

Dapad 84

## MEMORANDUM - OF CALL



Previous editions usable

TO:

YOU WERE CALLED BY-	YOU WERE VISITED BY-
OF (Organization)	
PLEASE PHONE	FTS AUTOVON
WILL CALL AGAIN	IS WAITING TO SEE YOU
RETURNED YOUR CALL	WISHES AN APPOINTMENT

RECEIVED BY DATE TIME
63-110 NSN 7540-00-634-4018 STANDARD FORM 63 (Rev. 8-81)

♥U.S. G.P.O. 1983-381-529 233


STANDARD FORM 63 (Rev. 8-81) Prescribed by GSA FPMR (41 CFR) 101—11.6

Good- File under "success"

Memo For The Record
From: Environmental Protection Specialist
Subj: Illegal Dumping activities at Camp Leign, MCB
Rof: (a) Onsite inspection of site on 22 June 1983 by
K. Jelly
(b) Onsite inspection of dump site on 3 April 1984
by K. Jelly

1. During resperence (a) it was determined that an approximately 200'x 200' grassed area was being utilized for disposal of debris and rubbish. During reference (b) it was determined that the area has been cleaned completely.

Ken Jolly A/6/84



## NATURAL RESOURCES AND ENVIRONMENTAL AFFAIRS DIVISION MARINE CORPS BASE CAMP LEJEUNE, NORTH CAROLINA 28542

5-25-83 Date

From: Director To: Dan

Subj: Damping-Camp Gligers

Mr Martin Bore Fire Dept ph 5037 advised this PM that he had observed a dump site just past NBC school C.G. - Dirt road to

right before Rail Road Crossing.

Boper, chemicals tronk ite. Jahan

Ken Take a look

at This at your convenience, take a Documenton shoto-

Follow up in comple of weeks - dfit to C.O.


Follow up in chaped up lets write the to C.O. Julian Ken- Your dein

## WORK REQUEST (MAINTENANCE MANAGEMENT) NAVFAC 9-11014/20 REV. 2-68) S/N 0105-LF-002-7510 Supersedes NAVDOCKS 2351

(PW Department see Instructions in NAVFAC MO-321)

Requestor see Instructions on Reverse Side

PART I—REQUEST (Filled out by Requestor)	
DCA CAMP GIEGER	2. REQUEST NO. 4081-83B
PLANNER and ESTIMATE branch, BASE MAINT. bldg (attn M. STRAIN)	4. DATE OF REQUEST 22AUG83
REQUEST FOR COST ESTIMATE PERFORMANCE OF WORK	SO. REQUEST WORK START ASAP
FOR FURTHER INFORMATION CALL	7. SKETCH/PLAN ATTACHED
SSCT HELTSLEY (ext 0153) DESCRIPTION OF WORK AND JUSTIFICATION (Including location, type, size, quantity, etc.)	YES X NO
BLDG: TC-341 LOCATION: Adjacent to the Gas Chamber DISCRIPTION: Clear present disposal site. JUSTIFICATION: Environmental Protection Agency has declared it an illegal and environmentally hashful.  DCA APPROVED	7
PART II—COST ESTIMATE  (Filled out by Maintenance Control Division if estimate requested)	
	12. ESTIMATE NO.
13. COST ESTIMATE 14. SKETCH/PLAN ATTACHED	
Tyes No	
To Long the	encer, and the original and one copy many
Experience of the policy of the property of the property of the property of the policy	the resident for do so are all but he alread
Overhead APPROVED. BASED ON PRESENT WORKLOAD, T	have proper block in nom?, Luctocours rate,
Equipment LE 12 MOV DE DECORD MODE 12 21V LED WIND  AUTHORIZED BY 25TH OF	AND FUND
Contingency we have been a compared to the sound of designments of the sound of the	D. BEFORE WORK IS STARTED AND
Section from the section of LOLY . Section of the s	17. DATE
denotes the control of the section o	
app and for white meaning the Public Month dispetitions.	the resume for despectat will be stated
The state of the s	regardamenta. Granda successo de figi que ascientablema, con table duminismassis o es
ADMONDATION TO TROCKE IN THE TOTAL T	
5. EZ 1997 - THAYCOMPT 140 (199 M.C.) OTHER FELLED CANCELED	HAS BEEN WILL BE PERFORMED



Memorandum For The Record From: Environmental Protection Specialist

Subject: Allegal Dumping activities at Camp Geiger, MCB

Ref: (a) Onsite inspection of affected area on 22 June 1983 by K. Jolly as requested by Danny Sharpe, Supervisory Ecologist

Encl: (1) Site map of Dump Site

1. The subject site was reported on 25 May 1983 to Director, NREAD, by Mr. Martin, Base Fire


Department.

2. During the reference, it was determined that an approximately 200-jost long, 200-jost wide grassed area has been utilized for the disposal of building demolition debris and assorted rubbish. appearance indicates that the discarded materials were generated during demolition and for renovation of a MCB building in the general vicinity. 3. approximately 90 percent of the deposited material

Consists of wooden debris, including lumber, utility Bales, crates, windows, doors, and pallets. Other debris includes bagged leaves, Chairs, mattresses, metal bathroom stalls, and assorted empty fluid Containers. The following discarded Chemicals were identified:

(1). I gallon of Everseal walking compound (2). approximately 2 gallons of lube oil-ACFT Piston Engine

(3). approximately 0.5 gallon of 2- Propanal



4. On 23 June 1983 at 0845 & Contacted Soxt.

Thompson, Camp Beiger Executive Office, Concerning

the dumping activity. Soxt. Thompson Referred me

to State Soxt. Helpsley, Camp Beiger Property, who

was divare of the dump but Claimed that the

facility (dump) was authorized. I informed him

that the illegal dump was a Violation of State

Statutes and that the material must be Removed

to the MCB Sanitary Landfill. Thempson stated

that he did not have manpower or facilities

to remove the material in a timely fashion,

and asked who to Confact. I suggested that

he follow his normal procedural Route to

request assistance from Base Maintenance, but


I clearly stated that I was not obligating

Base Maintenance in any way. Soxt. Thompson


is to Contact this office when the Cleanup is

completed.

Ken Jelly 6/23/83



NBC SCHOOL JEWAGE TREATMENT PLANT DIRT NOT TO SCALE



Memorandum For Record From: Environmental Protection Specialist Subject: Allegal Dumping activities at Camp Geign, MCB

Reference: (a) On-site inspections of affected area on 25 July 1983 They K. Jolly, MREAD

(b) Forecon between K. Jolly and It. Goehring, DCA, on 27 July 1983

1. During reference (a), it was determined that no refuse had been removed from the dump site as NREAD recommended. During reference (b), It. Goehring was briefed on the Situation and advised that all materials should be removed to the Base Sanitary Landfill as soon as possible. It. Doehring was also notified that the materials could not be burned. It. Goehring stated that he had a manpower problem told him to contact his Chain of command to request help. Doehring to call NREAD and report status.

Ken Jolly 7/27/83 STATE OF THE STATE ESTATE OF THE STATE OF THE STAT Alexander Tilberrage Beer Commenter

From: Director

To: Base Maintenance Officer

Subj: Unauthorized Dump at Camp Geiger

Ref: (a) Work Request No. 4081-83B of 22 Aug 1983

(b) Dir NREAD ltr NREAD/dds/th of 7 Oct 1983 (c) Inspection of Unauthorized Camp Geiger Dumpsite on

21 Feb 1984 by Mr. K. JOLLY, NREAD

1. The subject dumpsite has been operating in violation of State regulations and is considered an environmental hazard due to the apparent lack of control over disposal activities. References (a) and (b) requested that the subject dumpsite be cleared as soon as possible.

- 2. During reference (c) it was determined that no solid waste had been removed from the subject dumpsite.
- 3. Please advise as to the status of the requested removal of debris from the subject site. Point of contact in this matter is Mr. Ken JOLLY, NREAD, telephone 5003/2083.

J. I. WOOTEN

the experience beauty being a manager of the manager of the section of the sectio 

Care Control of the C

A STATE OF THE STA