

BLDG NO
HOUSING

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD
MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
6509	6-26-87	1368	Insulate pipes in Attics
6525	Comp.	1800	Repr. damage to House
6500-(82)	12-11-87	12958	Repr. fire damage.
6500-(88)	1-27-89	45,841	Repr. fire damage.
6500-(89)	10-27-89	12,958 1344	Repr. fire damage.
6502	2-24-89	9197	Seal door vents
6501	2-3-89	8107	Repr. fire damage. Repl dishwashers in Watkins Village
6501	12-8-89	282	Repr. fire damage
6504	1-27-89	9423	Install fireplace glass doors & screens.
6505	3-3-89	4193	Install underground Storm Drain
6507	4-17-89	16779	Patch additional plaster wall, water damage.
6513	12-22-89	636	Repr. fire damage.
6514	1-5-90	1081	Repr. fire damage.
6506	11-1-91	317431	Perform Air infiltration Test & Repr. air leaks in Family Housing.
6503	—	48430	Inspect for proper installation, set thermostats
6502	—	339	Repr. fire damage.
6510	11-18-91	1275	Repr. fire damage to house.
6516	3-16-90	771	Secure fire damage quarters
6517	3-16-90	931	" " " "
6518	3-16-90	183	" " " "
6519	5/18/90	2682	Repr to damaged (Fire) Atrs.
6520	8-10-90	26022	Make reprs to fire damaged house. 1st Amdmt 5/18/90
6521	8-10-90	23650	" " " " " " 1st Amdmt 1/19/90
6522	5-25-90	24,824	Repr. fire. damaged
6523	5/18/90	10136	Repr. fire damaged
6525	Comp	11046	" " "

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
6526	CP	12019	Spray round-up to control vegetation
6527	8-10-90	12674	Repr Termites damaged houses
6524	2 JUN 90	6069	Reprs to fire damaged house.
3017	CP	3650	Repr Bldg.
6503	11-23-90	1851	Repr damages to interior & exterior of house.
6504	11-16-90	1671	Repr damages to brick fire wall
6505	CP	3781	Remove 250 mailboxes & post
6509	FEB 14, 91	452	RPR FIRE DAMAGES TO QTRS, RPR CABINETS/RPLC EXH HOOD
1089	12-28-90	75	INSTALL SMOKE DETECTOR.
1091	12-28-90	110	INSTALL 3 SMOKE DETECTORS
0101	1-11-91	287	INSTALL 10" CEILING FAN + 120V CIRCUIT.
1093	2-22-91	801	EXCHANGE ADULT TOILET FOR BABY TOILET
6510	1-APR 91	2000	RPR HOUSE THAT WAS DAMAGE BY FIRE.
6516	9-9-91	652	RPR 6" LATERAL TERRA COTTA SANITARY LINE
6514	11-1-91	1669	Rpl 6" LATERAL SANITARY SEWER
1140	6-12-91	472	INSTALL LIGHT SWITCH
6517	7-22-91	996	REMOVE INSULATION
8080	11-1-91	1406	INST ELECT CIRCUITS + LIGHTING SYSTEM
6500	10-18-91	1007	RPLC DAMAGE MAOMITE SIDING
6518	9-23-91	1704	RPR DAMAGE TO QTRS WHERE TREE FELL
6504	31 Jan 92	628	RPR FIRE DAMAGE TO HOUSE.
0101	5-9-92	317	TAP EXISTING COLD WATER LINE UNDER TR 245T BIN 15
6505	CP	89 018	PERFORM AIR INFILTRATION TESTING ORP Family Home ¹⁹⁹⁸
6507	7-31-91	4772	RPL HOUSE NUMBERS ON 700 HOUSES IN TT2 AREA
6509	8-11-92	3483	REPAIR FLOORS - QTRS 3106
4329	10-16-92	4888	RELOCATE HYDRANTS
6508	3-12-93	4252	DEMOLISH QTRS QUARTERS
6510	CP	4544	Rpr fire damage

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
6511	8/13/93	2811	RPR FIRE DAMAGE d QRTS LCH 1402
6512	7/23/93	5165	RPLC Siding
8414		4960	INSTALL WATER HEATER REOPENED 9 FEB 94
6516	10/22/93	1507	RPR BROKEN SEWER LATERAL
6510	7/2/93	868	1ST AMEND
6505	010695	78,919	1ST AMD Purged SEP 28 1998
6513	9-17-99	3095	RPR PORCH ON TT-450 CX per EWW
6501	3-25-94	23941	RPR FIRE DAMAGES
6504	4-2-99	3088	MAKE RPRS TO HARDWOOD FLOORS
8414	4-1-94	6218	INST STM OPERATED HOT WTR IN BLDG. Purged SEP 28 1998
2128	5-10-96	513	REPLACE WATT HOUR METER Also fixed
6501	3-25-94	158	RPLC BURNED T'STAT AND CABLE/ BURNED @ TRN
6501	3-25-94	8511	2 nd AMD
6506	4-15-94	3964	RPR FIRE DAMAGE
6504	5-6-94	8790	1ST AMEND
6507	2-23-96	1341	REPAIR FLOOR Purged SEP 28 1998 dtd
6512	1-27-95	8901	Rpr Fire Damage Purged 9/28/98
6513	7-28-95	1628	Rpr Fire Damage " SEP 28 1998
6514	031795	5699	Paint Interior " SEP 28 1998
6515	031795	5699	" " " SEP 28 1998
6516	030395	5699	" " " SEP 28 1998
6517	3-10-95	5654	" " PP2202 " SEP 28 1998
6518	5-2-95	987	Rpr fire damage LCH 450 " SEP 28 1998
6519	7-14-95	1837	Rpr house walls " SEP 28 1998
6520	10-20-95	11267	RPR FIRE DAMAGE SEP 28 1998
6521	9-8-95	4300	RPR EXTERIOR Purged dtd SEP 28 1998

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
6523	9-29-95	8406	RPP TERMITE DAMAGE - TT 2393 Purged at SEP 28 1998
6521	9-8-95	546	1st Amend Purged at SEP 28 1998
6525	9-29-95	922	Amend #1 Purged at SEP 28 1998
6523	9-29-95	5556	2nd Amend ment Purged at SEP 28 1998
6520	10/20/95	580	1st Amend ment Purged at SEP 28 1998
6520	10/20/95	4939	2nd Amend ment " SEP 28 1998
6535	5-31-96	2517	Remove FOUNDATION SLAB purged 8/24/00 g
6536	5-13-96	13498	REPAIR FIRE DAMAGE TT 3149 purged 8/24/00 g
6534	1-12-96	8593	REPLACE DISHWASHER
6537	11-15-96	14955	RPP WATER METERS 9-11-02 purged ll
6536	5-13-96	894	1ST AMND
6536	5-13-96	8857	2ND AMND
- 4023	1-15-99	1190	RPP CULVERTS/EROSION LCH 10% as per Mr. Harper per email
- 6541	1-15-99	596	RPLC STOPS/CK as per Mr. Harper per email
6542	7-24-98	6770	INSTALL FILTERS } 9-11-02 purged ll
6542	7-24-98	0	1ST AMND
6504		3643	Install water filters in ltr BB17, RR42
- 6505	1-15-99	14293	Install water filters in ltr BB18 - BB24, RR37, RR43 As per Mr. Harper CK per email
6500	5/21/99	16574	Rpp - Beamed House TT2517
3125		2836	Provide Mtl's for Self Help Proj. Troop Tr. Jon # Chgd to 6501
6501	6/25/99	2836	Provide mtl's for Self Help Proj Troop Trng.
3151	7/25/00	2,082.	Re-instl door holder chains + Binder Keys m loy Masjid
→ 6500	5/21/99	3,864.	1st Amendment
CLM1		13,540.	02-156210 (walls/ceilings) CAMBAR