

| JOB ORDER NO | DATE COMPLETED | COST    | DESCRIPTION  |
|--------------|----------------|---------|--|
| 7609         |                | 0/E     | Repair leak in sewer line                            |
| 1016         |                | 279     | Install service                                      |
| 6660         | 8-7-73         | 1336    | Pump out oil tanks at PP hog                         |
| 6658         | 7-20-73        | 162,116 | Repair & paint                                       |
| 9005         | 6-29-73        | 2677    | Yearly maint to Household                            |
| 7946         |                | 132     | Install mail slots                                   |
| 7595         | 5-25-73        | 3598    | Clean up public area PP, BB, BR & Naps               |
| 7562         | 3-23-73        | 325     | Replace (2) lighting panels                          |
| 7427         | 2-23-73        | 283     | Clean roof gutters & downspouts                      |
| 6573         | 11-24-72       | 0/E     | Repair/replace fire box refractory                   |
| 6084         | 3-16-73        | 0/E     | Snow clean up in Paradise Point, BB, RR              |
| 7733         | 4-28-72        | 138     | Clean roof gutters & down spouts                     |
| 6726         | 10-24-75       | 193,011 | paint ext trim (2-story houses PP, BB, RR)           |
| 6058         |                | 2968    | Install (419) double garbage can holders             |
| 7167         | 12/17/76       | 176     | Pick up 2 loads of pine straw                        |
| 8317         | 12-9-78        | 5516    | Repair driveway ribbon & sidewalks BB-17 thru BB-24  |
| 6688         | 10-14-77       | 268.    | Remove debris from roofs, gutters & downspouts       |
| 4391         | 3-18-85        | 439     | Purchase Material for Self-Help                      |
| 3362         |                | 318     | ISSUE MATERIAL FOR SELF-HELP, Plant Shrubs CHB ENTR. |
| 3427         |                | 4363    | REPAIR Ballfields.                                   |
| 5768         |                | 14,472  | " " SAFETY Problems on Balcony RAILS UEPH Bldgs.     |
| 9761         |                |         | PERFORM PM to bldg. MAINT. Rm & Pit, Steam & Cond.   |
| 1053         | 1-20-89        | 6083    | CONSTRUCT Boat Deck FOR BRIDGE                       |
| 1148         | 11-17-88       | 2589    | TROOP TRAINING Project MATERIAL.                     |
| 1083         | 3-7-85         | 60      | INSTALL Bumpers, Pender Piles, cleats & STANCHIONS.  |
| 2228         | 3-29-85        |         | ASSIST ARCHAEOLOGIST in Collection                   |

| JOB ORDER NO | DATE COMPLETED | COST                  | DESCRIPTION   |
|--------------|----------------|-----------------------|---|
| 1198         | 2-17-88        | 33,461                | TROOP TRAINING PROJECT MATERIALS.                           |
| 1065         | 4-7-89         | 11,353                | INSTALL STEAM Line & Connect mess Hall Equipment.           |
| 1083         | 9 JUN 90       | 4330                  | Provide Elec Service for Bldg MCEYS BLDG                    |
| 2210         | 12-9-94        | 5101                  | Remove STUMPS (CK to be comp by contractor)                 |
| 2013         | 6-28-96        | 6553                  | INSTALL METERS <small>SEP 28 1998</small> <i>Purple ink</i> |
| 3093         | 9/17/99        | 2,975                 | Waterhour Meter   |
| J088         |                | 68,890. <sup>28</sup> | Complete Asbestos Inspections of CHB Bldgs.                 |

BB MISC

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

GR0655

| JOB ORDER NO                  | DATE COMPLETED | COST      | DESCRIPTION  |
|-------------------------------|----------------|-----------|--|
| 021-04366-42                  | 5/12/61        | E 1684.04 | Replace screen   |
| 021-03085                     | 11/18/60       | E 644.46  | Provide water service at dump  |
| CONTRACT                      | 7/13/67        | 29,596.00 | Replace Steam & condensate lines   |
| AA9-23-XX-20676               | 4/18/69        | 1,652     | Clear out hard ditches for mosquito control in CHB                                       |
| AA9-23-XX-30873               | 7/26/68        | 535       | Replace transformer - 50 KVA - at BB Demolition area                                     |
| AA9-23-XX-31940               | 5/16/69        | 822       | Repair tank trail between CHB & Boat Basin   |
| AA9-23-XX-45159               | 6/18/69        | 250       | Swop Ing - Construction of sidewalks in CHB area   |
| AA9-23-XX-45206               |                |           | Swop Ing - Construction of sidewalks in CHB Bks area                                     |
| AA4-23-2365-XXT               | 2-22-74        | 913       | Place (2) litter deposit cans (In/Out Horcomb Blvd - Smeads Ferry <sup>Main Gate</sup> ) |
| AA4-23-4872-XXT               | 6-21-74        | -         | Repair of hydraulic telescoping (Shop equipment)   |
| AA4-23-4905-2378              | (Amend)        |           | Relocate primary elec. lines over Main Gate - Horcomb Blvd                               |
| AA4-23-4448-2371-T            | 3-1-74         | 1159      | Clean-up Montford Point and Verona Cemetery  |
| <del>AA4-23-4448-2371-T</del> |                |           |  |
| AA4-23-3854-231               | 8-17-73        | 397       | Paint + Repair   |
| AA4-23-3551-231               | 2-22-74        | -         | Repair sheathing prior to roofing contracts  |
| AA4-23-3390-231               | 2-1-74         | 3294      | Repair and Paint window & door screens   |
| AA4-23-3389-231               | 1-25-77        | 4748      | Repair or Replace screen doors + windows   |
| AA4-23-3289-231               | 8-17-77        | 1104      | Clean-Up Cemetery - Montford Point + Verona Loop   |
| AA4-23-2578-231               | 5-2-74         | -         | Relocate bleachers - Camp Johnson  |
| AA4-23-2538-231               | 4-5-74         | 568       | Construct 31 metal boxes for Insect Vectors  |
| AA4-23-2533-231               | 3-8-74         | 296       | Prepare Scoreboards (75)   |
| AA4-23-2481-2363              | 11-16-73       | 323       | Fabricate + install cover on truck (Insect Vector)                                       |
| AA4-23-2440-231               | 2-1-74         | 2372      | Install Vents to augers  |
| AA4-23-2398-2370              | 12-17-73       | 1000      | Procure Svc Contract to Rip & re-calibrate steam gage                                    |
| AA4-23-1062-2373              | 11-14-73       | -         | Construct Nestle bridge across Nicks Run   |
| AA4-23-1059-2373              | 10-24-73       | 428       | Construct Outdoor Classroom - Shed 5H  |

| JOB ORDER NO     | DATE COMPLETED | COST | DESCRIPTION  |
|------------------|----------------|------|--|
| AA3-23-0007-232  | 6-7-74         | -    | Repair spillway at Henderson's Pond                      |
| AA3-23-0003-231  | 12-20-74       | 1600 | Repair erosion at Henderson's                            |
| AA3-23-4575-231  | 3-13-73        | 812  | Clean ditches / haul away spoil Brewster Blvd            |
| AA3-23-4472-238  | 2-9-73         | 237  | Replace damaged steel gate                               |
| AA3-23-4418-2330 | 6-18-73        | 2160 | Procure 2 transformers                                   |
| AA3-23-4184-231  | 2-9-73         | 251  | Replace gate   |
| AA3-23-4113-2371 | 12-22-72       | 82   | Replace culvert. Install by NC Highway Dept              |
| AA3-23-3520-2352 | 6-29-73        |      |  |
| AA3-23-3520-2352 | 6-29-73        | 3299 | Repair Master TV Antenna                                 |
| AA3-23-2755-231  | 6-22-73        | 328  | Modify Used Oil Tanks                                    |
| AA3-23-2743-2343 | 6-1-77         | 167  | Mail Boxes   |
| AA3-23-2716-2371 | 6-29-73        | 2700 | P.M. Emerg. Generator                                    |
| AA3-23-2704-231  | 4-13-73        | -    | Snow clean up MCB  |
| AA3-23-2701-2371 | 3-2-73         | 441  | Clean-up leaves, pine straw (H. Paint)                   |
| AA3-23-2681-231  | 2-1-73         | -    | Snow Storm Clean-up MCB                                  |
| AA3-2655-231     | 1-12-73        | -    | Repair, Install & Remove X-mas decorations (Bldg 1-1202) |
| AA3-23-2634-231  | 2-16-73        | 4737 | Procure, modify & install 30-waste oil tank              |
| AA3-23-2609-231  | 11-17-72       | -    | Provide labor + materials for M.C. Bell                  |
| AA3-23-1031-2393 | 9-21-72        | -    | Rang-dry net towers                                      |
| AA3-23-0552-231  | 4-27-73        | -    | Provide support for exotic dances mazeover               |
| AA3-23-0189-     | 6-8-73         | 6505 | Install 115V recept. + water to (28) camp sites          |
| AA3-23-0185-231  | 6-29-73        | 3000 | Construct a rec. area at South end of Area 5             |

| JOB ORDER NO | DATE COMPLETED | COST  | DESCRIPTION   |
|--------------|----------------|-------|---|
| 4132         | 2-23-73        | 281   |   |
| 7609         | 2-15-74        |       | REPAIR LEAK IN SEWERLINE  |
| 3322         | 1-11-74        | 2,791 | CORRECT DRAINAGE, EROSION, GRADE, FERTILIZE, RESEED ROAD SHOULDERS. |
| 3871         | 8-15-73        | 1457  | REPLACE CABLE DEHYDRATOR  |
| 4345         | 10-19-73       | 230   | REPLACE MAIN SEWER PANEL  |
| 3238         | 7-13-73        | 1065  | MAKE WINDOW SCREENS + SASH, INSTALL GLASS, PRIME + PAINT            |
| 2315         | 7-13-73        | 220   | CHECK SERVICEABILITY ON 60 SPACE HEATERS                            |
| 5103         | 6-6-73         | 768   | REPAIR, REPLACE WINDOW SCREENS                                      |
| 3264         | 10-5-73        | 344   | MISC REPAIRS TO QUONSET HATS  |
| 3997         | 9-28-73        | 325   | CONSTRUCT SASH, PRIME + INSTALL GLASS                               |
| 3526         | 11-9-73        | 1,411 | REPLACE CULVERT UNDER STREET  |
| 4571         | 2-20-73        |       | REPLACE POLE HWY 172  |
| 4468         | 4-13-73        | 496   | CONSTRUCT SIGNS + PAINT FENCE                                       |
| 3434         | 6-1-73         | 2431  | REPLACE WINDOW SCREENS  |
| 4313         | 1-19-73        | 335   | CONSTRUCT 12 SCREEN DOORS   |
| 4142         | 11-10-72       |       | REPAIR WATER MAIN BREAK   |
| 4135         | 12-8-72        | 285   | 12 SCREEN DOORS   |
| 3862         | 9-14-72        |       | BROKEN FIRE HYDRANT   |
| 3776         | 8-18-72        | 299   | CONSTRUCT + PAINT 12 DOORS  |
| 3261         | 7-7-72         | 437   | SPRAY WEEDS   |
| 3233         | 5-5-72         | 661   | FAB. 12 WINDOW SASHES, 24 SCREENS                                   |
| 1046         | 12-6-72        | 1489  | INSTALL TELLER WINDOW   |
| 1097         | 3-2-73         | 590   | INSTALL 3 ADDITIONAL STREET LIGHTS.                                 |
| 1016         | 11-9-77        | 1489  | INSTALL TELLER WINDOW   |
| 3716         | Close out      | 4608  | Clear right of way + draglines sawmill ditch                        |
| 3356         | Close out      | 4015  | Procure material (Court House Bay)                                  |
| 1009         | 4-28-78        | 437   | Construct (2) bus stops   |

| JOB ORDER NO    | DATE COMPLETED | COST            | DESCRIPTION   |
|-----------------|----------------|-----------------|---|
| 1155            | 9-28-76        | -               | hoop training Proj: CONST. Shelter                            |
| 1029            | 11-28-75       | 4318            | install new elec. svc to sawmill                              |
| 1100            |                | 400             | (amend) const of mooring fac. at CAB at <sup>Boat</sup> Basin |
| 3381            | 8-16-74        | 1701            | rep & paint ext (2) coats                                     |
| 5619            | 8-20-76        | 1554            | rep range house (reuse tower)                                 |
| 2752            | 5-14-76        | 170             | rep boat rudder   |
| 4999            | 3-21-75        | 173             | Self-Help - Issue mat to fertilize/seed bare places           |
| 4487            | 12-19-75       | 430             | install roll roofing over existing roof.                      |
| 3932            | 11-22-74       | 3797            | Self-help - rep bridge  |
| 3485            | 7-19-74        | 365             | clear right-of-way beneath overhead steamline                 |
| 3532            | 10-4-74        | 876             | spray weeds across from MUG'S & DEMO                          |
| <del>3932</del> |                | <del>3797</del> | <del>Self-help -</del>  |
| 6761            |                | 2960            | cut dead trees in Imp Lands area.                             |
| 3485            |                | 425             | (amend) clear right-of-way                                    |
| 5724            | 8-21-76        | -0/E            | rep water main near BB-102                                    |
| <del>1100</del> |                | <del>2350</del> |   |
| <del>2752</del> |                | <del>170</del>  |   |
| <del>5619</del> |                |                 |   |
| 2509            |                | 928             | clean out & prepare (3) sludge beds                           |
| 5724            |                | 0/E             | repair water main near BB-102                                 |
| 3729            | 9/30/77        | /               | maint & service to grease & oil separator                     |
| 3352            | 10/18/76       | 4,000           | Procure material  |
| 3706            | 12/21/76       | 686             | Purchase Lorain loop extender                                 |
| 1000            | 9/23/76        | 5000            | Construct (2) LCU landing ramp.                               |
| 6935            | 11/12/76       | 287             | assemble & install 13 nail boxes                              |
| 3351            | 10/18/76       | 1840            | Procure material  |
| 3307            | 10/21/76       | 3177            | Correct erosion   |
| 3271            | 10/18/76       | 720             | Correct erosion   |
| 3354            | 10/18/76       | 5171            | Procure material  |