101	B ORDER NO	COMPLETED	COST				DESCRIPTION			
	1736	9-20-74	282	Row	cool 6	0-0	Souths	ide		
	1712	9-30-74	406	Recuren	of main	t Sohn	son s	ervice	control	esye
	1849	1-9-74	385	" "	1 11	11		11	11	11
	1808	3-1-74	873	Insta	el 6 1	ecepto	cles	-		
	1793	10-21-73	289	Chang	eleck	onlin	der + n	rabe de	ys)	
	1769	10-10-73	214	Instal	2 50' K	arle,			/	
	1721	12-28-73	379	Recure	ng main	tolons	onsewe	ie cont	tale.	sys
1	1712	9-28-78	317	lı	1 11	/ "	11	11		/11
	1837	(-29-73	350	te	**	44	h	4		44
-	1785	3-29-72	350	H	Le.	te	11	/,		11
	1736	9-29-72	350	"		, ,,	,	r.	1	11
	1727	7-7-72	998	Repla	wse	ction o	I book	ler.		
	1805	2-9-73	313	Repla	u V	belte	andes	notor-	moun	to
	1869	4-13-73	178	Riplan	· heat	circul	lating ,	sump		
	1815	1-11-73	421	Replac	e au	lating	pung	/		
	1780	11-17-72	209	Instal	l my	tacks	_ '			
27	1795	1-31-75	373	Install o	Judy (1				
	1791	6-30-75	435	Maint 4	to John	son Si	a Contra	of Supt		
-	1797			OF	up. s	ek in	roof.	· ·		
	1805	6.20.75	559	Snotall	(4) AIC	0	. 0			
-	1771	Comal	506	Recurre	mg yna	and to	contro	Gyor	ems	
	1756	9/12/77	643	Recure	ing me	sint Te	contu	al Ly	elems	
<u> </u>	1754	2/1/77	643	PM A	2	7 177				0.
	1730	12/31/76	596	Recur	ung -	maint		L. Cong	78 T SO T	
	1757			Rean	neng	main	it			111
	1749	4/2/76	506	Resur	ring .	main	z			,
-	1725		443	Recu	rung		c			
			482		//	main				
	1723	8/26/75	. 475	Recu	neing -	main	c			

TT-60 INT. PAI	NT SQ FT	EXT. PAI	NT SQ FT CONDEN. LINES LIN FT FACILITY HISTORY RECORD MCBCL 11011/3					
JOB ORDER NO COMPLETED		соѕт	DESCRIPTION					
AA923 XX 15102	7/19/68	506	Replace floor tile damaged with ink in Wing 4					
AA923XX 15122	4/11/69	132	Install antenna hook-up from master antenna to auditorium in TT 60					
AA923** 15141	6/27/69	143	Perform preventive maintenance to Johnson service system in TT 60 school					
23 0320 2319T	3/13/70	143	Perform preventive maintenance to Johnson service system					
AA023 0324 2319T	6/30/70	144	Perform preventive maintenance to Johnson service system					
AA123 0331 23XXT	11/6/70	370	Replace circulating pump in booler room					
23 0322 2319T	12/31/70	151	Perform recurring maintenance to Johnson service system					
AA123 0328 2312T	9/11/70	60	Furnish and install two halyard on (1) flagpole approx 30' to 35' high					
AA123 0334 23197	4/2/71	151	Perform recurring maintenance to Johnson control service system					
AA123 0341 2319	6/30/71	155	Perform recurring maintenance to Johnson service system					
AA123 0362 23XX	6/4/71	461	Install air cond. in library at school Bldgs no 5400, TT 60, and %C 1500					
AA223 0320 23197	10/1/71	329	Perform recurring maintenance to Johnson service control systems					
AA223 0323 23197	12/30/71	329	Perform recurring maintenance to Johnson service control system					
AA223 0361 23187	Q 9/17/71	68	Repair reach-in reefer					
223 0366 23187	3/31/72	333	Perform recurring maintenance to Johnson service control system					
AA223 0381 23207	1/21/72	807	Fabricate and install eight steel columns four in TT 60 cafeteria					
A223 0372 23XX	3/10/72	334	Correct drainage on playground rear of school					
AA223 9225 23187	4/28/72	333	Perform recurring maintenance to Johnson service controls system					
AA223 9209 2316	2/18/72	541	Install florescent lights in two sections of auditorium designated for class.					
1781	12-6-79	160	rooms.					
1781	12-6-74	169	Install 2 tube strip lights					
1775	1-24-75	199	Install 6 suttite					
1771	3-31-75	432	Becuring maint to Sohnson service controls					
1766	10-18-74	854	Haul dist fell holes, seed area					
1750	9-6-74	139	Inst 7 receptacles					
1744	12-28-74	432	Recursing maint to Salman Service Portale					