

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
5102	4/6/76	6391	Rprs / v paint extension
5504	7/2/76	965	Rpl AC comp.
5002	3/2/74	/	Rpr awning
5105	4/6/74	26,693	Structural, mechanical, elect & paint ^{ing.} Rpr.
4834	9-23-77	2116	(cont) Replace roof + ceiling on T.V. room
3555			Replace built up roof + replace ceiling tile
3360	11-25-80	400	Procure. oil tank from Lukabak Oil Co
4282	9-26-80	519	Reinsulate basement piping
4107	9-14-81	521	Rpl. double pipe handrails and paint
3976	6-5-81	1049	Rpl lrg. and unsightly shrubbery
4728	11-19-82	397	Extend Roof again
4043	9-9-83	15,027	Interior + Ext. Repairs
1214	7-23-83	756	Install Sump pump in Basement Under Back Music room
4188	5-10-85	2897	Rpl ceiling tile w/ sheet rock ceiling + lights 980 SF
4489	9-4-85	2977	Rpl partitions in Mens head + rpl swinging door by snack bar
6081	1-6-86	2079	Reinsulate all Potable water piping under Bldg.
3208	7-22-88	3300	Rplc package heat pump on roof of Bldg.
8255	8-7-92	522	Cut Holes in Door in BEHIST ROOM AND INSTALL GLASS.
EBLD	7/27/01	4817	Rplc 10 ton cond. unit
EBLP		2450	" 4 " " "
EBLU		2895	CAMBAR 02-125687 RPL Carpet

