FACILITY HISTORY RECORD BLDG NO INT. PAINT SQ FT EXT. PAINT SQ FT ROOF SQ FT CONDEN. LINES LIN FT AS 212 MCBCL IIOII/3 DATE JOB ORDER NO DESCRIPTION COST MODIFICATION of BIOG. 0275 6-13-74 4.120 2 868 3279 7-1-74 INSTAK WENDOW SCREEPS FURNESH & INJAIL 92 METAL SCREENS 99 4015 9 Relight & other mtre to Blkg 3251 18.835 4028 PURGED 99 1-(

.

JOB ORDER NO	DATE	соѕт	DESCRIPTION
3906	9-5-75	287	Repair + laint interior
3601	7-11-75	471	Repair A/C system
Cont# 18-3029	FySo	1657	Diff. Paint
_ @ 2035		582	Remane & replace defective batteries in Ema lighting
4643	4-27-78	855	Replace doar, ino tall glace, and patch tales macany and
3908	1.20.78	4263	Replace, (90) mussing stair triads
2566	5-26-78	1116	I.m. fallow up - Eren bottoney operated light units
4202	8-24-79	789	Siple floor tile + rubles bore
3/89	Cmp,	1412	Reple Centrifugal perps n Halmasiptin .
43/5	ond	1035	Repte condrat reach
4)41	9-28:79	11,579	Pt. und g Canax 1 coat these
3416	12-21-79		Remore areadaby Dume from A5-705 Parstal
3437	1-4-80	533	Lel @ locks on stairwell doors at fath ends of bldg
4070	6-9-80	880	Clean capting fails draw & pan
3468	Comp	1550	Rel Centrepetal pump # 2 on Heating
3121	8-20-82	6837	Replace all Wendow Acreen
	3-27-81	143	Repair to caling I floor tile
3178	1-15-8B	1195	Repair circulation Aputape
9191	Conp.	3507	theat water tower.
4818	Conp.	9542	Int ppr.
4674	12-9-83		Replace V-Blinds
4204	8-26-83		Replace dook Tijam K.
4665	9-30-45	666	Rpl y. Blinds in from
5178	Compl	4,652	Pearan cyclic most RepAm 3-26-84
1027	2-19-98	2374	Install Auorescent lighting
3251	11-20-87	1133	Relight & other Mint to Bldy
- 4665	9-30-85	6/10	Rept Venetian Blinds
8154	12-20-91	872	INST HANDICAP BAMP