

| JOB ORDER NO | DATE COMPLETED | COST | DESCRIPTION |
|--------------|----------------|------|--|
| 3795 | 3-16-79 | 3503 | PT Wnt G. Dms |
| 3959 | 3-30-79 | 2273 | PT Wnt G (18) Dms 1 Coat |
| 3957 | Comp | 567 | Prove. Seve catches install u/lts |
| 3344 | Comp | 1731 | Install pulley Chams on safety wd |
| 3456 | 4-10-81 | 1221 | Rpl. circulating pumps |
| 1098 | 11-7-80 | 209 | Install door & locks |
| 4527 | 8-15-80 | 1942 | Paint rooms |
| 4111 | 6-13-80 | 470 | Delete 19MH from Shop 2 |
| 3948 | 5-2-80 | 838 | Retube Condensing coil |
| 4055 | 7-27-79 | 1065 | Rpl. water coil in A/H unit |
| 3756 | 6-8-79 | 395 | Rpl. circulating pump |
| 4154 | 5-18-79 | 1724 | Paint rooms |
| 3623 | 5-18-79 | 2583 | Rpl. (4) circulating pumps |
| 4008 | 7-30-82 | 1266 | Paint rooms |
| 3675 | 8-27-82 | 1072 | Paint rooms |
| 3567 | 8-17-82 | 944 | Paint rooms |
| 3692 | 8-11-82 | 3250 | order Compressor |
| 4033 | 8-17-82 | 3695 | repr. air compressor |
| 3267 | 7-12-82 | 354 | Mpl doors |
| 1331 | 7-30-82 | 365 | Cut hole in chimney |
| 3478 | 2-26-82 | 1246 | rpl. condensate pump |
| 4316 | 2-2-83 | 7878 | repr. a/c |
| 2004 | 1-14-83 | 377 | elect. to same |
| 1232 | 5-10-82 | 946 | Install benches |
| 1250 | 10-8-82 | 3852 | Cut hole in wall inst. door jamb & had doors & paint |
| 3919 | 2-4-83 | 2641 | repr. cooling system |
| 3117 | | 1762 | Replace suspended ceiling |

| JOB ORDER NO | DATE COMPLETED | COST | DESCRIPTION |
|-----------------|---------------------|----------------|---|
| 3676 | 7-22-74 | 137 | PM MESS HALL REFERS REFRIG |
| 3846 | 8-22-74 | 2000 | PROCURE A.C. COMPRESSOR |
| 3783 | 8-1-74 | | PM MESS HALL REFRIG |
| 4068 | 8-27-74 | | PM MESS HALL REFRIG |
| 3645 | 7-23-74 | | REPAIR SWER LINE |
| 5456 | 12-31-74 | 464 | REPLACE 4 CIRCULATING PUMPS |
| 3509 | 2-17-76 | 468 | Repair of cooling tower of AS-705 |
| 3602 | 7-11-75 | 884 | Replace 3 pumps in AC system |
| 4219 | 2-13-76 | 1002 | Replace A/C motor |
| 5391 | 9-30-76 | 257 | PM TV dist. system |
| 3610 | 11-7-75 | 405 | Repair TV Antenna |
| 5473 | 6/25/76 | 224 | Rpl (1) exterior door |
| 5472 | 6/25/76 | 224 | Rpl door (1) |
| 6670 | 5/26/75 | 942 | PM to master TV |
| 3527 | 11-25-77 | 1313 | Repair leaks + expansion joints |
| 4189 | 8-19-77 | 1412 | Repair 2 A/C compressors |
| 4007 | 7-1-77 | 11,320 | Paint ext. 2 coats |
| 4627 | Close Out | | (Procure contract to furnish + install push button station on elevator) |
| 4629 | 11-25-77 | 686 | |
| 4629 | 11-25-77 | 686 | Replace AC Motor |
| 3287 | Comp | 280 | Procure contract to rep. elevator door |
| 2438 | 12-1-78 | 237 | Remove manifold to clothes dryer and install two odd vents thru wall |
| 1023 | 12-1-78 | 140 | Constant greasol between pits and elevator drive machines (in mess Rm) |
| 5348 | 12-15-78 | 2812 | Rpl (4) circulating pumps |
| 2633 | 6-2-78 | 582 | Install elec circuit and vent adapters for dryer |
| 3771 | 3-16-79 | 756 | Repr ceiling in Lobby & Parl |