

BLDG NO
BB-51

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD
MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
Contract	6-13-66		Install Ventilating System
NB-5-310-484-0317	10/2/64	1,140	Repair (10) overhead doors - replace tension springs
NB6-197-623-046	11/19/65	404	Repair brick walls
NB6-197-623-051	4/8/66	90	Repair overhead door in Welding Shop
HQ8-OMB-OMB-123	11/15/68	463	Install chain pull mechanism on (1) door
AA9-23-XX-30564	11/22/68	2,558	Repair & paint overhead doors (7 at 40 sections)
AA9-23-XX-31747	3/28/69	166	Repairs to exhaust system
3767	7-9-71	168	Repair & Paint on doors
3126	2-1-74	3484	Repair ext. 7 Blde
3135	1-25-74	915	Repair & paint int trim
3831		1011	Remove damaged brick
2518		838	Install (10) A/C
4399	3-10-72	566	Replace overhead door rollers
4415	5-7-71	837	Repair door, replace rollers hinges
1121	4-30-71	1600	Install chain hoist
1127	5-8-70	1800	Install chain hoist
3252	9-10-70	296	Repair (4) down spouts
1218	8-6-76	215	Install (1) 8ft flo light
2662	12/23/75	249	treat for termites BB-51
79-2640	1980	34,500	Replace doors
5193	10-12-78	731	Rpr doors and paint
3653	4-20-79	1840	Ext repair to buldy
4801	9-19-80	825	Rpl shower stall
3556	8-1-80	419	Raise section of water line
1085	1-25-80	573	Remove old wiring, install new 100 amp service
1015	5-8-81	261	Provide Water, Drain, & elec for welder.

