T. Barbee File

From: Director, Natural Resources and Environmental Affairs

Division, Marine Corps Base, Camp Lejeune

To: Fire Chief, Base Fire Department, Marine Corps Base,

Camp Lejeune

Subj: PCB TRANSFORMER INVENTORY UPDATE

Ref: (a) 40 CFR 761.30(a)(1)(vi)

Encl: (1) Recently identified PCB Transformers at BB-52

1. The Electrical Distribution Shop, Base Maintenance Division has advised of the presence of three additional PCB transformers in the Courthouse Bay area. In accordance with the reference, the enclosure is provided.

2. Point of contact is Mr. Tom Barbee, at extension 5977.

J. I. WOOTEN

Signatur Leinner in der Sier in der Sie Gegenfahren der Sier in de

English of the Section of the Control of the Contro

TWO I PASSED LANCE TO US FOR THE PASSED

and the flactory of the Mandaland of Managara and Allerday

CTTE KOLEROPON I. CONT. C. D. D. B. C. L. C. C. C.

6240 NREAD 24 Feb 87

From: Director, Natural Resources and Environmental Affairs

Division, Marine Corps Base, Camp Lejeune

To: Fire Chief, Base Fire Department, Marine Corps Base,

Camp Lejeune

Subj: PCB TRANSFORMER INVENTORY UPDATE

Ref: (a) 40 CFR 761.30(a)(1)(vi)

Encl: (1) Recently identified PCB Transformers at BB-52

- 1. The Electrical Distribution Shop, Base Maintenance Division has advised of the presence of three additional PCB transformers in the Courthouse Bay area. In accordance with the reference, the enclosure is provided.
- 2. Point of contact is Mr. Tom Barbee, at extension 5977.

J. I. WOOTEN

The care of the second of the agree of


And the second the supercoduction of the partial tendent categories and the super-

KINE KOLERYTON IS LEGEN FOR VINCEN DISCOURTER

31003

THREE RECENTLY IDENTIFIED PCB TRANSFORMERS AT BB-52

SERIAL NUMBERS	SPECIFIC LOCATION	DIELECTRIC DATA	TRANSFORMER KVA
61J15395]	Within a chain-link	35.0 gal (est.) INTERTEEN (191.3 kg, est)	167.0
61J15396]	fence adjacent to		167.0
61J15397]	westend of Bldg.		167.0



Memorandum

18 Feb 1987

Director, natural Rosources and Environmental Offair Division, Rection

Chief, Fire Department, Facilities

SUBJ: PCB Transformer Somertony Update REF. 40 CFR 761.30(a)(1)(v?)

ENCL. (1) Recently Herly sel PCB Transformen at BB-52

BASEMANTON Department of the

BASEMANTON Department of the

Hasander of the

Presence of three additional PCB transformers in

Hatands and Hashulom Wastes section Management Southern

of these recently identified DEB transformers located

that Conthouse Bay area.

In accordance a in Present; the enclosure is provided.

2. POC is mi Tom Barbea, \$5977.

Danny, Please read, review. If OK, send to be Typed and send out. Thank! P.S. Kresky said C.G. is bldgowner. Do not need OIC and NCOIC on file with Fire Dept. (por phoneon 0815 on 20 Feb) 32.9

Director, natural Rosources and Environmental Offair Division, Rection

Chief, Fire Dapartment, Facilities

REF. 40 CFR 761.30(a)(1)(vi)

1. The Glectrical Distribution Shop bearing of the presence of three additional pc B + rans Summers in Autorides and Hazardon Waster section Management Section

of these recently identified DEB transformers located

+h& Conthouse Bay area.

In accordance a in Regeon; the enclosure is provided. Report the view of the follow

2. POC is mr. Tom Barbee, ext. 977.

J I Wooten

Enclosure 1. Tocently Identified PCB Transformen at BB-52.

Home at Pter punto of promoto Contact in the entry and any of

SERIAL NUMBERS	SPECIFIC LOCATION	DIELECTRIC DATA	TRANSFORMERKVA
61515395	WITHIN A CHAIN-LINK	35. ogal (estimated)	167.0
61J15396	· FENCE ADJACENT TO	INTERTEEN	167.0
61515397	WEST END OF BLOG. BB-52	(1913 kg, estimated)	167.0

