

GENERAL DYNAMICS**Land Systems Division**

P.O. Box 527, Warren, Michigan 48090

Inter-Office Memo

AJD/sm:84-320


11 December 84

TO: H. Rinna
FROM: A. J. De Stefano
SUBJ: MRS Condensation
ENCL: ITR 14-0033

1. Three (3) vehicles were noted during the last year in which water was present in the MRS. However, this was the result of improper sealing of window PN 12285867. (See ITR 1207-0001, 1265-0001, 1595-0001, and 1161-0002) All of the above vehicles were received in early 1984, and subsequent vehicles did not exhibit this problem. No condensation problems were noted.
2. Condensation in the MRS of fielded vehicles is considered a problem. However, it is seasonal and is usually prevalent during times of wide temperature fluctuation. At worst case 30% of a battalion's vehicles may have this problem. (See ITR 14-0033, attached)



A. J. De Stefano
Site Supervisor
Fort Hood, Texas

Art
Please put this into the computer
B.B is B1H1
Return to me 

GENERAL DYNAMICS

Land System Division

TO: [Illegible]

FROM: [Illegible]

SUBJECT: [Illegible]

[Illegible text follows, including what appears to be a date and a reference number.]

[Illegible text follows, including what appears to be a description of the project or system.]

[Illegible text follows, including what appears to be a list of items or a table.]

[Illegible text follows, including what appears to be a signature or name.]

[Illegible signature]

[Illegible name]

[Illegible title]

[Illegible handwritten notes]