

NREAD/KJ/jc  
11090/3  
27 Feb 1984

From: Director  
To: Base Maintenance Officer

Subj: Underground Gasoline Storage Tank and Supply Line at  
Building A-1; apparent leak(s) in

Ref: (a) Inspection of Gasoline Storage Facilities at Bldg. A-1  
on 21 Feb 1984 by Captain THOMASON and Mr. J. FULCHER,  
BFD, Mr. T. SHEPARD, BMain, and Mr. K. JOLLY, NREAD  
(b) Reinspection of Gasoline Storage Facilities at Bldg. A-1  
on 24 Feb 1984 by Chief PADGETT and Mr. L. SMITH, BFD,  
Mr. L. ALEXANDER, BMain and Mr. K. JOLLY, NREAD

1. During references (a) and (b), gasoline was identified in a drop inlet and storm drain downgrade of and adjacent to the subject facilities. During reference (b), it was determined that a deteriorated fuel line between the subject tank and an adjacent pump was leaking gasoline into the adjacent soil. The gasoline leakage is contributing to POL pollution of adjacent surface and ground waters.

2. It is requested that the subject fuel line be replaced immediately and the storage tank be tested for possible additional leaks.

3. Point of contact in this matter is Mr. Ken JOLLY, NREAD, telephone 5003/2033.

J. I. WOOTEN

