

## Memorandum 5200 NREAD

DATE: 28 Aug 87

FROM: Albert C. Henry, Jr., Wildlife Biologist, NREAD, MCB, Camp Lejeune

TO: Charles D. Peterson, Wildlife Manager, NREAD, MCB, Camp Lejeune

## SUBJ: STANDING WATER IN TANK TRAIL

- 1. Two possible short-term solutions to the problem of water standing in the Tank Trail approximately 200 300 yards down Sneads Ferry Road from OP-5 are:
- a. There is an existing ditch running east to west which starts at the problem site and empties into a small pond and Tank Trails by Marines Road. This ditch runs away from Sneads Ferry Road and would carry the standing water if a pump was set up and 50 feet or so of hose was laid down the ditch. The problem is that the hole is deeper than the bottom of the ditch, thus the standing water.
- b. The pond (it is dry) east of Sneads Ferry Road (between Sneads Ferry Road and the Tank Trail) could hold the water from the problem site if a small earthen dam was erected to block the ditch running to the culvert under Sneads Ferry Road. The water could then be pumped over to the pond.
- 2. Colonel Lilly, Don Gurganus, and Jim Grimmet were at the site with me, and I discussed both of these solutions with them.

albert C. Henry In.

