
CONTRACTOR'S SUBMITTAL TRANSMITTAL CONTRACT NO. LANTDIV NORFOLK 4-4355/3 (Rev. 11-80) TRANSMITTAL NO 81-C-1766 34 11 Aug 83 FROM CONTRACTOR PROJECT TITLE AND LOCATION Trader Construction Company Public Works & Helipad MCB Lockwood Greene/Six Associates Camp Lejeune, N.C. CONTRACTOR USE ONLY REVIEWER USE ONLY *List only one specification division per form. **ACTION CODES A-Approved List only one of the following categories on each transmittal form, D-Disapproved and indicate which is being submitted AN-Approved as noted Contractor Approved RA-Receipt acknowledged. OICC Approval Deviation/Substitution C-Comments For OICC Approval R-Resubmit PROJ. SPEC. SECT. NO. OF ITEM IDENTIFICATION ACTION REVIEWER'S & PARA. and/or (Type, size, model no., Mfg. name, dwg. or PROJ. DWG. NO. CODES INITIALS brochure number) CODE AND DATE 137 08330 Doors, 7'8x10'0 7 Doors, 8'8x12'0 Doors, 11'4x12'0 7 Doors, 10'4x12'-"B" Cable door Pit 7 Shop Drawings - Hydraulic Dockleveler Dock Bumpers Certificate of Compliance CONTRACTOR'S COMMENTS COPY OF TRANSMITTAL AND SUBMITTALS TO ROICC CONTRACTOR REPRESENTATIVE (Signature) ROICC. Camp Lejeune. N.C. DATE RECEIVED BY REVIEWER FROM (Reviewer) Six Associates, Inc. Trader Construction Co. Submittals are returned with action indicated. Approval of an item does not include approval of any deviation from the contract requirements unless the con-Submittals are forwarded to LANTDIV with A-E recommendations indicated in REVIEWER USE ONLY Section and in comments below on ONE COPY of the REVIEWER'S COMMENTS The dock leveler submittal does not contain enough data to determine Contract Document compliance. See NAVFAC letter dated 19 May 83 regarding deviation submittals. COPIES TO: ROICC (2) LANTDIV (1) A-E (1) DATE SIGNATURE 8/31/83



SUPERIOR BUMPER PRODUCTS, Inc.

Manufacturers and Distributors
450 BISHOP ST., N. W.
ATLANTA, GEORGIA 3038

ATLANTA, O	GEORGIA 30381
JOB and LOCATION: Traler Co Architect	nstructionPublic Works-Camp Leja: Contractor
THRE/	ADED ROD BUMPER
41111111	4½"
10"	36" 36"
12	3 8 "
**Bumpers which are 6 or 10 on each side and 1	inches wide have 2 mounting holes 2 inch wide bumpers have 3/side
XXX Threaded Rod Loading *Threaded on 3/4 inc	Dock Bumper h threaded rods*
Thickness 41 (Bolts by	ll Length <u>38</u> Width <u>10</u> others) 4 6 Size of Bolts <u>5/8</u> <u>3/4</u>
Total Number of bumpers to be	furnished (14)
Bumpers to be installed by	the lequipme
Remarks:	furnished 14 furnished 14 certified that the lequipment the lequipment of the lequ
	in is hereby certain marked or oracle is in
я _с	"It is hereby certified that the lequipment of the lequipment of the hereby certified that t
	com liance of submitted Governous com sacces, and is submitted Governous com
	appropried by

