

TELECON LARRY EVANS

6 JUN 2011

1. HE CALLED UPON ARRIVAL IN SAN JUAN, TO CONNECT W/ FIELD.
 2. BOB ADVISED CONCERN W/ MLV DRAWINGS HE PROVIDED.
 - (a) 18.0-2-321.59 REV 4, PDF MP 57 SHOWS "PARCELONETA CONNECTION" (3 VALVES)^{MLV#7+7A}, BUT LARRY'S MLV#7* SHOWS ONLY ONE VALVE, 50x60' TOP OF PAD. HOWEVER IS PEM. IF ^{PREPA} ~~YOU~~ ASK FOR MORE FILL ~~TO~~ FOR LARGER PAD FOR 3 VALVES. FOR STUB-OUT THAT PREPA SAYS IS NOT NEEDED, I WOULD HAVE DIFFICULTY FINDING THAT ~~TO~~ BE A MINIMIZED ~~TO~~ WETLAND IMPACT. (MLV#13-14 PALO SECO LATERAL IS 101.5 x 50' W/ 3 VALVES.)
 - (b) 18.0-2-321.94 REV 3 MLV#15+16 MP 87 BAYAMON CONNECTION IS IN WETLAND PER NWT & PREPA'S DRAWINGS BUT NOT ~~LARRY~~ AMONG LARRY EVANS PROVIDE DRAWINGS* - THIS IS ALSO A "STUB-OUT."
- * 20110602 LARRY EVANS UPLOAD OF VALVE STATION DRAWINGS
3. LARRY WILL GET W/ APPLICANT. UNDERSTANDS.