
Preliminary Data – Hurricane Katrina Canal Breachings, 17<sup>th</sup> Street, London Avenue and Industrial Canal

Dr. Ivor van Heerden Director Center for the Study of Public Health Impacts of Hurricanes, Deputy Director LSU Hurricane Center Louisiana State University



# Advisory 18, Submitted Saturday 2200



#### "New Orleans Will Flood"

# 10 M SPOT Satellite Image: 2 Sept 2005

AT LOUISIANA STATE UNIVERSITY

DeWitt Braud and Rob Cunningham

10 M SPOT Satellite Image: 2 Sept 2005 With Water depth overlays – Orleans East

Levee Overtopping

Industrial Canal Overwash

Levee Degradation

Flood elevation: +1ft NAVD 88 2 Sept 2005

Levee Degradation

Color

Water Depth

15

14

ATURAL SYSTEMS MODELING GROUP

P DeWitt Braud and Rob Cunningham



### Scour Trench from Overtopping for 3 hours



### 10 M SPOT Satellite Image: 2 Sept 2005 With Water depth overlays

17th Street canal break

Water Depth


Color

Industrial Canal Overwash

London Ave Canal Breaks


Flood elevation: +3ft NAVD 88

AT LOUISIANA STATE UNIVERSITY DeWitt Braud and Rob Cunningham



#### **17th Street Canal Breach**

Hurricane Katrina Surge at the Industrial Canal & Lake at the 17th Street Canal IC-Peak at 0830 AM; Lake Peak 0900 AM





17<sup>th</sup> Street Canal – Note displaced levee section in middle of the breach, which moved 35 feet





Earth berm and fence moved 35 feet laterally (heave) by water pressure

#### Wood and organic matter

09.28.2005

A Listen

17<sup>th</sup> Street


17th Street Canal -'Heaved' yard behind levee wall that moved 35 feet laterally

01 06


Old swamp cyprus stumps exposed by scour

09.28.2005





### 17<sup>th</sup> Street Canal - Aerial Sketch Preliminary Data



### London Ave Canal – Filmore Breach

Clubhouse (as built) at base of levee soil embankment - London Ave Canal west breach. Note pine tree location on left.

Daniel Cantrell

#### Club house and pine tree after heave – London Ave Canal west breach, rose 6-8 feet!



#### **Daniel Cantrell**

London Ave Canal bowed wall segments near Filmore Road, east side of canal

28 12:37 PM


London Ave Canal – Large 'sand boil' at base of levee soil embankment, east side

No.

MAR A

1:03 PM

London Ave Canal – Heaves In yard, tilted flower bed and buildings, east side.



### Mirabeau Break on London Ave.







#### Mirabeau Breach – Blowout Preliminary Data

0

-4 FEET

-10+

MARSH

PEAT


CANAL


SAND

Û

#### **Industrial Canal Breachings**


Hurricane Katrina Surge at the Industrial Canal & Lake at the 17th Street Canal IC-Peak at 0830 AM; Lake Peak 0900 AM








# Levee Failure on East Side of Industrial Canal















1:32 PM

415

Note: 'R' bars bent horizontal while wall at 45 degree angle – barge bottom move across after wall collapsed?

# 20 1:36 PM


MINIMUM



Levee wall tilted back. Cracks and soil failure in front of wall and development of downward percolation holes Cyprus tree stump from Old swamp floor

20

#### **Industrial Canal Levee failure – preliminary data**





Over 1000 Louisianan's perished from the Katrina floods Approximately 100,000 Families are now homeless, most of whom heeded evacuation orders. They believed in the security of the levee systems. What happens to them?