BP ADMINISTERED CLAIMS THROUGH AUGUST 23

This chart will be discontinued due to transition of individual and business claims to the Gulf Coast Claims Facility

	oranio to tito ouri ocaci oranio i acinty					
State	# Claims Filed	# Checks Disbursed	\$ Disbursed			
TX	5,064	3,593	\$11,190,349			
LA	35,012	50,098	\$153,232,283			
MS	26,150	12,843	\$30,539,987			
AL	31,216	34,327	\$97,970,137			
FL	39,353	24,106	\$81,899,687			
GA	4,795	2,735	\$7,707,417			
Other	12,330	5,937	\$16,433,069			
Total	153,920	133,639	\$398,972,929			

BOOM RECOVERY ACTIVITY					
Activity					Total
Location	LA	MS	AL	FL	
Boom Deployed or Assigned	1,858,808	51,900	54,250	0	1,964,958
Boom Staged	567,025	18,400	391,474	36,450	1,013,349
Net Boom Recovered in past 24 hour period	24,280	15,850	44,900	_	85,030

SHORELINE/BEACH IMPACT RESPONSE (Miles)					
Impact Areas	LA	MS	AL	FL	Total
Moderate to Heavy	114.6	11	3	3	131.6
Light to Trace	234.6	98	66	125	523.6
Change in past 24 hour period	0.3	0.0	-4.0	0.0	-3.7

Gulf of Mexico Incident - Daily Dashboard -

Period: 8/24/10 6AM - 8/25/10 6AM

Produced BP's Washington, DC Office Sources: BP and National Incident Command



Highlights:

- All Individual and Business claims transitioned to the Gulf Coast Claims Facility.
- Operations to recover broken drill pipe from the capping stack and blowout preventer ongoing.
- Boom recovery continues across Gulf

RESPONSE EQUIPMENT						
	LA	MS	AL	FL	Drill Site	Total
Vessel of Opportunity	1,006	136	183	81	0	1,406
Near throu	gh deco	_	demobili		_	2,134
Total moran	JII WIII (–	- -	_	_	72
Total:	_	_	_	_	_	4,447

MISCELLANEOUS					
	Prior 24hrs	Total			
Wildlife Impacts	143	8,070			
Response Personnel	-	29,705			

BP Gulf of Mexico Incident Daily Update – August 25, 2010

Produced by BP's Washington, DC Office Sources: BP and National Incident Command



Topline

Removal of BOP and Capping Stack – The ambient pressure test conducted over the weekend was successful in determining that the BOP and Capping Stack could be removed from the Macondo wellhead without risk of hydrocarbon leakage. The vessel *Enterprise* is currently in process of removing the broken drill pipe that is in the failed blowout preventer. The middle rams on the Capping Stack were successfully opened today and they are preparing to commence fishing for the drill pipe. The Capping Stack, which was placed on top of the blowout preventer in July to seal the well, will then be removed. After the broken drill pipe and capping stack have been removed, the *Q4000*, another vessel onsite, will remove the failed Macondo blowout preventer.

Once all the equipment has been cleared away from the Macondo wellhead, the *Development Driller II*, which will place a new BOP onto the well. This BOP had been in place on the second relief well during drilling operations there. That second relief well is currently cemented in and has a storm packer in place.

BP is complying with government directives concerning all recovery of equipment from the Macondo well. We are following Admiral Allen's instruction to bring equipment it to the surface. The U.S. Government will then preserve it at a facility in New Orleans specified by the Marine Board of Investigation. Additionally, we are preparing responses to a recent request from the Department of the Interior that BP and other parties provide input into the types of inspection, testing and analysis that government agencies or others might conduct on the BOP.

Relief Wells – The *Development Driller III* remains on standby and the first relief well is approximately 50 feet from the intercept point with the Macondo wellbore. Once the new BOP is on the Macondo wellhead, the *DDIII* will proceed with drilling and ranging operations in the first relief well. The new BOP on the Macondo wellhead will provide a more robust system to contain any pressure put into the Macondo well during intercept and a bottom kill operation.

Claims Transition to Gulf Coast Claims Facility Underway – On Monday, BP transitioned its individual and business claims program to the Gulf Coast Claims Facility (GCCF). BP's claims team will continue to handle government claims and funding requests. The contact information for government claims with BP is:

Online at www.bp.com/governmentclaim;
 Email at governmentclaims@worleyco.com;

Mail to:Government Entity Claims and Funding Requests

1905 W. Thomas Street

Suite D-358

Hammond, LA 70401;

Phone 1-877-710-4064; orFax 1-800-810-5650.

The GCCF will administer all new claims, and all claims that were pending as of August 23. For detailed information on procedures, contact information and office locations, please visit the GCCF website at: http://www.qulfcoastclaimsfacility.com/.

State Summaries – Shoreline Operations

LOUISIANA

SHORELINE: Continue to identify oiling and reset boom.

BOOM: Recovered 35,000 ft of hard boom yesterday and deployed 10,720 feet. 1,858,808 feet of boom remains deployed.

MISSISSIPPI

SHORELINE: No new oiling reported. Crews continued manual beach cleaning in Harrison, Hancock and Jackson Counties..

BOOM: Recovered 15,850 ft of boom yesterday. 51,900 feet of boom remains deployed.

ALABAMA

SHORELINE: No new oiling reported. Crews continued manual beach cleaning in Gulf Shores, Ft. Morgan, Orange Beach and on Dauphin Island.

BOOM: 44,900 ft of boom recovered yesterday. 54,250 feet of boom remains deployed.

FLORIDA

SHORELINE: No new oiling reported. Crews continued beach cleaning. Mechanical cleaning will continue in Okaloosa and Walton Counties.

BOOM: Final boom recovery has been completed throughout Florida.

Information Resources					
Government claims can be filed at: www.bp.com/governmentclaim Individual and business claims should visit the Gulf Coast Claims Facility website at: http://www.gulfcoastclaimsfacility.com/	(877) 710 4064				
Environment / Community Hotline – to report oil on the beach or shoreline or other environment or community impacts and access the Rapid Response Team	(866) 448-5816				
Wildlife – to report and access care for impacted, i.e. oiled wildlife	(866) 557-1401				
Volunteers – to request volunteer information	(866) 448-5816				

Worker Health and Respirator Use

- BP personal exposure monitoring program summary includes an explanation of the program and the results of the tests. To view the report, visit the BP website:
 - http://www.bp.com/liveassets/bp_internet/globalbp/globalbp_uk_english/incident_response/STAGING/local_assets/downloads_pdfs/health_monitoring_summary_report_july.pdf.
- U.S. Department of Labor's guidance on protecting worker health at: http://www.osha.gov/oilspills/interim-guidance-qa.html. This guidance answers commonly asked questions about heat stress, use of respirators, and chemical exposure.

BP Environmental Monitoring Program – several sampling and monitoring programs have been implemented. The data is posted on BP's website at: http://www.bp.com/sectiongenericarticle.do?categoryld=9033821&contentId=7 062498#

Interactive Mapping Websites – Interactive Mapping Tool meant to provide a one-stop shop for detailed near-real-time information about the response to the Deepwater Horizon BP oil spill.

- The BP mapping tool is located at: http://www.gulfofmexicoresponsemap.com.
- The U.S. Government mapping tool that is located at: www.GeoPlatform.gov/gulfresponse.

BP Website: www.bp.com

Twitter: Oil_Spill_2010

Facebook: Deepwater Horizon Response

Joint Incident Command website: www.restorethegulf.gov