

# U.S. Senate

## Desk Description and Condition Report

Desk No : **66.00000.015**

Paper Label No.(on shelf bottom): 15

Painted No. (on bottom): N/A

Other identifying labels or marks (specify location): Stretcher: 15, 15, XV / Top: 15, 6 (crayon); underside of top: 6 (pencil) / Drawer Bottom: outside - No. 51 (?) / Drawer Back: 15 (pencil) / Bottom of Shelf (other than paper label): N-- (chalk) / Inkwell: 15, 3 (pencil)

### Description of Desk

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 3/8	32 3/16		
Width (front)	28 11/16	26 3/8	25 5/8	
Width (rear)	27 3/8	25	24 3/16	
Depth	19 5/8	19 15/16	19 1/8	9 13/16

\* Note: Dimensions do not include "booster" blocks added to feet or writing top.

### Woods

Primary:

Mahogany

Mahogany veneer

Rosewood veneer

Other Wood (specify): \_\_\_\_\_

\_\_\_\_\_

Character of case mahogany:

Plain

Ribbon

Mottled

Crotch

Other

Secondary:

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				✓	
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior	✓	✓			
Drawer Front	✓				



### Condition of Desk

#### Structure

Previous breaks in structural elements: Yes   
 (shown on schematic)  
 No

Current split or broken elements: Yes   
 (shown on schematic)  
 No

Other loose or damaged joinery: Yes   
 (describe in narrative)  
 No

Damage to drawer front: Extreme   
 Moderate   
 Minor

Drawer lock: relocated on face Yes

Drawer lock: resized on inside Yes

Cockbead on drawer front: Damaged   
 (show on schematic)  
 Missing   
 Loose   
 Replacements

Replaced drawer-side runners: Yes   
 No

Replaced case-side runners: Yes   
 No

Drawer bottom pieced-out at back edge: Yes   
 No

Wear on Feet	Extreme	Moderate	Minor
Front	✓		
Rear			✓

Number of loose spindles: No: 0

Number of replaced spindles: (show on schematic) No: 4

Replaced veneers and cross-banding: Yes   
 (show on schematic)  
 No

Missing veneers and cross-banding: Yes   
 (show on schematic)  
 No

Delaminated/loose veneers & cross-banding: Yes   
 (show on schematic)  
 No

Shelf supports: Original/old   
 New/recent   
 Missing

Spindle support board in case: Yes   
 No

**Finish**

Age	Excellent	Good	Fair	Poor
New			✓	
Old				
Unk.				

Note: Describe finish problems in narrative.

**Hardware/Attachments**

Item	Mismatch	Missing	Damaged
Knob (L)			
Knob (R)			✓

Toe cap size:	Right toe: 5
	Left toe: 5