

**U.S. Senate  
Desk Description and Condition Report**

Desk No : **66.00000.065**

Paper Label No.(on shelf bottom): **74**

Painted No. (on bottom): **N/A**

Other identifying labels or marks (specify location): Stretcher: 74, 76, LXV / Top: 62 (crayon) / Drawer Back: 74 (pencil) / Inside Case Back: 74 (chalk), 12 (chalk), 69 (pencil) / Bottom of Shelf (other than paper label): chalk inscription / Inkwell: 65 (pencil)

**Description of Desk**

Dimensions (in inches)

	Overall	Orig. Desk*	Case	Shelf
Height	35 1/16	32 1/4		
Width (front)	28 1/2	26 1/2	25 5/8	
Width (rear)	25 1/4	23 5/16	22 5/8	
Depth	20	20	19 1/4	10 1/4

\* Note: Dimensions do not include "booster" blocks added to feet or writing top.

**Woods**

Primary:

Mahogany

Mahogany veneer

Rosewood veneer

Other Wood (specify): \_\_\_\_\_

\_\_\_\_\_

Character of case mahogany:

Plain

Ribbon

Mottled

Crotch

Other

**Secondary:**

Element	Pine	Ash	Poplar	Mahog	Other
Drawer Sides				✓	
Drawer Bottom			✓		
Drawer Back			✓		
Case Interior		✓			
Drawer Front	✓				



## Condition of Desk

### Structure

Previous breaks in structural elements: Yes   
(shown on schematic)  
No

Current split or broken elements: Yes   
(shown on schematic)  
No

Other loose or damaged joinery: Yes   
(describe in narrative)  
No

Damage to drawer front: Extreme   
Moderate   
Minor

Drawer lock: relocated on face Yes   
Drawer lock: resized on inside Yes

Cockbead on drawer front: Damaged   
(show on schematic)  
Missing   
Loose   
Replacements

Replaced drawer-side runners: Yes   
No

Replaced case-side runners: Yes   
No

Drawer bottom pieced-out at back edge: Yes   
No

Wear on Feet	Extreme	Moderate	Minor
Front	✓		
Rear			✓

Number of loose spindles: No: 1

Number of replaced spindles: (show on schematic) No: 2

Replaced veneers and cross-banding: Yes   
(show on schematic)  
No

Missing veneers and cross-banding: Yes   
(show on schematic)  
No

Delaminated/loose veneers & cross-banding: Yes   
(show on schematic) No

Shelf supports: Original/old   
New/recent   
Missing

Spindle support board in case: Yes   
No

## Finish

Age	Excellent	Good	Fair	Poor
New			✓	
Old				
Unk.				

Note: Describe finish problems in narrative.

## Hardware/Attachments

Item	Mismatch	Missing	Damaged
Knob (L)	✓		
Knob (R)			

Toe cap size:

Right toe: 5

Left toe: 6A