


HADNOT POINT			Cost	s (\$00	00)	
FACIL. IDENT.	WORK DESCRIPTION	1986		1988		1990
Plant Bldg.	Equipment: Treatment	W		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
No. 602	Associated					
CONTHMINATED	Other					
Distrib. Sys.	Pipes and Valves		400.00		500.00	
From:	Pumping Stations	1	700.00	1 2 2 2	300.00	
To:	Manholes	1.		100 T 100 T		
Above Grnd.	Tunnels	, ,				a and the same of the
Below Grnd.	Other Pump Repairs New Pour	i i v		6000.00		7
Plant Bldg.	Pour manual m	· · · · ·				1
No. <u>603</u>	Equipment: Treatment	1				
No. <u>203</u>	Associated Other	14.				
	OCHEL	4.		100		
Distrib. Sys.	Pipes and Valves		500.00			
From:	Pumping Stations		200.00			
To:	Manholes		N. C.			
Above Grnd.	Tunnels					
Below Grnd.	Other Pump Repaires	1. 1. 12	2500.00			1500,00
Dlant Dlda		a trade year				100
Plant Bldg.	Equipment: Treatment					
No. 606	Associated					16
	Other					
Distrib. Sys.	Pipes and Valves			~ 0		
From:	Pumping Stations			500,00		
To:	Manholes		38.2			
Above Grnd.	Tunnels					
Below Grnd.	Other Pump Repairs			6000.00		




			Cost	s (\$00	0)	
FACIL. IDENT.	WORK DESCRIPTION	1986	1981	1988	1989	1920
Plant Bldg.	Equipment: Treatment					
No. 608	Associated					
	Other					
Distrib. Sys.	Pipes and Valves		400.00			500.0
From:	Pumping Stations		7000			5 00.0
To:	Manholes			48.00		
Above Grnd.	Tunnels .	, ,				
Below Grnd.	Other Pump Repaires	· iv		150000		
			19.77			
Plant Bldg.	Equipment: Treatment	•				
No. <u>609</u>	Associated					
	Other					
Distrib. Sys.	Pipes and Valves				500,00	
From:	Pumping Stations					
To:	Manholes					
Above Grnd.	Tunnels					- 172 122
Below Grnd.	Other Pump Repairs		5000.00			
Plant Bldg.	Equipment: Treatment					
No. 610	Associated					
	Other		1 m. 3 m			
Distrib. Sys:	Pipes and Valves					500.00
From:	Pumping Stations					
To:	Manholes		100		- 10 B 12	uni di
Above Grnd.	Tunnels					
Below Grnd.	Other Pung REPAIRS			600.00		




			Cost	s (\$00	0)	
FACIL. IDENT.	WORK DESCRIPTION	1986	1987	1988	1989	1924
Plant Bldg.	Equipment: Treatment					
No. 6/3	Associated					
	Other					
Distrib. Sys.	Pipes and Valves					500.00
From:	Pumping Stations		W. Spalin			THE STATE
To:	Manholes	1.71	4			
Above Grnd.	Tunnels	1 1				
Below Grnd.	Other Pump Repairs				5000.00	
Plant Bldg.	Equipment: Treatment					
No. <u>6/6</u>	Associated	<u> </u>				
	Other	I.				
		•				
Distrib. Sys.	Pipes and Valves					600.00
From:	Pumping Stations					
To:	Manholes					
Above Grnd.	Tunnels					des Acres
Below Grnd.	Other Pump Repaires	and the sales of the		3000.00	C = 1 - 1 10 - 1	Anne de
Plant Bldg.	Equipment: Treatment					100
No. <u>620</u>	Associated					
	Other			74		
	The state of the s					
Distrib. Sys.	Pipes and Valves					1000.00
From:	Pumping Stations					
To:	Manholes					
Above Grnd.	Tunnels					100
Below Grnd.	Other Pump Repaires					1000.00




Costs (\$000) 1986 1987 1988 1989 1920 FACIL. IDENT. WORK DESCRIPTION Plant Bldg. Equipment: Treatment No. 622 Associated Other Distrib. Sys. Pipes and Valves Pumping Stations From: To: Manholes Above Grnd. Tunnels Below Grnd. Other Pump Repaires 400,00 400.00 Plant Bldg. Equipment: Treatment No. 623 Associated Other Pipes and Valves Distrib. Sys. Pumping Stations From: Manholes To: Above Grnd. Tunnels Other Pums Repaires Below Grnd. 400.00 400.00 Plant Bldg. Equipment: Treatment Associated No. 628 Other Distrib. Sys. Pipes and Valves From: Pumping Stations To: Manholes Above Grnd. Tunnels Other Pump Repaires Below Grnd. 400.00 400.00




THE STATE OF THE STATE OF			Cost	s (\$00	0)	
FACIL. IDENT.	WORK DESCRIPTION	1986	1957	1988	1989	1990
Plant Bldg.	Equipment: Treatment					
No. 629	Associated					
	Other					
Distrib. Sys.	Pipes and Valves					
From:	Pumping Stations			13 3 Sept. 18		
To:	Manholes					
Above Grnd.	Tunnels	3 1				
Below Grnd.	Other Pump Repairs	,1 ,1		400.00		400.00
Plant Bldg.	Equipment: Treatment					1
No. <u>632</u>	Associated					
	Other	4.	5 6	1.0		
Distrib. Sys.	Pipes and Valves			1000,00		
From:	Pumping Stations					
To:	Manholes			10.33		177. 19. 11
Above Grnd.	Tunnels		A. Account			
Below Grnd.	Other Pump Repaires			6000.00		400.00
Plant Bldg.	Equipment: Treatment					
No. 633	Associated					
	Other					
Distrib. Sys.	Pipes and Valves					1000.00
From:	Pumping Stations	and the second				7000.00
To:	Manholes					
Above Grnd.	Tunnels					
Below Grnd.	Other Pump Repaires				6000.00	
	a distance				20000	



			Cost	s (\$00	0)	
FACIL. IDENT.	WORK DESCRIPTION	1986	1957	1988	1989	1920
Plant Bldg.	Equipment: Treatment					
No. 634	Associated					
contaminates	Other			9.8		
Distrib. Sys.	Pipes and Valves		500.00			10090
From:	Pumping Stations					
To:	Manholes			Same State of		
Above Grnd.	Tunnels	2 3				
Below Grnd.	Other Punt Repaires	.1 .1		3000,00		
Plant Bldg.	Equipment: Treatment	1	1			
No. 635	Associated					-
	Other		1000			
		•••				
Distrib. Sys.	Pipes and Valves				1000.00	11 1 7 15
From:	Pumping Stations					
To:	Manholes					
Above Grnd.	Tunnels					
Below Grnd.	Other Pump Repaires		6000.00			
Plant Bldg.	Equipment: Treatment					
No. <u>636</u>	Associated					
	Other					
				4		
Distrib. Sys.	Pipes and Valves		1000.00			
From:	Pumping Stations		L sakers			
To:	Manholes					
Above Grnd.	Tunnels		7 38			
Below Grnd.	Other Turn Repaires		6000.00			14 14 1




			Cost	s (\$00	0)	
FACIL. IDENT.	WORK DESCRIPTION	1986	1982	1988	1989	192
Plant Bldg.	Equipment: Treatment					
No. 637	Associated					
Confaminated	Other					
Distrib. Sys.	Pipes and Valves				500,00	
From:	Pumping Stations					
To:	Manholes	et a				
Above Grnd.	Tunnels	,				
Below Grnd.	Other Pump Replies	, 4		3000,00		
Dlank Dldg						
Plant Bldg. No. <u><38</u>	Equipment: Treatment	``				
	Associated	- P.				
	Other	1:.				
Distrib. Sys.	Pipes and Valves				1000.00	
From:	Pumping Stations					
То:	Manholes		F 125			4.16
Above Grnd.	Tunnels					
Below Grnd.	Other Pump Repairs				3000.00	
Plant Bldg:	Equipment: Treatment	•				par en criar
No. <u>439</u>	Associated	A A				
no. <u>a</u>	Other					
						N
Distrib. Sys.	Pipes and Valves	300,00				
From:	Pumping Stations			va v		
To:	Manholes					
Above Grnd.	Tunnels					
Below Grnd.	Other Pump Repaires				2000.00	




			Cost	s (\$00	0)	
FACIL. IDENT.	WORK DESCRIPTION	1986	1987	1988	1989	192
Plant Bldg.	Equipment: Treatment					
No. 640	Associated					
	Other Replace AUX ENG. (DIESEL)			4000,00	1	
Distrib. Sys.	Pipes and Valves		100.00			
From:	Pumping Stations		700.0-			
To:	Manholes	1.7		20 20 20		
Above Grnd.	Tunnels	,			1 1 2 1 4	
Below Grnd.	Other Pump Repaires	i i		6000.00		1
Plant Bldg.	Equipment: Treatment	1.				
No. <u>641</u>	Associated	-				
	Other	4.				Pile.
	CHEL	1.				
Distrib. Sys.	Pipes and Valves	500.00				
From:	Pumping Stations		5 2 3			
To:	Manholes					
Above Grnd.	Tunnels		Maria de la companya	100		
Below Grnd.	Other Pump Rephiles	6000.00	3 %			
Plant Bldg.	Equipment: Treatment	· .				
No. 642	Associated	2.00		45		
	Other					
Distrib. Sys.	Pipes and Valves					
From.	Pumping Stations		1000.00			
From:	Pumping Stations Manholes				-	
Above Grnd.	Tunnels					
Below Grnd.			1.00 .0			
DOLOW GITTA.	Other Pump Repaires	2 2 2 2	6000,00			

The second secon	Charles to the Control of the Contro	The state of the s				


WORK DESCRIPTION Equipment: Treatment	1986	1987	1006	3000	
Equipment: Treatment	disconnect limitations are a second		1775	1957	11990
Associated					
Other					
Pipes and Valves					500,00
Pumping Stations					33070
Manholes		JUNE DE LA	and policy of	472 75 8	To select the
Tunnels					
Other Pump Repaires	A 108 1		6000.00		
Equipment: Treatment		I to the late of	1		
	*				
CCHEL					
Pipes and Valves		500,00	94.1		
Manholes					
Tunnels					- [1]
Other Pump Repaires		A-125	6000,00	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	op den ere
Equipment: Treatment	• •			1 14 15	181 49
Other					10 mg
Pines and Valves		7.0.0			
		200190			
			2000 10		
	Pipes and Valves Pumping Stations Manholes Tunnels Other Pump Repairs Equipment: Treatment Associated Other Pipes and Valves Pumping Stations Manholes Tunnels Other Pump Repairs Equipment: Treatment Associated	Pipes and Valves Pumping Stations Manholes Tunnels Other Pump Repairs Equipment: Treatment Associated Other Pipes and Valves Pumping Stations Manholes Tunnels Other Pump Repairs Equipment: Treatment Associated Other Pipes and Valves Pumping Stations Manholes Tunnels Other Pipes and Valves Pumping Stations Manholes Tunnels	Pipes and Valves Pumping Stations Manholes Tunnels Other Pump Repairs Equipment: Treatment Associated Other Pipes and Valves Pumping Stations Manholes Tunnels Other Pump Repairs Equipment: Treatment Associated Other Pipes and Valves Pumping Stations Associated Other Pipes and Valves Pumping Stations Manholes Tunnels	Pipes and Valves Pumping Stations Manholes Tunnels Other Pump Repairs Equipment: Treatment Associated Other Pipes and Valves Pumping Stations Manholes Tunnels Other Pump Repairs Equipment: Treatment Associated Other Pipes and Valves Pumping Stations Equipment: Treatment Associated Other Pipes and Valves Pumping Stations Manholes Tunnels Other Pipes and Valves Pumping Stations Manholes Tunnels	Pipes and Valves Pumping Stations Manholes Tunnels Other Pump Kephins Equipment: Treatment Associated Other Pipes and Valves Pumping Stations Manholes Tunnels Other Pump Kephins Equipment: Treatment Associated Other Pipes and Valves Pumping Stations Associated Other Pipes and Valves Pumping Stations Manholes Tunnels Other Pipes and Valves Pumping Stations Manholes Tunnels




			Cost	s (\$00	00)	
FACIL. IDENT.	WORK DESCRIPTION	1986	1987	1988	1989	1920
Plant Bldg.	Equipment: Treatment					
No. 654	Associated					100
	Other					
Distrib. Sys.	Pipes and Valves		500.00			
From:	Pumping Stations	* 100				
To:	Manholes	1./				Assessment of the second
Above Grnd.	Tunnels	,				
Below Grnd.	Other Pump Repairs	. 21		No. of the state of	3000.00	Property of
		7.				
Plant Bldg.	Equipment: Treatment					
No. 655	Associated					
	Other	4 .				
Distrib. Sys.	Pipes and Valves			600,00		
From:	Pumping Stations					
To:	Manholes					
Above Grnd.	Tunnels		4377			
Below Grnd.	Other Pump Resains		6000,00	3000.00	300000	3000.00
Plant Bldg.	Equipment: Treatment					
No. <u>660</u>	Associated					
Contaminated	Other					
Distails Com:	Division and Walters					
Distrib. Sys.	Pipes and Valves		200,00			
From:	Pumping Stations Manholes					
Above Grnd.	Tunnels					10 PG - NO-11
Below Grnd.				1500,00		
below Gilla.	Other Pump Repaires			1500,00		



			Cost	s (\$00	0)	
FACIL. IDENT.	WORK DESCRIPTION	1986	1957	1988	1959	1990
Plant Bldg.	Equipment: Treatment					
No. (6/	Associated	Secretary Property				is west
	Other		A Comment			
Distrib. Sys.	Pipes and Valves				50000	
From:	Pumping Stations	us i	A PARTY			
To:	Manholes					
Above Grnd.	Tunnels	, ,	ala esta	1000		
Below Grnd.	Other Pump Repaires	1 25		1500,00		
Plant Bldg.	Equipment: Treatment	1.	1			
No. 662	Associated		1			
	Other	4	107 7	7 7		
Distrib Sug	Divos and Values		- Secretary			/
Distrib. Sys.	Pipes and Valves					600,00
From:	Pumping Stations Manholes					
Above Grnd.	Tunnels					
Below Grnd.	Other Pump Repairs	•		1500.00	-	
Plant Bldg.						
No. <u>LCH-4007</u>	Equipment: Treatment Associated					
No. <u>CCH.4007</u>						
	Other Aux Eng		400000			
Distrib. Sys.	Pipes and Valves					500.00
From:	Pumping Stations					
To:	Manholes	day of the board				
Above Grnd.	Tunnels					The second
Below Grnd.	Other Pump Repaires				6000,00	



			Cost	s (\$00	0)	1 2 2
FACIL. IDENT.	WORK DESCRIPTION	1986	1957	1958	1989	1920
Plant Bldg.	Equipment: Treatment					
No. LCH-4009	Associated			C. 6. 14.		
	Other		A PROPERTY.	191+1012(HSU)		
Distrib. Sys.	Pipes and Valves			500.00		
From:	Pumping Stations					
To:	Manholes		199-9-			Signature State of the State of
Above Grnd.	Tunnels	, ,				
Below Grnd.	Other Pump Repaires	, ,,,	40000		400.00	
Plant Bldg.	Equipment: Treatment					
No. 5/8L	Associated	and the state of				
	Other					
	Cther					
Distrib. Sys.	Pipes and Valves					100.00
From:	Pumping Stations					
To:	Manholes					
Above Grnd.	Tunnels					and the state of the state of
Below Grnd.	Other Pump Repaires			400.00		400,00
Plant Bldg.	Equipment: Treatment					
No. 607	Associated					
	Other		de e e e			
Distrib. Sys.	Pipes and Valves					100
From:	Pumping Stations					100.00
To:	Manholes					
Above Grnd.	Tunnels					No. 100
Below Grnd.				4/00 00		600.00
Below Grna.	Other Pump Repaires			400.00		600.0




		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1986	1987	1988	1989	1924		
Plant Bldg.	Equipment: Treatment							
No. 643	Associated		100	200 1000				
	Other							
Distrib. Sys.	Pipes and Valves	` ·-	400.00			100.00		
From:	Pumping Stations	To Capital						
To:	Manholes	1						
Above Grnd.	Tunnels	,						
Below Grnd.	Other Pump Repaires	1 25			50000			
Plant Bldg.	Equipment: Treatment	15.						
No. 644	Associated							
	Other	4.						
Distrib. Sys.	Pipes and Valves			400.00				
From:	Pumping Stations							
To:	Manholes							
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires				5000,00			
Plant Bldg.	Equipment: Treatment				400.00			
No. 645	Associated	E PER MILLER			700.00			
	Other							
Distrib. Sys.	Pipes and Valves		300,00					
From:	Pumping Stations		300,00					
To:	Manholes							
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires				50000			


to be a second or	die de la lace	t de la		4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	

	WORK DESCRIPTION	Costs (\$000)						
FACIL. IDENT.		1956	1987	1988	1989	1920		
Plant Bldg.	Equipment: Treatment							
No. 646	Associated							
	Other							
Distrib. Sys.	Pipes and Valves			200.00				
From:	Pumping Stations	38 8 3 3		200.00				
To:	Manholes							
Above Grnd.	Tunnels	, ,		Address to the				
Below Grnd.	Other Pump Repairs	.1	500000			***		
51 . 511				ı ı				
Plant Bldg.	Equipment: Treatment	- ; ;						
No. 647	Associated	Р.						
	Other							
Distrib. Sys.	Pipes and Valves				300.00			
From:	Pumping Stations	<u> </u>			300.0	100		
To:	Manholes					a de como de		
Above Grnd.	Tunnels			4.10	Charles S. C.	1.4.		
Below Grnd.	Other Puna Repaires	and the same		5000,00				
					No.			
Plant Bldg.	Equipment: Treatment							
No. 648	Associated							
	Other		0.181.04					
Distrib. Sys.	Pipes and Valves					200,00		
From:	Pumping Stations			75.3				
To:	Manholes							
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires			5000,00				

REAL PROPERTY FACILITIES MANUAL




		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1986	1987	1988	1989	1920		
Plant Bldg.	Equipment: Treatment							
No. 649	Associated					Maria was		
	Other	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				11 -12		
Distrib. Sys.	Pipes and Valves		400.00					
From:	Pumping Stations			and the second				
To:	Manholes							
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires	, 1 25		5000,00				
Plant Bldg.	Equipment: Treatment							
No. 650	Associated							
	Other	4.						
			A. A. A.					
Distrib. Sys.	Pipes and Valves		Same and	500.00				
From:	Pumping Stations							
To:	Manholes							
Above Grnd.	Tunnels				ay a di	All marin		
Below Grnd.	Other Pump Repaires					60000		
Plant Bldg.	Equipment: Treatment					Tal. No.		
No.	Associated					16.		
	Other					10 c 41		
Distrib. Sys.	Pipes and Valves							
From:	Pumping Stations							
To:	Manholes							
Above Grnd.	Tunnels							
Below Grnd.	Other							




		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1956	1957	19.88	19.89	1990		
Plant Bldg.	Equipment: Treatment							
No. TT-23	Associated							
CONTAMINATED	Other							
Distrib. Sys.	Pipes and Valves							
From:	Pumping Stations							
To:	Manholes	*11						
Above Grnd.	Tunnels	• ;						
Below Grnd.	Other Pump Repaires	2 as	2000.00			·		
Plant Bldg.	Equipment: Treatment	1						
No. TT-25	Associated	. B.						
	Other	4 .		ALC: HE TOTAL				
Distrib. Sys.	Pipes and Valves			500,00				
From:	Pumping Stations							
To:	Manholes							
Above Grnd.	Tunnels							
Below Grnd.	Other Pamp Repaires				3000.00			
		•						
Plant Bldg.	Equipment: Treatment							
No. 77-26	Associated							
contaminated	Other							
Distrib Suc:	Pipes and Valves				400.00			
Distrib. Sys.	Pumping Stations				70000			
From:	Manholes							
To:Above Grnd.								
	Tunnels		4					
Below Grnd.	Other Punys Repuis		2000,00					




		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1986	1987	1988	1989	1920		
Plant Bldg.	Equipment: Treatment							
No. 77.52	Associated							
	Other					44		
Distrib. Sys.	Pipes and Valves	1.						
From:	Pumping Stations		\$5 (100 B) (100 B)	1000.00				
To:	Manholes	- 1	3 C					
Above Grnd.	Tunnels	,						
Below Grnd.	Other Pump Kepains	. 25		6000,00				
			11000					
Plant Bldg.	Equipment: Treatment	1,	10000000000000000000000000000000000000			:		
No. 77-54	Associated	n						
	Other Aux Engine Nephin		500,00					
Distrib. Sys.	Pipes and Valves		9.36		500.00			
From:	Pumping Stations				50000			
To:	Manholes		12 Sept. 100					
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires.			600,00				
D1 - 1 D12				30 10 10 1				
Plant Bldg.	Equipment: Treatment					til skaled		
No. TT-67	Associated							
	Other							
Distrib. Sys.	Pipes and Valves		400.00					
From:	Pumping Stations		700,00					
To:	Manholes		A Children					
Above Grnd.	Tunnels				100 100			
Below Grnd.	Other Pump Repnies		400.00		400,00			




	WORK DESCRIPTION	Costs (\$000)						
FACIL. IDENT.		1986	1952	1988	1989	1994		
Plant Bldg.	Equipment: Treatment							
No. Te-100	Associated			345				
ABANDON	Other			gage d		16 10 15		
Distrib. Sys.	Pipes and Valves							
From:	Pumping Stations							
To:	Manholes		A Section of	12 May 12 13				
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires	1 25	1	· · · · · · · · · · · · · · · · · · ·		1		
Plant Bldg.	Equipment: Treatment	- 1	1					
	Associated							
No. <u>TC-104</u>								
	Other		/					
Distrib. Sys.	Pipes and Valves			1000,00				
From:	Pumping Stations							
To:	Manholes							
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repairs		6000,00	4 1 90				
Plant Bldg.	Equipment: Treatment							
No. TC-190	Associated							
	Other		F 45.90	34-1				
Distrib Suc	Dinos and Values							
Distrib. Sys.	Pipes and Valves		() () () () () () () () () ()	1000.00		100.00		
From:	Pumping Stations							
	Manholes				4			
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repair			4000.00				




		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1986	1987	1988	19.89	1924		
Plant Bldg.	Equipment: Treatment		5.5	The state of the		1.1		
No. TC-191	Associated							
	Other		1 1 1			- 100		
Distrib. Sys.	Pipes and Valves			1000,00		400.00		
From:	Pumping Stations		4.1	100-10-				
To:	Manholes	9/18/20						
Above Grnd.	Tunnels	,						
Below Grnd.	Other Pump Repaires		1877	4000.00				
		200 300				44		
Plant Bldg.	Equipment: Treatment				A 37 37 18 17			
No. TC-201	Associated	- B						
Honodon	Other		-		100			
Distrib. Sys.	Pipes and Valves				Tu. 1			
From:	Pumping Stations							
To:	Manholes			1 To 1				
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires							
Plant Bldg.	Equipment: Treatment		The state of the s	1				
No. TC 325	Associated							
	Other							
Distrib Suc	Dines and Values							
Distrib. Sys.	Pipes and Valves			1000.00				
From:	Pumping Stations Manholes							
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires							
Below Gilla.	OCHEL FUMP REPRINS		6000,00		110-25			




		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1956	1987	1988	1989	1920		
Plant Bldg.	Equipment: Treatment							
No. 70-502	Associated							
	Other							
Distrib. Sys.	Pipes and Valves			1000,00				
From:	Pumping Stations		1					
To:	Manholes	* 111						
Above Grnd.	Tunnels				A TOTAL CONT.	ar at 10.1		
Below Grnd.	Other Pump Repaires	.1 .1		6000.00		·		
Dlant Dlda	I Boulement - Treatment			T	1			
Plant Bldg. No. Tesoy	Equipment: Treatment					10 To		
	Associated	1.		1				
	Other	1:						
Distrib. Sys.	Pipes and Valves		100,00		1000.00	1		
From:	Pumping Stations		700.00		200, 20			
To:	Manholes					and the second		
Above Grnd.	Tunnels		- P					
Below Grnd.	Other Pump Repaires	•			6000,00			
					- 180 marin 19	49.0		
Plant Bldg:	Equipment: Treatment							
No. TC-600	Associated							
	Other		10000			Lepia		
Distrib Cos	Dinas and Walana					110		
Distrib. Sys.	Pipes and Valves		100.10	100		400,00		
From:	Pumping Stations			- Company Same				
Above Grnd.	Manholes							
	Tunnels							
Below Grnd.	Other Pump Repaires		1004 7 10			4000.00		




			Cost	s (\$00	0)	
FACIL. IDENT.	WORK DESCRIPTION	1984	1987	1988	1959	1920
Plant Bldg.	Equipment: Treatment					
No. TC-604	Associated					
	Other			8 / 685	a Santa	
Distrib. Sys.	Pipes and Valves		500.00			
From:	Pumping Stations		20010			
To:	Manholes				15-	
Above Grnd.	Tunnels	, ,				
Below Grnd.	Other Puny Readires				6000.00	
Plant Bldg.	Equipment: Treatment	· ,	Fig. Later Sec.			
No. <u>TC.700</u>	Associated	1				
	Other					
Distrib. Sys.	Pipes and Valves	1000.00				
From:	Pumping Stations		L. L.			
To:	Manholes					
Above Grnd.	Tunnels					
Below Grnd.	Other Pump Repaires	6000.00	1			
Dlant Dlda	I need and in the second					
Plant Bldg.	Equipment: Treatment					1 m - 4 m
No. TC-901	Associated					
ABHINDOPED	Other					
Distrib. Sys.	Pipes and Valves					
From:	Pumping Stations					
To:	Manholes	200				Mar to 1
Above Grnd.	Tunnels		84 m			
Below Grnd.	Other Pump Repairs					




		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1986			1989	11996		
Plant Bldg.	Equipment: Treatment							
No. TC-1000	Associated							
	Other				1 - 11	110		
Distrib. Sys.	Pipes and Valves		600.00					
From:	Pumping Stations							
To:	Manholes							
Above Grnd.	Tunnels	· · · · · · · · · · · · · · · · · · ·		10.00		a territory		
Below Grnd.	Other Pump Repaire	1 28		3000.00		2000:00		
Dlant Dldg								
Plant Bldg.	Equipment: Treatment							
No. TC-1001	Associated	P.						
	Other	• • • • • • • • • • • • • • • • • • • •						
Distrib. Sys.	Pipes and Valves							
From:	Pumping Stations		1000.00					
To:	Manholes	•				Six and Andrew		
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires		600000					
						11.00		
Plant Bldg.	Equipment: Treatment							
No. TC-1251	Associated					de de de		
	Other					11 . 140		
Distrib. Sys.	Pipes and Valves			10				
From:	Pumping Stations			50000				
To:	Manholes							
Above Grnd.	Tunnels							
Below Grnd.			30.5 THE			100 - 1 1		
octow office.	Other Pump Repaires			8.50	4000.00	19		




		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1986	1987	1988	1989	1994		
Plant Bldg.	Equipment: Treatment				0.00			
No. Te-1253	Associated		The same of					
	Other							
Distrib. Sys.	Pipes and Valves	*		100		600.00		
From:	Pumping Stations							
To:	Manholes				2007			
Above Grnd.	Tunnels			1 1 1 1 1 1 1				
Below Grnd.	Other Pump Repairs	.1 .1			4000,00	i.		
Plant Bldg.	Equipment: Treatment	15.	T T					
No. TC-1254	Associated				State Service	make in the		
	Other							
Distrib. Sys.	Pipes and Valves				600,00			
From:	Pumping Stations	-18 4 % B		a de la composition della comp				
To:	Manholes	Physical de Asserta			district A	STATE AND ST		
Above Grnd.	Tunnels					Section of the section		
Below Grnd.	Other Pump Repaires		4	4000,00				
Plant Bldg.	Equipment: Treatment					and professor		
No. 70-1255	Associated							
	Other							
			Bull Co.			14.201.77		
Distrib. Sys:	Pipes and Valves		1000,00			500.00		
From:	Pumping Stations	29						
To:	Manholes			50-5				
Above Grnd.	Tunnels	A STATE OF THE STA		alai (t.)				
Below Grnd.	Other Pump Repairs		6000,00			图 图 图		




		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1984	1987	1988	1919	1990		
Plant Bldg.	Equipment: Treatment							
No. TC-1256	Associated					1.		
	Other							
Distrib. Sys.	Pipes and Valves	· .			700.00			
From:	Pumping Stations		2.50		100.00			
To:	Manholes					31-31-21		
Above Grnd.	Tunnels	, ,			Maria de A	W 147.0		
Below Grnd.	Other Pump Repaires			4000.2				
Plant Bldg.	Equipment: Massiment							
	Equipment: Treatment Associated					400		
No. AS/06	Other	P						
	Other	1:.						
Distrib. Sys.	Pipes and Valves					1000,00		
From:	Pumping Stations							
To:	Manholes							
Above Grnd.	Tunnels .	was a second						
Below Grnd.	Other Punp Repaires					600000		
Plant Bldg.	Equipment: Treatment				_			
No. AS-131	Associated		# Spade	4.0				
	Other							
Distrib. Sys.	Pipes and Valves							
From:	Pumping Stations				50000			
To:	Manholes							
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires		8.8. 32.75		4000.00			
	The state of the s				1000.00			



		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1956	1987	1988	1989	1990		
Plant Bldg.	Equipment: Treatment					10.00		
No. AS-203	Associated			100	8			
	Other			1.				
Distrib. Sys.	Pipes and Valves							
From:	Pumping Stations				1000.40			
To:	Manholes	- 1	· ·					
Above Grnd.	Tunnels	1 ,						
Below Grnd.								
below Gina.	Other Pump Repairs	1 21	4000.00	/		- 1		
Plant Bldg.	Equipment: Treatment		T					
No. AS 4140	Associated					1 3 3		
	Other							
Distrib. Sys.	Pipes and Valves		1000,00					
From:	Pumping Stations							
To:	Manholes				to the second			
Above Grnd.	Tunnels		J. 42					
Below Grnd.	Other Pamp Ropaires		6000.00					
Plant Bldg.	Equipment: Treatment	-						
No. 195-4150	Associated							
contrainated	Other							
Distrib. Sys.	Pipes and Valves							
From:	Pumping Stations							
To:	Manholes	A LONG ALL						
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repaires		500.00	Vana -				




			Cost	s (\$00	00)	44 478
FACIL. IDENT.	WORK DESCRIPTION	1984	19.87	1915	1959	1990
Plant Bldg.	Equipment: Treatment					
No. 45-5001	Associated					
	Other		and the second			
Distrib. Sys.	Pipes and Valves					600,0
From:	Pumping Stations					
To:	Manholes					
Above Grnd.	Tunnels		5 20			1 1 1 1
Below Grnd.	Other Pump Repaires	, 1		60000		
Dlast Dida						
Plant Bldg.	Equipment: Treatment		10.00			
No. 45-5009	Associated	- 1				
	Other	1.	-			
Distrib. Sys.	Pipes and Valves		400,00			
From:	Pumping Stations					
To:	Manholes					
Above Grnd.	Tunnels					
Below Grnd.	Other PUMP REPAIRS			eng Politic	600000	\$ 47 A.
Plant Bldg.	Equipment: Treatment					
No.	Associated					
44.75	Other		- 10 TeV			
Distrib. Sys.	Pipes and Valves					
From:	Pumping Stations		191 103			10 10 10
To:	Manholes					
Above Grnd.	Tunnels					
Below Grnd.	Other					




REAL PROPERTY FACILITIES MANUAL


		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1956	1957	1988	1959	199		
Plant Bldg.	Equipment: Treatment				Color St. C.			
No. AR-45	Associated							
	Other							
Distrib. Sys.	Pipes and Valves			600,00		12		
From:	Pumping Stations					alle 194 may ,		
To:	Manholes	-1						
Above Grnd.	Tunnels	,						
Below Grnd.	Other Pump Repaires	.1 21	500.00		6000.00			
Plant Bldg.	Equipment: Treatment							
No. RR-47	Associated		-			1.0		
No	Other	4.						
		• •		,				
Distrib. Sys.	Pipes and Valves			600,00				
From:	Pumping Stations							
To:	Manholes							
Above Grnd.	Tunnels			4		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Below Grnd.	Other Puny Repaires		6000.00		600,00			
Plant Bldg.	Equipment: Treatment							
No. RR.97	Associated							
	Other							
Distrib. Sys:	Pipes and Valves			500.00				
From:	Pumping Stations			300,00				
To:	Manholes							
Above Grnd.	Tunnels					3 - 4 - 7 - 8 -		
Below Grnd.	Other Pump Repaires		400.00			6000,00		




			Cost	s (\$00	00)	
FACIL. IDENT.	WORK DESCRIPTION	1986	1952	1988	1989	1990
Plant Bldg.	Equipment: Treatment					
No. RR-229	Associated					
	Other					
Distrib. Sys.	Pipes and Valves				100.00	
From:	Pumping Stations				700.0	
To:	Manholes	* * * * * * * * * * * * * * * * * * *				
Above Grnd.	Tunnels	9-1-1				
Below Grnd.	Other Pump Repaires	4 48		500,00		4000,00
Dlamb Dlam						AND SAFE IS
Plant Bldg.	Equipment: Treatment	, ``				
No. <u>BB-44</u>	Associated	14				
	Other					
Distrib. Sys.	Pipes and Valves				600,00	
From:	Pumping Stations		1000		600,00	4
To:	Manholes					
Above Grnd.	Tunnels					
Below Grnd.	Other Pump Repaires		6000.00	-11-15 Sec. 17-15	Control of the	500,00
Plant Bldg.	Equipment: Treatment					
No. 88-220	Associated		-			
	Other					and the second
Distrib Sus:	Dinos and Values		2			
Distrib. Sys.	Pipes and Valves		200.00			
From:	Pumping Stations					
Above Grnd.	Manholes					
	Tunnels	100 to	F 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Below Grnd.	Other			500,00	2 1	300000



			Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1984	1987	1988	1989	1990			
Plant Bldg.	Equipment: Treatment								
No. 33-221	Associated	Control Paris							
	Other	1 e 1 m				4 1,4			
Distrib. Sys.	Pipes and Valves		100.00						
From:	Pumping Stations	animum in the little of the			Salar Alice				
To:	Manholes	1.7							
Above Grnd.	Tunnels	,							
Below Grnd.	Other Pump Repairs	, in		500,00		3000,0			
Plant Bldg.	Equipment: Treatment	- 1	1	T					
No. A-5	Associated								
	Other	-							
	·	<u> </u>							
Distrib. Sys.	Pipes and Valves								
From:	Pumping Stations	10 A 1.78 C.			The Market Server				
To:	Manholes			and the state					
Above Grnd.	Tunnels								
Below Grnd.	Other Pump Repaires		400.00	of the	500,00	600.00			
Plant Bldg.	Equipment: Treatment								
No. New BB-43	Associated								
	Other								
Distrib. Sys.	Pipes and Valves								
From:	Pumping Stations								
To:	Manholes								
Above Grnd.	Tunnels								
Below Grnd.	Other Pump Repaires					4			
DOLOW OLING.	COLOR THING KEDNINS	The second		400,00		400,00			



		Costs (\$000)						
FACIL. IDENT.	WORK DESCRIPTION	1984	1987	1988	1937	1920		
Plant Bldg.	Equipment: Treatment							
No. New well	Associated							
NO #	Other							
Distrib. Sys.	Pipes and Valves	· ·.				40000		
From:	Pumping Stations					10-		
To:	Manholes	*./				The state of the		
Above Grnd.	Tunnels	, ,						
Below Grnd.	Other Pump Repaires	, 1	200,00	400,00	400.00			
Plant Bldg.	Equipment: Treatment	- 1						
No. <u>BA-164</u>	Associated	P.						
	Other							
Distrib. Sys.	Pipes and Valves				500.00			
From:	Pumping Stations							
To:	Manholes							
Above Grnd.	Tunnels							
Below Grnd.	Other Pump Repairs		400.00		6000,00	200.00		
Plant Bldg.	Equipment: Treatment		-					
No. BA-190	Associated							
	Other							
Distrib. Sys.	Pipes and Valves			5.00.00				
From:	Pumping Stations							
To:	Manholes							
Above Grnd.	Tunnels	Aller Discounting						
Below Grnd.	Other Puna Repnies		400,00		6000.00			



LONG RANGE MAINTENANCE PLAN WATER TREATMENT