

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4459	Comp	207	Install phase-motoring relay for York A/C compressor
3234	Comp	558	Assist fire dept to test / flush sprinkler (10) bldgs
0177	4-27-79	230	Replc (6) steam traps on new cage
5036	2-27-81	1185	Replace Controls Compressor
4842	10-7-80		Assist Fire dept. to test + flush sprinkler system
✓ 0102	12-14-84	215	Dig Trench & Backfill
✓ 12355	5-24-85	5263	Remove dumpster cans from Behind Burger King
✓ 3390	6-8-84	2922	Change Leaking Shaft Seal on Compressor
✓ 4637	Comp	672	Repa. Packing Area in Vicinity of 1220, 1200 & 1300
✓ 5293	4-20-84	427	RPA of Rpl the steam Meter - Hot Water coil
✓ 6078	3-28-86	8447	INSTALL Drop-INLET & R/R TO DRAW LIQUID
3292	8-21-87	4047	Rem & Replace steam meter at Bldg. 1220.
3282	10-2-87	2797	Relo & Remove Water Meter at Bldg. 1220.
2058	7-22-88	1094	Replace compactor Power Unit next to Burger King
3077	—	10,161	Replace cooling Tower for A/C system, old unit
3508		2605	is rusted out.
3508	12-7-90	2605	Repl sheetrock ceiling.
3671	7-1-91	1287	PROCURE SERV CONTRACT TO PERFORM TUBE ANALYSIS
3860	11-22-91	7201	ASSIST CONTRACTOR REBUILDING YORK CHILLER
3671	7-1-91	5502	RPR CHILLER
3859	10-11-91	31566	PROCURE A SERV CONTRACT.
4851	3-15-94	3124	Replace A/C compressor + Air Drier
3017	11-25-94	3536	REM OLD CONTROL VALVE Pledged 9/14/94 dta
EBLO	4-6-01	3137.20	#01-4513
EBLO	5/3/02	6244	Install Double Door 02-122121

