Grease Rack

BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
S-1616					

JOB ORDER NO or Contract No.	DATE COMPLETED	COST	DESCRIPTION
4170	10-31-73	709	CLEAN UP OIL SPILLS

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION