BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
1808					

JOB ORDER NO	DATE ~~COMPLETED~~ signed	COST	DESCRIPTION
023-03460-82	5/28/63		Renovate
NB4=05371-220510	4/13/64	$92.61	Install 60A switch (safety) and connect machine shop trailers (2)
3441	7-2575	3716	Repair to Butler Bldg
5709	10-22-76	9E	Replace steam drain rear of Bldg
5709	8/18/76	/	Rpl steam drain rear of Bldg
4106	3-1277	6530	Rewire bldg. as per insp -
4815	1-25-78	1508	Maint Fabricate and install door rafters do repair work and paint
2107	4-21-80	448	Rpl Underg'd oil tank (used oil)
3048	Comp	1246	Make repairs to east of metal bldg.
4409	Comp	3529	Rpr. large drainage ditch
4764	10-2384	1517	Clean out and pump out water and oil -
3339	10-2684	2,706	Replace yard hydrants Rep safety Rails
4268	2-1-85	1147	

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION

BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
1810					MCBCL 11011/3

JOB ORDER NO	DATE ~~COMPLETED~~ signed	COST	DESCRIPTION
NB4-04373-22	4/29/63	225.24	Renovate
2718	3-8-73	349	Hook up planner, dewalt saw + table saw
1091	10-30-72	114	Inst exhaust fan
2884	9-17-76	1050	Install elect circuits for equip
5552	7/18/76	339	Make repairs to sliding metal doors
3371	10/18/76	986	Rpr ext doors + siding
4512	2-27-78	3743	Self-Help do repair work and paint
3439	8-28-80	138	Make criterion rpr to metal bldg
3226	5-20-83	1658	Rpr. Ext. walls Rpl + Repl window units
2075	3-1-83	581	Clean oil Spill
3339		2306	Rpl Frost Proof yard Hydrants, Pneumatic Tank level Gauges
4268	2-1-88	1143	Rpl two freeze yard Hydrants at the vehicle wash Platform
4764	10-25-84	1517	clean out, Pump the excess water out + Pump out the Excess oil
4606	4-7-95	9359	Rprs to steel Siding
4606	4-7-95	647	1st Amendment
4606	4-7-95	2240	2nd Amend
4088	8-22-97	6192	Self Help / Purged 9-19-01
4338	2-2-01	8817	# 01-142221

Purged 4/19/99 GL

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION