

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
0102	1-7-83	593	Cut greenery for season
3458	1-21-83	338	Rpr elect ceiling & wall damaged
0113	9-24-82	1488	connect new oven
1204	10-26-82	1382	construct handicap Ramp
3420	10-1-82	3434	Rplc service Intracon main
4843	2-11-83	8422	Scrape, Clean & Paint gallery area 2 coats
4213	12-1-82	2519	Rig & install Rpr parts on Boiler
1066	4-15-83	831	install connect new exhaust fan
4013	10-29-82	1881	Rig/Install chemical Pump
5008	9-23-83	350	PROCURE ROTATING ASSEMBLY FOR FEED WATER PUMP
3393	12-29-83	5663	PROCURE PORTS FOR BLOW DOWN VALVES
5982	3-11-83	5193	MAINT
3065	10-24-86	782	Appl Lights in Kitchen Area
4352	9-26-86	4312	Rpr. + Paint
1025	2-20-87	17044 (Dm)	MAKE Modif. to wall
3101	1-16-87	6165	Open windows, replace ceiling tile, etc
0102	3-30-84	5823	Renovate for Pizza Express
0100	12-7-84	6937	Renovate Hall and Lounge
0101	10-26-84	3247	Renovation in "Regimental Room"
3598	6-8-84	2746	Repairs to ceiling and floor in mens dressing Room, china Storage and Hallway areas
5259	2-17-84	1287	Remove and Replace Condensate Pump and Reservoir in Steam Pit
4129	2-8-84	4240	Plaster repairs and Paint
3863	8-8-84	1717	Procure Repair Parts for a boiler Feedwater Pumps -
3841	9-14-84	639	Repairs to Reprotery on Boiler # 10
4842	11-9-84	666	Repair water Damaged Plaster -
6095	4-17-87	2304	Repl feeder to 200A Panel.
3852	7-11-86	572	Repl Key & Bush Lock.

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
2027	11-30-90	861	Fabricate 8 Straight flange holders.
8047	7-22-91	1927	CONST OF ACS IN HTG PLANT
3662	12-13-91	1625	INSTALL 1338 SF FLOOR TILE
3876	10-2-91	28506	PROCURE SERV CONTRACT
4053	4-24-92	1072	REMOVE/RPLC KILOWATT HR METER
4032	5-15-92	3816	RPMV HOT WATER COILS
4128	5-8-92	1287	INSTALL 8 EACH SALT TREATED JOIST UNDER FLOOR OF UJ Furnace Room
4711	9-3-93	438	PROCURE BACK FLOW PREVENTION
4867	9-16-94	5111	RPLC STEAM COIL
3105	6-17-94	1124	REPLACE WALL PANELING
2128	5-27-94	513	RPLC Meter Electric
3124	8-2-94	8318	RPLC ceiling Tiles
3124	8-2-94	2301	1ST Amend ment
3230	010695	7211	RPL Floor in Lejune Room It Purged 4/19/99
3349	021095	2128	Relocate VALVE It Purged 4/19/99
3381	022495	2290	Rplc 6 motors on ventilation sys
3381	022495	590	1st amend
3385	11-15-96	2566	Rplc guns on cooling tower
3500	2-9-96	1140	Rpl Roof leaks JWC PURGED 99
3623	1-12-96	860	Rpl Drain line JWC PURGED 99
3957		577	INST CIRCUIT
1001	8-8-97	736	INST HOT WATER LINE JWC PURGED 99
4362	3-13-98	11466	REPAIR WATER DAM 90 9-10-02 purged PC
4390	11/20/98	4113	INSTALL Boiler Door 9-10-02 purged PC
CLMI	5/11/02	6690.	paint bldg. PV # 02-134092
A371	5/3/02	6690.00	pressure wash PV # 02-104905