OB ORDER NO	DATE COMPLETED	соѕт	DESCRIPTION
	8-1-73	53	repl door alass
1733	9.30.7	53/	repl. Jan wheels on cooling tower
4724	11-30-79	594	306. 12 return air gully (A)
3849	1		
3266	11-4-88	935	Rel wendow latches return sin gulleria disete.
3394	12-15-80	3774	Rel Ceramie base & ceramie Spor tile
3704	2-6-81	1344	Rpis on resterior dans
447/	9-18-81	515	Rol. broken weter Jountain
3886	8880	1262	Ran A/R
3849	8-15-80	996	Rel lail fin hat water tank
3465	12-18-81	2893	Repair A/c compressor
3073	2-17-84	1138	Repuil + steam traps
E823	Compl	5524	Cáclic maint 12-18-85
3544	Compl	343	Dewinterize A/C Syst 4-23-84
3670	Compl	6192/	Rur Leaks + Annual Maint on 1/8 2-21-84
3237	1-12-90	8215	KEPI Sumo Pumps
4305	8-11-86	10822	TEEPI LIGHTS & Ceiting THEY OUT THE
3099	12-1490	480 -	Turn on steam/heat Deleted 9/24/83
3260	2-22-91	2752	MISC STRUCT, ELECT & PRINT RORS

OB ORDER NO	COMPLETED	соѕт	DESCRIPTION
12 110 2 1 3 1	10.40.00		