BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
633					MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
3669	1-13-73	2932	Replace well pumps
4306	6-21-73	405	Repr " "
4044	8/28/75	1089	Rpl deep well pump.
4452	2/9/76	522	Rpl cement in ditch
3949	2-24-77		Repair erosion at Well House 633

TC650

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
1105	4-23-81	1805	Construct training platform
1105	3-2-81	138	amendment to above
3556	2-10-84	1614	Interior & exterior repairs
~~3255~~		1420	~~RFR Boiler Tubes~~