

BLDG NO TC-1064	INT. PAINT SQ FT 7500 sf	EXT. PAINT SQ FT 600 sf 36 windows	ROOF SQ FT 4917 sf	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
--------------------	-----------------------------	---------------------------------------	-----------------------	----------------------	--

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
Addend NB4-04817-22	5/22/64	1086.00	Insulate new steam line
NB4-04817-22	11/27/63	E 2457	Renovate
Contract	3/31/70		Renovate mechanical system
4037	12-1-70	2609	Plent Vent
316	2-1-69	1992	Misc repairs door roof siding & paint
CMONH-157	7-27-67	74	Repair to fire extinguisher
3344	6-26-69	2312	Replace (2) shower stalls
3792	8/18/75	4292	Rm & paint ext
5319	8-28-78	791	Repair and Paint BOQ Rms 1079/01
4567	8-25-78	1544	Repair heating and hot water systems
4535	4-28-78	648	Repair ceiling and paint
80-2012	1981	600.	Ext. paint
80-C-2012	8-12-81	824.	" "
3251	11-21-79	7224	Repe Wdgs before contract party
3964	Comp	1577	Interior paint
3630	Comp	758	Interior paint
4856	9-19-80	1032	Paint interior
4228	12-5-80	2329	Replace hot water heater
3701	10-23-81	3374	Replace ceiling diffusers
3763	8-27-82	266	Paint
2149	8-6-82	3364	treat Wdgs for termites
4100	9-17-82	6863	Replace steam & condensate piping
3630	8-27-82	758	Interior paint
4051	8-15-82	1240	Paint 4 Rooms complete
3519	7-15-83	1822	Paint Boiler Rm
3970	12-3-82	4575	Repair head walls

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3513	7-8-83	3129	Replace screen doors
5130	5-18-84	462	Replace turbine ventilators
9935	1-15-86	15363	PERFORM RECOVERING CYCLIC MAINT
4646	3-14-86	1788	PAINT ROOMS COMPLETE INTERIOR
3369	11-08-91	3583	Fabricate vanities in shop & install them
3369	11-08-91	6905	RENOVATE ROOMS IN BER Removed
388			
3839	8-16-96	3969	RFRS To Exterior PURGED 99
3839	8-16-96	488	1ST AMD PURGED 99
81055	12/22/00	1, 011	Cyclic Maint.
81055			Cyclic Maint. 1st Amd.
EB60	9/7/01	1548	Cyclic maint 01-41013