

JOB ORDER NO	DATE COMPLETED <small>Signed</small>	COST	DESCRIPTION
138-62	7/12/61	815.52	Paint interior (C 2/2/62)
NB4-04824-22	12/5/63	1812.46	Repair termite damage (C 10/6/64)
2183	4-20-72	261	Replace shower stall cabinet unit
4085	12-17-70	493	Repair water heaters
3164	7-1-69	2064	More repair to doors, roof siding & paint
31310	10-31-68	257	Replace operator Valve Valve
3757	10-3-75	7597	Repair & paint
3848	1/25-77		Repair water lines
3235	10-27-78	359	Repair hole in ceiling and paint int complete one coat
4540	4-28-78	462	Repair ceiling and paint room C
80-2012	1981	600.	Ext. paint
80-C-2012	8-12-81	824.00	" "
3364	12-14-79	353	Paint interior Room 6
3085	9-26-79	483	Replc steam coil in heating unit
3957	11-21-79	7224	Repu bldg before contact pt. (6) bldg
3191	11-4-80	834	Paint ^{ems} 4-B, 5, 6
3550	5-25-80	1828	Replace baseboard, Floor tile & hall damaged by termites.
4840	9-3-80	674.	Paint rms 5, 6.
4806	8-29-80	1075	Replace Condensate Receiver
3883	Comp	13651	Replace screens in window
3701	10-23-81	3374	Replace ceiling diffusers
4310	9-16-83	538	Replace shower stall
3744	9-3-82	979	Replace steam coils
5085	10-7-83	1645	Interior paint
3145	4-30-82	768	Interior repairs
4187	8-17-83	376	

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4487	7-8-83	518	Interior paint
3366	10-2-84	5935	Repairs windows, doors, walls
3040	6-3-83	5645	Replace steam & condensate lines
4577	8-19-83	730	Amendment to 50.4577 White Bldg HTC 1065 add TC 1066 APT #5
3600	9-10-84	212	Paint APT #5
5116	Comp	968	Rplc Turbine Ventilators 9-15-83
4232	10-15-87	5519	Repl Shingle Roof
4625	8-13-84	855	INT PAINT
3420	3-25-91	10954	FAR A/C FRAMES & INSTALL, REMOVE/INSTALL COMMODES & SHOWERS
3839	8-16-96	3969	RPR EXTERIOR JWC PURGED '99
3922	4-18-97	4891	RPL HOT WATER STORAGE TANK JWC PURGED '99
81297	12/22/08	743	Cyclic Maint.
EBGØ		1208	Cyclic maint 01-41015
NRMS		3,568.	02-126381 CAMBAR (Remove Abrasives/Rpl w/ Glass Bld)