BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
M - 103					MCBCL 11011/3

JOB ORDER NO or Contract No.	DATE COMPLETED or signed	COST	DESCRIPTION
NB4-047922	10/30/63	7.	Repair windows, doors and paint 2 coats; paint exterior of building 2 coats
CONTRACT	C 7/28/65		~~Exterior painted~~
N62470-70-C-0492	12/15/70		Exterior paint
3203	10-13-72	886	Repair roof & paint new wood
3652	7/24/75	2962	general repairs
4626	6-9-78	809	Interior repairs and ~~paint~~ head 2 coats
4316	5-23-79	144	Identify & connect telephone system
4003	8-17-79	569	Replc steam coil in Hot water storage TNK
1011	11-2-79	2500	Procure contract for the purchase & charleston fema
3605	8-13-82	974	update Service to Bldg.
1333	6-18-82	654	Install air conditioners
1274	5-11-83	4154	install drop ceilings
3434	1-26-90	118410	Renovate office, head & storage areas.
3167	comp	12994	1 " ", Rewire heating sys. structural repr & repaint.
3115	12-14-90	83	Turn on Steam/Heat

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION