M - 116	INT SQ FT	EXT. PAI	INT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
JOB ORDER NO or :	DATE XCOMPLETEDX 07 signed	соѕт			DESCRIPTION	
NB4-04761-22	11/5/63	2601.29	Renovate ; pr	paint interior		
NB4-04760-22	11/5/63	106.78	Paint exterio			
N B40=04576 1b=22	12/13/63x				xx6ttx	
ONTRACT	C 7/28/65		Exterior pain	nted		
N62470-70-C-0492			Exterior pai			
45171	6-6-69	337	- 100		Chapelo	
2570	12-10-71	OE	Repair x	sign at		
3848	6-30-71	2029	Repair N	in damage	e	
2553	3-29-74	205	Dieat Ch	and don	termites.	
3244	620-75	133	Texaco	inqueate	in Dipl en Y	ruch Rm
3267	11-28-25	2930	Kepain	& Dount en	riside 2 Chape	0
33/5	103175	4827	Repair	& paints	ext o	
5487	6/28/16	263	place,	sollier	on wall fro	em grant torea
1240	7-13.77	1020	alteration	ma for Ori	thodor clapel	
Crent 18-302	19- Ky80	31657	Ext Par	nto		
1018	11-9-19	2060	enstal	(6) 230	volt A/C circuit	ts.
4691	829.79		Repla		in mens head	
3/97	10-24-80		Instal	Il new car		
1175	6-5-81	532	INSTALL (Z		ghts	
34/4	8-20-82	1/152	Replace &	Hot + cold W	ater lines to	- men's + Wamen'the
1270	7.23.83	F010815	anstal	Onever conf		
		1	0	Repried De		usor tile
	8-31-84	. 10	1 '0 '	0	2	Ola M-116 + Raid winds
3847	Compl.	3309	Fell tre	e in vicinit	y of 604 B. cut	Phto section
ARREST		\		to wood		
3422	11-16-87	2941	11-		Near Chapel.	

JOB ORDER NO	COMPLETED	COST	DESCRIPTION			
3250	6-13-86	1014	REMOVE & REPIANT SHRUBBERY.			
4357	4-19-85	354	REPIC. COST IRON RADIATOR, PER INSPECT.			
3526	4-16-91	193	Procure Services Contract to furnish of last window atoms			
4664	10-22-93	4866	Repair Pews + Flores			
4906	7-1-94	6330	DISMANTLE DUCT WORK			
4906	7-1-90	911	1ST AMENDMENT			
3266	4-21-95	3850	Replace LITES PURGED 98			
CLMS		7445	Install Kitchen Sink & cabinets 02-171546			
) ,						
	-					

.