L-108	DATE		
IOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3500	8/2/77	3418	Repairs and Paint water tank and supports - didg
337	11/29/69	238	Repair and paint exterior and Inter of water tan
3737	11/26/69	169	Additional time on 3737
		1×	
	F		

JOB ORDER NO	DATE COMPLETED	СОЗТ	DESCRIPTION
	++		
	+ +		
	+ +		
and the second			
	+		
	+		
	+ +		
	+ +		
	++		
	++		
<u>198 03955 20</u>			
in interaction of the second			
148		1	