BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
A5527					MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
1279	~~1299~~ 4/19/76	569	install electric power
5737	8/26/76	/	Rpr pump on tank
5743	8/26/76	/	Rpr electric valves
Cont.# N62470-78-C-3041	1-19-81	113,881.50	Rpl petroleum storage tanks
3967	3-2-83	132.	Repair broken water line
1124	3-25-83	622.	Install 1" waterline & Frostproof faucet

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION