

BLDG NO
A-2

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD
MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
023-03191-82	4/63	E 1792	Renovate
70-4080	12-12-69	0/E	Repair overhead crane
67-	8-5-66	363	Replace 140' z cast iron soil pipe
68	6/11/68	422	Replace condenser pump
68	3-1-68	137	Install deluge shower in battery rm
68	3-22-68	3671	Make repair
68	3-22-68	558	Repair & paint
69	8-30-68	5181	replace (5) Carrier M7D steam unit
71-3914	11-6-70	467	Repair overhead chain hoist
73-3828	10-2-72	2072	Replace 10 ton chain hoist
4-3347	9-14-73	548	Repair & paint door
4-1055	4-26-74	2406	Install additional 4d 7ae
4235	12-12-75	1994	Remove & replace 2 dispensing pumps
3427	8-16-74	2955	Repair misc throughout bldg & paint partial int
3426	8-16-74	3697	Paint ext complete
3579	6-28-74	6610	Repair ext
1085	12-6-77	1025	Construct a battery room with exhaust fan, battery deep sink
3337	11-18-77	358	Replace wiring / install new outlets
4274	3-21-78	544	Feb doors & paint
4566	4-19-78	332	Paint partitions of bldg - 1 coat
3428	6-8-79	600	Rpl unit heater in engine Bay
4049	5-30-80	921	Rpr drain lines
1001	8-21-81	845	Install skimmer in heat area
4211	1-15-81	3693	Make Repair prior to contract paint
1034	3-1982	351	install 2 window exhaust fans