BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4262	4-7-78	967	Rpr and Paint int/ext
3217	Comp	2207	Exterior and interior repairs
1183	9-25-81	1608	Install hot water heaters
3219	2-11-83	903	Perform Misc plumbing Repairs
1157	4-8-83	518	Install screen doors
3269	5-16-84	295	Repairs to inter. & epter.
3378	5-2-86	1290	Rpl & Refit Doors, Repl Hot water Heater Rec. Shower.
3906	4-10-84	3244	Dewinter - All The Rec. Bldg & Comsh Hot water closed
3185	5-22-87	586	MISC. REPAIRS TO BLDGS.
3039	8-19-94	1255	Repair Roof

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION