

(FIRE PROTECTION PROJECTS)


SUMMARY FOR CORRECTION OF FACILITY DEFICIENCIES
 VMC 10956 (8-74) SN 0000-00-00A-5360 U/I:PH (100 SHEETS PER PAD)

SUBMITTING ACTIVITY AND LOCATION
NAVY CORPS BASE, CAMP LEJEUNE, NORTH CAROLINA 28542

B. ACTIVITY CODE: **8270-175**
 C. UIC: **67001**
 D. AREA COMD. CODE: **05A**
 E. MC CODE: **R**
 F. COMPONENT NAME: _____
 G. BASED ON NAVAL TRADITIONAL: _____

CATEGORY CODE	PROJECT TITLE	ITEM ID NO.	S A	SCOPE		ESTIMATED COST (\$000)	EST. YEAR	YEAR		MOS.	C O D E	C O D E	S. P. U. SATISFIED		S P E C	C A T	PROJECT PLAN		I A N. L.	P R
				QUANTITY	U.M.			AUTH.	FUND				WITH	W/O			PROJ.	MASTER PLAN		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21
12-10	UPGRADE WATER MAIN, 200 AREA MONTFORD POINT	LE532R	DA		LS	99.2	85					CM			B		O&MMC			
10-60	SPRINKLER SYSTEM, BUILDING 2615	LE533R	KA		LS	116.9	85					CM			B		O&MMC			
24-11	SPRINKLER SYSTEM, BUILDING M-231	LE534R	FA		LS	80.1	85					CM			B		O&MMC			
24-11	SPRINKLER SYSTEM, <u>BLDG. BB-45</u>	LE535R	IA	1	LS	77.2	85					CM			B		O&MMC			
VARIOUS	EMERGENCY LIGHTING, VARIOUS BUILDINGS, BASEWIDE	LE536R	KA		LS	94.5	85					CM			B		O&MMC			
VARIOUS	EXIT & DIRECTIONAL SIGNS, VARIOUS BUILDINGS, BASEWIDE	LE537R	KA		LS	70.5	85					CM			B		O&MMC			

CLASSIFICATION



BLDG NO
BB-45

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD
MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED 2-2-72	COST	DESCRIPTION
H98- CM3 - ONK-108	12/8/67	487	Install deadlocks (41)
AA9-23-XX-11120	6/20/69	1,000	Renovation - Troop Ing
AA9-23-XX-30791	11/15/68	1,028	Replace built-up roof over lounge
AA9-23-XX-31631	3/21/69	84	Replace hot water radiator valves
AA9-23-XX-31860	5/30/69	412	Replace hot water coil
AA-1-23-4218-2314	2/2/71	139	Paint rooms 205 & 208 complete
AA-1-23-4219-2314	2/16/71	319	Paint interior & give rooms completed
AA-1-23-4293-23	2/28/71	83	Paint room 234 completed
AA-1-23-4338-23	3/10/71	407	Interior paint (5 rms)
AA-1-23-4408-2314	3/22/71	286	Interior paint
AA-1-23-4437-23V	3/29/71	352	Paint & plaster
AA-1-23-4463-23V	4/1/71	194	Paint & plaster
AA-1-23-4519-	4/19/71	859	Paint & plaster
AA-1-23-4594	5/3/71	112	Paint rm 243 & refinish floor
AA-1-23-4600	5/28/71	124	Paint & refinish floor rm 210
AA-1-23-4704	6/1/71	149	Repair plaster & paint
AA-1-23-3871	7/19/71	145	Repair plaster & paint
AA-1-23-3912-232	6/23/72	8,388	Repair to interior, exterior, & replace built up roof
AA-1-23-4029	8/19/71	126	Paint rm 110 complete, clean & refinish floor
AA-1-23-4409-23XX	12/6/71	125	minor plaster work & paint interior 3 rm 108
AA-1-23-4494	1/17/72	150	Repair plaster paint clean & refinish floor
4015	11-3-72	199	Paint peeling moulding
4916	4-13-73	166	Paint Rm 225, sand & refinish floor
4891	4-20-73	330	Repair venetian blinds
4691	3-15-73	134	Paint Rm 119 & sand floor
0262	5-3-74	195	Install (2) 220V outlets per A/C

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
5073	4-11-75	0/E	Repair 45 V-blends
0138	10/1/75	287	Install exhaust fan
5761	9-17-76	334	Leak @ shower stall cabinet
4764712	4-9-76	870	Remove & replace electric underground
5262	5/17/76	850	Replace five shower stalls
4720	1/8/76	492	Sand & refinish floor
Comp # 79-2620	1979	1222	Edt paint
16270-78-C-8114	12-17-80	3512	Steam pit improvements for energy conservation
5313	1-12-79	687	Rpl. cylinders in deadlocks
3532	1-3-79	205	Paint into room on coat
5398	9-5-78	108	Sand refinish floor
4400	5-15-78	1466	Self Help paint one coat
4404	4-28-78	500	Secure Celotex Ceiling in room (13) re-install 1 pipe fitting for WC 41
4928	Comp	213	Rpl. celotex ceiling w/ gypsum board and paint in rm 230
4928	Comp	213	Paint interior of rooms 215/230 light beige
4678	9-14-79	412	Paint ^{rm} sand floor
3711	1-29-79	310	Paint ^{rm} sand floor - refinish
4139	4-23-79	312	Paint ^{rm}
3966	3-16-79	317	Paint rm. sand - refinish floor
4067	10-31-80	551	Rpl. metal railing with sheet rock
4658	11-21-80	370	Rpl. brick lintels
3050	Comp	5737	Plaster Repair and paint bldg
1256	9-4-81	7012	Install floor tile, Remove and Reinstall shoe molding
3998	9-25-81	832	7ab + Repair window - screens and paint both sides
3582	3-6-81	11,374	paint portion of bldg one or two coats
3162	71-27-81	1336	Install condenser state pump
3289	5-7-82	303	Repair interior and paint
3307	5-7-82	392	Sand, scrape, clean and paint Room 121