BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
BB-47					MCBCL 11011/3

JOB ORDER NO	DATE ~~COMPLETED~~ Signed	COST	DESCRIPTION
H08-CM-OND-167	6/28/68	130	Self-Help paint - exterior complete & reglaze windows
3626	2-22-96	7150	Rpl Well Pump [illegible] PUMPED 99
3626	2-22-96	612	1 ST AMS [illegible] PUMPED 99

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION