

BB-250
JOB ORDER NODATE
COMPLETED

COST

DESCRIPTION

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
5465	9-26-78	923	Rep. A/C compressors
4964	5-18-78	500	Purchase 5 H.P. circulating pump
5382	8-28-78	125	Repair A/C unit
4790	8-12-79	4406	Change air filters in A/C unit - 4 bldgs
49.C-9497	12-21-81	23,633	Connection to Ventilation system
5924	3-8-79	2600 317	Electric maint.
5465	1-31-79	2476	Repair A/C compressors
3998	7-30-79	1049	Resecure balcony rails
3229	10-30-79	3068	Repa venetian blinds
5030	4-10-81	1657	Rpl. screws in ex. shower drain cover with Tamper proof screws
4548	5-8-81	88	Mount to 458 Rpr in ext. hand rails
3654	10-16-81	1009	RPL. tube bundle in domestic hot water heater
4065	9-28-81	818	RPL. AIR F. Hous in A/C System
3745	Comp	179	Purchase Plastic Room & Card Signs
3671	Comp	1172	RPR balcony rails
4517	8-28-81	460	RPR Burned Wiring in trough
3543	COMP	3147	Replace "V" Blinds in Rms as per list.
3543	8-20-82	3147	Amendment #1 Replace "V" Blinds as per list.
4849	12-3-84	3243	Service clean & Repair small exhaust fan in Rooms
4824	3-25-83	2724	Rep Window Screens missing or Damaged
4820	4-1-83	1851	Rpl 10 metal door with wood.
3060	2-19-82	1466	Replace weather stripping.
4248	4-4-83	1208	RPR balcony rails
4389	4-29-83	510	Rpl Venetian Blinds
4060	2-6-87	1967	Landscape ground in rear of Bldgs
5817	11-19-84	5,010	Perform cyclic maint.
5724	11-6-84	1454	Replace steam coil
3461	2-10-84	5982	clean fan + coil in rooms

BB-250-255

-40301-1340

