FILE FOLDER

DESCRIPTION ON TAB:

227
J.O. completed
Outside/inside of actual folder did not contain hand written information
Outside/inside of actual folder did contain hand written information

DE	SCRIPTION:
	J.O. Card
	Tab page did not contain hand written information
Ц	Tab page contained hand written information *Scanned as next image

JOB OR	DER NO	DATE	соѕт	DESCRIPTION
3.	513	1-3-74	4233	Repairs + paint interior complete 1 coal
	032	8-28-25	4032	Rel metal enendoew einet
3	344	3-10-78	4374	Repair work/self help
	4326	4-7-78	1492	Pull and regain steam coil
	5413	9-29-78	434	Rps a/c
the same of the sa	3618	2-22.80	662	Replace Cail in Water heater
	4239	12.19.80	1263	1) condenpate pump + Tank assy.
* 3				
-	- 20			

BLDG NO . INT. PAINT SQ FT EXT. PAINT SQ FT FACILITY HISTORY RECORD ROOF SQ FT CONDEN. LINES LIN FT MCBCL 11011/3 DATE COMPLETED JOB ORDER NO DESCRIPTION COST

DESCRIPTION: CONTRACT Data Contract Data Tab page did not contain hand written information Tab page contained hand written information *Scanned as next image

DE	SCRIPTION:
	J.O. Pending
þ	Tab page did not contain hand written information
	Tab page contained hand written information *Scanned as next image