FILE FOLDER

DESCRIPTION ON TAB:


404

J.O. Completed

Outside/inside of actual folder did not contain hand written information

 Outside/inside of actual folder did contain hand written information
*Scanned as next image

Confidential Records Management, Inc. New Bern, NC 1-888-622-4425 9/08



DESCRIPTION:

Ø

J.O. CarD

Tab page did not contain hand written information

Tab page contained hand written information *Scanned as next image

| JOB ORDER NO | DATE COMPLETED Signed | СОЗТ | DESCRIPTION |
|---------------|-----------------------------|------|--|
| 022-06741-620 | 1/22/62 | | Rehabilitate steam pits (C 5/11/62) |
| 022-06741-620 | 2/13/62 | | Rehabilitate, paint int and exterior (C 3/19/62) |
| Contract | 2/9/67 | | Head & shower renovation. |
| Contract | 3/31/70 | | Renovate mechanical system |
| Contract | 12/10/69 | | Exterior repairs & paint |
| 4547 | 2-28-74 | 1327 | Self help - Interior 1 coat |
| 3910 | 12.18-74 | | Install glass |
| 1076 | 10-14-69 | 331 | Install lanatain |
| 4670 | 2-11-72 | | Remove + upl steam coil in hot water Leale |
| 4158 | 9-15-71 | 491 | Rev tank + size insulation |
| 4620 | 6-15-70 | 1569 | Paint interior complete, minor uses to place |
| 1135 | 12-17-69 | 36 | Install window bass |
| 223-587 | 7-1-66 | 2178 | Sell file - paint interior 1 roat |
| 3635 | 4-8-75 | 280 | Replace 55 stokes |
| 5376 | 7-30.76 | 331 | Replace doteriorated where in Upitur |
| 5708 | 8/16/76 | 801 | Row to steam pit |
| 0-2095 | 3-16-81 | | est sainting |
| 4811 | 77 | 2750 | Paint int Bid / chat complete |
| 5293 | 9-1-78 | 409 | Repair A/C system |
| 3339 | 11-2679 | 3927 | Pm Kollow ge |
| 3458 | 2.8.80 | 3672 | tepl condensate receiver, repair Elect, in pit |
| 4019 | 10-12.99 | 199 | 11 Botts in main water supply values |
| 4586 | 9-6-79 | 653 | painting |
| 4032 | Comp | 1655 | Secure inspect, panel covers in hallway |
| 3490 | Comp | 1633 | Rpr. clothesline post + install new wire |

| JOB ORDER NO | COMPLETED | соѕт | DESCRIPTION |
|--------------|-----------|------|-------------|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| , | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| <u></u> | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

DESCRIPTION:

work requests

Tab page did not contain hand written information

Tab page contained hand written information *Scanned as next image

DESCRIPTION:

Contract Data

Tab page did not contain hand written information

Tab page contained hand written information *Scanned as next image

DESCRIPTION:

J.o. Pending

 \square Tab page did not contain hand written information

Tab page contained hand written information *Scanned as next image