INSPECTION REPORT ON LONG TERM HAZ/ WASTE STORAGE FACILITIES AT BUILDING TP-451 TP-463



UNITED STATES MARINE CORPS MARINE CORPS BASE CAMP LEJEUNE, NORTH CAROLINA 28542

IN REPLY REFER TO 6240 NREAD 8 Aug 86

From: Commanding General, Marine Corps Base, Camp Lejeune To: Defense Reutilization and Marketing Officer, Camp Lejeune

- Subj: INSPECTION REPORT ON LONG TERM HAZARDOUS WASTE STORAGE FACILITIES AT BUILDINGS TP-451 and TC-863
- Ref: (a) Onsite inspection by Mr. Becker, NREAD, and Mr. Eggers, DRMO
 - (b) CG MCB ltr FAC/REA/hf 6280 of 15 Jul 83
- Encl: (1) Inspection Checklist for Long Term Hazardous Waste Storage Facilities at Buildings TP-451 and TC-863

1. The enclosure provides results of reference (a) as required by refernce (b). No discrepancies were noted. Point of contact is Mr. Danny Becker, NREAD, extensions 5003/2083.

PE Black

P. E. BLACK By direction

Copy to: AC/S FAC BFIRECHIEF SJA BMO BSAFETYMGR

98 11 986 9NV 11

arende en estamenta de real destrictor de la Constanta de la constanta de la constanta de la constanta de la c Parte de la constanta de la cons

Averal Average Construction of the Constructio

οιοι του του Δασφοράτατοι (**** του δούτου), που από τους παλλα Για του πολαγγραφικού του δεταδρίου (* 1990)

ne na seneral esti ne el prese regionar de presidente de la companya de la companya de la companya de la compa La currix Messa de la currix de la companya de la companya de la currix de la currix de la currix de la currix d

11 the lose - 11 se

INSPECTION CHECKLIST FOR LONG TERM HAZARDOUS WASTE/MATERIALS STORAGE FACILITIES AT TP-451/TC/863

FACILITIES AND EQUIPMENT		SAT	UNSAT	COMMENTS	
1.	FACILITY GROUNDS	X			
2.	FACILITY SECURITY (LOCKS, DOORS, SIGNS, ETC.)	Х			
3.	EMERGENCY TELEPHONE AND FIRE ALARMS	X		· ·	
4.	UNLOADING PAD DRAIN VALVE	X		and the second sec	
5.	EXHAUST' FANS	X			
6.	INTERIOR LIGHTING AND ELECTRICAL OUTLETS	X		The inoperative light noted in the July inspection is undergoing repair.	
7.	SAFETY SHOWERS/ EYE LAVAGES	Х			
8.	CURBS, GRATES, OTHER FIXTURES	X	6.4		
9.	NON-SPARKING SHOVELS (2)	Х			
10,	ABSORBENT (EQUIVALENT OF FOUR 55-GAL BARRELS)	X			
11.	HAZ MAT PUMPS OR EQUIVALENT	X			
12.	FIRE EXTINGUISHERS	Х			
,13.	PROTECTIVE GEAR AND EQUIPMENT	Х		n	
14.	EMPTY CONTAINERS AND OVERPACK DRUMS	Х		ENCLOSURE 171	

OPE	GRATIONAL CONSIDERATIONS	SAT	UNSAT	COMMENTS
1.	Required operator inspections and Inspection Log	X		
2.	Emergency Contingency Plan Posting & Operator Familiarity	X		
3.	Fire Department Phone number posting	X		
4.	Condition of containers in use	X		
5.	Presence of odors/vapors, res- idues in sumps, deck, etc.	Х		
6.	Unloading Pad Valve Operation	X		
7.	Compatibility of Material Storage	X		
8.	Implementation of previously recommended corrective action	X		
9.	Facility Operators since last Inspection	X		George Eggers

ADDITIONAL COMMENTS, EXPLANATIONS, ETC:



UNITED STATES MARINE CORPS MARINE CORPS BASE CAMP LEJEUNE, NORTH CAROLINA 28542

Learge. IN REPLY REFER TO

NREAD 10 Sep 86


- From: Commanding General, Marine Corps Base, Camp Lejeune To: Defense Reutilization and Marketing Officer, Camp Lejeune
- Subj: INSPECTION REPORT ON LONG TERM HAZARDOUS WASTE STORAGE FACILITIES AT BUILDINGS TP-451 and TP-463
- Ref: (a) Onsite inspection by Mr. Becker, NREAD, and Mr. Eggers, DRMO
 - (b) CG MCB ltr FAC/REA/hf 6280 of 15 Jul 83
- Encl: (1) Inspection Checklist for Long Term Hazardous Waste Storage Facilities at Buildings TP-451 and TP-463

1. The enclosure provides results of reference (a) as required by refernce (b). It was noted that four hazardous waste labels did not have EPA ID nos. or EPA Waste nos. on them. This discrepancy was corrected on the spot. Point of contact in this matter is Mr. Danny Becker, NREAD, extensions 5003/2083.

&. J. Woola

J. I. WOOTEN By direction

Copy to: AC/S FAC BFIRECHIEF SJA BMO BSAFETYMGR



INSPECTION CHECKLIST FOR LONG TERM HAZARDOUS WASTE/MATERIALS STORAGE FACILITIES AT TP-451/2P/463

PARTICIPANTS Beckers, Barbee, FACILITIES AND EQUIPMENT		SAT	UNSAT	COMMENTS		
L,	FACILITY GROUNDS	x	à			
2.	FACILITY SECURITY (LOCKS, DOORS, SIGNS, ETC.)	Х				
3.	EMERGENCY TELEPHONE AND FIRE ALARMS	Х				
١.	UNLOADING PAD DRAIN VALVE	х		Dirt & sediment needs to be cleaned out		
5.	EXHAUST' FANS	Х				
6.	INTERIOR LIGHTING AND ELECTRICAL OUTLETS	X				
7.	SAFETY SHOWERS/ EYE LAVAGES	x				
3.	CURBS, GRATES, OTHER FIXTURES	х		•		
э.	NON-SPARKING SHOVELS (2)	Х				
10.	ABSORBENT (EQUIVALENT OF FOUR 55-GAL BARRELS)	Х				
11.	HAZ MAT PUMPS OR EQUIVALENT	X				
12.	FIRE EXTINGUISHERS	х				
13.	PBOTECTIVE GEAR AND EQUIPMENT	Х				
14	EMPTY CONTAINERS AND OVERPACK DRUMS	Х		ENCLOSURE (I)		

	·	1	11				
OPERATIONAL CONSIDERATIONS		SAT	UNSAT	COL	IMENTS		
1.	Required operator inspections and Inspection Log	x					
2,	Emergency Contingency Plan Posting & Operator Familiarity	x	1.1				•
3.	Fire Department Phone number posting	x					
4.	Condition of containers in use	x					
5.	Presence of odors/vapors, res- idues in sumps, deck, etc.	x	1				
6.	Unloading Pad Valve Operation	x				· · ·	
7,	Compatibility of Material Storage	x		4 ¹	2 		
8,	Implementation of previously recommended corrective action	x					
9.	Facility Operators since last Inspection	x		George Eggers		5	

ADDITIONAL COMMENTS, EXPLANATIONS, ETC:

Operator must ensure that Hazardous Waste labels are visible from isles. Operator must ensure

that Hazardous Waste labels are completely filled out upon receipt.



UNITED STATES MARINE CORPS Marine Corps Base Camp Lejeune, North Carolina 28542-5001

> 6240 NREAD 10 Sep 86

From: Commanding General, Marine Corps Base, Camp Lejeune To: Defense Reutilization and Marketing Officer, Camp Lejeune

- Subj: INSPECTION REPORT ON LONG TERM HAZARDOUS WASTE STORAGE PACILITIES AT BUILDINGS TP-451 and TP-463
- Ref: (a) Onsite inspection by Mr. Becker, NREAD, and Mr. Eggers, DRMO
 - (b) CG MCB ltr FAC/REA/hf 6280 of 15 Jul 83
- Encl: (1) Inspection Checklist for Long Term Hazardous Waste Storage Facilities at Buildings TP-451 and TP-463

1. The enclosure provides results of reference (a) as required by refernce (b). It was noted that four hazardous waste labels did not have EPA ID nos. or EPA Waste nos. on them. This discrepancy was corrected on the spot. Point of contact in this matter is Mr. Danny Becker, NREAD, extensions 5003/2083.

> J. I. WOOTEN By direction

Copy to: AC/S FAC BFIRECHIEF SJA BMO BSAFETYMGR

N.

559

Nº1

PROP RUBBLE

15 SEP 1986 07 52



UNITED STATES MARINE CORPS MARINE CORPS BASE CAMP LEJEUNE, NORTH CAROLINA 28542

IN REPLY REFER TO 6280 NREAD 18 Apr 1986

- From: Commanding General, Marine Corps Base, Camp Lejeune To: Defense Reutilization and Marketing Officer, Camp Lejeune
- Subj: INSPECTION REPORT ON LONG TERM HAZARDOUS WASTE STORAGE FACILITIES AT BUILDINGS TP-451 AND TC-863
- Ref: (a) Onsite Inspection by Messrs. Becker and Martin, NREAD and Mr. Eggers, DRMO
 (b) CG, MCB CLNC ltr FAC/REA/hf 6280 of 15 Jul 1983
- Encl: (1) Inspection Checklist for Long Term Hazardous Waste Storage Facilities at Buildings TP-451 and TC-863


1. The enclosure provides results of reference (a) as required by reference (b). No discrepancies were noted. Point of contact in this matter is Mr. Danny Becker, Natural Resources and Environmental Affairs Division, extensions 5003/2083.

J. I. WOOTEN

J. I. WOOTEN By direction

Copy to: AC/S, FAC SJA BaseFireCh BMO BaseSafetyMgr

RECEIVED APR 22 1986 DPDO - LEJEUNE



INSPECTION CHECKLIST FOR LONG TERM HAZARDOUS WASTE/MATERIALS STORAGE FACILITIES AT TP-451/TC/863

INSP	ECTION CHECKLIST FOR DOM		. 1 [
PART	ICIPANTS BECKER, MARTIN,	EGGERS	" 1		DATE: 16 Apr 1986
	ITIES AND EQUIPMENT	SAT	UNSAT	COM	MENTS
	ILITY GROUNDS	, X		19 	
2. FAC DOO	ILITY SECURITY (LOCKS, RS, SIGNS, ETC.)	X			
3. EME	RGENCY TELEPHONE AND E ALARMS	X			
4. UNL	OADING PAD DRAIN VALVE	Х			
5. EXH	AUST FANS	X			
	ERIOR LIGHTING AND CTRICAL OUTLETS	X			
	ETY SHOWERS/ LAVAGES	X			
	BS, GRATES, OTHER TURES	Х		•	
	-SPARKING SHOVELS (2)	X			
	ORBENT (EQUIVALENT OF R 55-GAL BARRELS)	X			
11. HAZ	MAT PUMPS OR IVALENT	Х			
3	E EXTINGUISHERS	Х			
	TECTIVE GEAR AND IPMENT	X		4	
14. EMP OVE	TY CONTAINERS AND RPACK DRUMS	х			ENCLOSURE (1)

operator inspections ection Log y Contingency Plan & Operator Familiarity artment Phone osting	X · X X			
<u>& Operator Familiarity</u> artment Phone osting	· ·			
osting	x.			· · · · · · · · · · · · · · · · · · ·
그는 것은 것이 아내는 아내는 것이 같아.	6.8%			
n of containers	X			
of odors/vapors, res- sumps, deck, etc.	X	,		
g Pad Valve Operation	Х			
ility of Material	X			
tation of previously ded corrective action	x			
Operators since pection	x		. George Eggers	
1	sumps, deck, etc. g Pad Valve Operation ility of Material tation of previously ded corrective action Operators since spection	sumps, deck, etc.	sumps, deck, etc. A ng Pad Valve Operation X ility of Material X itation of previously X ided corrective action X Operators since y	sumps, deck, etc. A ng Pad Valve Operation X ility of Material X itation of previously X ided corrective action X

•

•

.

.1

...

1.12.5 10

.

ž

.

Sec. 1.